




Machining cost**Travel-mode cost****Stability penalty****Runtime (ms)**