THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA

Well Details			Objectives:			
Field		SEIBOU	To repair the Bulk line of SEIB 003L on F2000B reservoir and restore 1967 bopd of production.			
Well		SEIB 003L	1			
Flowstation		OPUKUSHI FS Scope of Work:		SEIDOON and Seet	actions the C4 Dullding with	
Well type	(Oil/Gas)	Oil	 Repair Flowline of SEIB003L and Sections the S4 Bulkline wit 4" SCH-80 and 6" SCH-80 respectively 			
Lift Type		Natural Flow				
Reservoir		F2000B				
Abandonment Watercut	%	90				
Timing		Q1,2017				
Job duration	(days)	21 days				
Economic Summary			Flowline Details			
Conduit Production Rate (Bopd)		1967	Length	(km)	21	
Reserves	(MM bbls)	1.99	Size	(inch)	4 & 6	
Current BSW	%	3	Schedule	(no.)	80	
Risked NPV 7%	(MM US\$)	-	Total Cost	(USD \$)	256,000	
Risked VIR	(-)	-	Account No.	Dev/Eng		

Proposal contributors

Name	Function	Signature	Date
Ezeike Emeka	Swamp Team PT (originator)		
Mmakwe Ibe	Swamp Team RE (contributor)		
Agwu Ndukwe	Swamp Team SPT (Reviewer)		
Security Classification	Restricted	Document Reference Number	SPDC-2016-10-00000116

Approval

Name	Function	Signature	Date
Okoro Chidi	WRFM Manager Swamp West		
Alo Edward	Operations Manager, Swamp West		
Nwadiuto Onyekwelu	Head Asset Engineering		

Justification:

The interval was producing at a rate of 1968 bopd; (BSW=3%, GOR=875scf/ stb, Sand=4pptb, THP =1260psi) on bean 24/64" before it was voluntarily closed-in due to the Forcados Export line outage in Feb 2016. However, there is a need to repair non-integral sections of the S4 Bulkline which evacuates production from SEIB003L. There is no vertical lift challenge associated with its performance as the current water-cut (3%)is far below the terminal water-cut value (90%) for the conduit. The attached IPR/VLP plot supports these facts.

In view of the reserves (1.99 MMstb) and 1967bopd potential from the interval, the well is proposed for Bulkline repair.


Flowline size and rating

The last recorded oil rate was 1967bopd with a FTHP of 1275 psi as at Jan 2016 welltest. No erosional velocity problems or excessive pipeline pressure drops are expected. However, in view of flowline theft menace in this area, it is recommended to install 6" SCH-80 line to deter theft.


The total cost of Bulkline replacement is 256,000 U\$D, assuming 50 U\$D dollars per barrel it will take 3 days to recover the investment

HSSE Issues: No annular pressure cases recorded. All HSSE procedures for FLLR and well open up should be strictly followed.

ATTACHMENT 1: CURRENT WELL SCHEMATIC



ATTACHMENT 2: PERFORMANCE PLOT FOR SEIB 003L



IPR PLOT

