NEMC/2 - closed-in W/22S and 51L @ 1700hrs 18/06/15 on high GOR due outage of SOKU AG compressor.	Closed	21,684 Closed	41,853	54,274	1,102	39%	1,396	794	1,267	2,061	NEMC022S	NEMC/2
ODEC/1 was manually s/d @ 1700hrs on 18/6/15 as part of efforts to reduce flaring. Flowing strings were: 2L/S, 4L/S & 9S. (5 strings). Facility to be restarted once Soku AG2 issues are resolved (LEC 30-June) or Belema AG restarted whichever comes first	Closed	20,288 Closed	40,587	52,213	1,062	29%	2,664	1,037	2,509	3,546	ODEC009S	ODEC/1
	17,624 Flowing		38,078	48,667	936	78%	167	618	178	796	NEMC002L	NEMC/1
	17,457 Flowing		37,900	47,871	898	64%		959	538	1,497	NEMC054L	NEMC/2
	16,974 Flowing		37,362	46,374	851	49%	1,342	1,541	1,577	3,118	NEMC007S	NEMC/1
	15,632 Flowing		35,785	43,256	749	0%		15	6,644	6,659	NEMC073T	NEMC/2
	10,656 Flowing			36,597	733	62%	444	999	606	1,605	NEMC015L	NEMC/1
	10,212 Flowing			34,992	618	44%	836	1,067	1,354	2,421	NEMC020S	NEMC/2
	9,375 Flowing		27,181	32,571	576	%0	3,004	0	5,212	5,212	NEMC069T	NEMC/2
	6,371 Flowing			27,359	476	20%	433	228	908	1,137	NEMC006S	NEMC/3
	5,939 Flowing			26,222	467	2%	562	20	1,205	1,225	NEMC058L	NEMC/3
	5,377 Flowing		19,856	24,998	442	0%	1,449	2	3,282	3,284	NEMC072T	NEMC/2
	3,928 Flowing		16,574	21,714	430	53%	963	2,519	2,240	4,759	NEMC043L	NEMC/2
	2,964 Flowing			16,955	429	60%	446	1,576	1,039	2,615	NEMC015S	NEMC/1
	2,518 Flowing			14,340	380	46%	171	387	449	836	NEMC033S	NEMC/3
	2,347 Flowing			13,504	372	55%	100	324	269	593	NEMC055S	NEMC/1
	2,247 Flowing		12,577		311	58%	72	321	231	551	NEMC033L	NEMC/3
	2,175 Flowing		12,346	12,360	198	0%	695	2	3,512	3,515	SBAR011T	SBAR/1
	1,481 Flowing	1,	8,834	8,845	182	0%	692	2	3,805	3,807	SBAR012T	SBAR/1
	788 Flowing		5,028	5,038	157	0%	788	9	5,028	5,038	SBAR010T	SBAR/1
Remarks	Status	Gas		e Gross oil e Net Oil	(Theor)	(Theor)	(Theor)		oil (Theor) (Theor)	(Theor)	Well	Facility
	Well	Cumulativ Cumulative	Cumulativ	Cumulativ	FGOR	BS&W	Gas		Total Net	<u>≗</u>		
					Total	Total	Formation Total	Total		Total		
							Total					

18/6/15 as part of efforts to reduce 18/6/15 as part of efforts to reduce flaring. Flowing strings were: 2L/S, 4L/S & 9S.(5 strings) . Facility to be restarted once Soku AG2 issues are resolved (LEC 30-June) or Belema AG restarted whichever comes first	28,634 Closed	28,634	45,516	64,761	2,531	63%	1,947	1,327	769	2,096	ODEC002L	ODEC/1
NEMC/2 - closed-in W/22S and 51L @ 1700hrs 18/06/15 on high GOR due outage of SOKU AG compressor.	26,687 Closed	26,687	44,747	62,665	1,826	79%	1,310	2,748	717	3,465	NEMC051L	NEMC/2
ODEC/1 was manually s/d @ 1700hrs on 18/6/15 as part of efforts to reduce flaring. Flowing strings were: 2L/S, 4L/S & 9S. (5 strings). Facility to be restarted once Soku AG2 issues are resolved (LEC 30-June) or Belema AG restarted whichever comes first	25,377 Closed	25,377	44,029					2,158		3,123	ODEC004L	ODEC/1
ODEC/1 was manually s/d @ 1700hrs on 18/6/15 as part of efforts to reduce flaring. Flowing strings were: 2L/S, 4L/S & 9S.(5 strings). Facility to be restarted once Soku AG2 issues are resolved (LEC 30-June) or Belema AG restarted whichever comes first	Closed	23,621 Closed	43,064					592		1,803	ODEC002S	ODEC/1
Remarks	Well		lativ Oil	Cumulativ Cumu e Gross oil e Net	Total FGOR (Theor)	Total BS&W (Theor)	Total Formation Total Gas BS&V (Theor) (Theor		Total Total Net Water oil (Theor) (Theor)	Total Gross oil (Theor)	Well	Facility

	33,674 Closed		46,478	5 67,779	6 5,235	68%	5,040	2,055	963	3,018	ODEC004S	ODEC/1
whichever comes first												
30-June) or Belema AG restarted												
once Soku AG2 issues are resolved (LEC												
& 9S.(5 strings) . Facility to be restarted												
flaring. Flowing strings were: 2L/S, 4L/S												
18/6/15 as part of efforts to reduce												
ODEC/1 was manually s/d @ 1700hrs on												
Remarks	Status	Oil Gas		e Gross oil e Net	(Theor)	(Theor)	(Theor)	(Theor)	oil (Theor) (Theor)	(Theor)	Well	Facility
	Well	Cumulativ Cumulative	Cumulativ	Cumulativ	FGOR	BS&W	Gas	Water	Total Net Water	Gross oil		
					Total	Total	Formation Total	Total		Total		***************************************
							Total					

Well Status	FGOR
Closed	15,175
Flowing	9,205
Grand Total	24,380

ODEC/1 was manually s/d @ 1700hrs on 18/6/15 as part of efforts to reduce flaring. Flowing strings were: 2L/S, 4L/S & 9S.(5 strings) . Facility to be restarted once Soku AG2 issues are resolved (LEC 30-June) or Belema AG restarted whichever comes first

NEMC/2 - closed-in W/22S and 51L @ 1700hrs 18/06/15 on high GOR due outage of SOKU AG compressor.

Ekomekido, Clementina SPDC-UIO/G/PNES1

From: Ikeobi, Chuks C SPDC-UIO/G/PNES1
Sent: Tuesday, June 30, 2015 12:13 PM

To: Ekomekido, Clementina SPDC-UIO/G/PNES1 **Subject:** FW: AG-2 issues and restoration activities.

From: Osasona, Sazy F SPDC-UIO/G/PMA Sent: Monday, June 29, 2015 2:28 PM

To: Oni, Olatunbosun OA SPDC-UIO/G/PNES; Ikeobi, Chuks C SPDC-UIO/G/PNES1

Cc: Oji, Eberechukwu E SPDC-UIO/G/PM; Adebisi, Olusola A SPDC-UIO/G/PNES1; Ovwagbedia, Arthur E SPDC-

UIO/G/PMA; Oleho, Austin M SPDC-UIO/G/PMA; Abioye, Taslim O SPDC-UIO/G/PMA

Subject: AG-2 issues and restoration activities.

L&G

Current Challenges

- 4k Inspection was carried out on 30th April 2015. Unit was started and ran for 10minutes, but shutdown due to insufficient gas to carry out 72hrs test run.
- Gas supply restored 24th May 2015 post repair of leaking flash gas outlet line flange. Unit was started but failed on LP turbine mean exit temp high alarm.

What we have done (24th May to 28th June)

- Carried out troubleshooting using both in-house expertise and OEM support.
- Progress on troubleshooting hampered as support from OEM stalled by contracting issues-Turbine controls (obsolete Rustronic Mark-2) specialist not resident in primary vendor. Primary vendor unable to properly secure the service of secondary vendor
- Continued troubleshooting with in-house resource. Awaiting advice from Mark-2 control specialist.

Way forward-29th June-4th July 2015.

- Help to resolved PO issues between vendors and exploiting alternative avenue to procuring service of specialist
- Established alternative specialist resource outside usual OEM to support AG-2 controls issues on 29th June, 2015. – Retired EPS control Engineer in Dubai.
- On line support and troubleshooting using alternative specialist currently ongoing
- Complete restoration of AG-2 envisaged in the week LEC 4th July 2015.

Sazy



The Shell Petroleum Development Company of Nigeria Limited

> Freeman House 21/22 Marina, Lagos P. M. B 2418 Lagos Nigeria Tel +234(0) 80702 25174 Telex +234 (0) 1 2601600 Internet www.shellnigeria.com

The Managing Director,

Aiteo Eastern E&P Company Limited 11A Pope John Paul II Street, Maitama, Abuja, Nigeria Attention: Mr. Emmanuel Ukegbu

18th June, 2015

Our ref: SPDC-2015-06-114

Dear Sir,

Re. Transition Operations - OML 29 Associated Gas flows to NLNG via Soku

This is to inform you that due to operational issues at Soku, the associated gas processing facility is currently down and out of operation. Therefore, we are currently unable to process any associated gas that is flowing from OML29 to NLNG through the SPDC JV facility at Soku.

This has resulted in significant non-routine flaring at the OML 29 facilities. We expect this condition to persist until the problem at Soku is resolved, which based on our latest estimate is end June 2015.

In line with our standard operating practice for managing extended non-routine flaring, we have to cream off wells of high gas oil ratio (HGOR wells) to reduce the flared gas. For OMI. 29 fields, this means cutting back on associated gas production with resultant production deferment.

Please note that in line with your obligations under the Transition Operations Agreement, you will need to immediately apply to the Department of Petroleum Resources for flaring waiver permit to cover the residual flaring after the cut back as notified in this letter. A sample template for waiver permit is attached for your benefit.

We assure you that we will continue to monitor progress on the restoration of operations at the associated gas facilities in Soku and its availability to receive normal production from OMI. 29.

Yours faithfully,

For: The Shell Petroleum Development Company of Nigeria Limited

Nnamdi Wali

Operations Completions and Handover Manager

Encl.

_				 		
Δ	**	0	n	•	n	٠

The Director,
Department of Petroleum Resources (DPR),
7, Kofo Abayomi Street,
Victoria Island, Lagos.

_		1
 -	т	0

Your ref:

Our ref:

Dear Sir,

Application for Temporary Flaring Permit on OML 29 Fields

In compliance with DPR's gas flaring guidelines in Part III, Section 1, subsection 3.8.8, page 52 EGASPIN (Revised Edition 2002), AITEO wishes to apply for a gas flaring waiver due to unscheduled downtime of third party associated gas processing facilities.

Date	Cause	Maximum Gas Flare Rate
	Total	

We would like to assure you of our continued commitment towards complying with regulatory provisions despite certain operational constraints that may lead to occasional gas flaring.

Yours faithfully,