

			AGBADA AGG RESTORATION PLAN	ORATION PLAN
S/N	TASKS LIST.	Action Party	22/10/14-23/10/14	23/10/14-31/10/14
	Commmence trouble shooting of Turbine trip on			
_	pressure/Ignition failure	Solar and Asset MTCE		
	Source for materials(ignition exciter,			
	bleed valve exhaust etc)			
2	2 and replace	Asset Team		
	Start unit and observe for			
ω	3 72 hours	Solar and Asset MTCE		