AGBADA 1 BOOSTER FAN COOLER BEARING REPLACEMENT AND ALIGNMENT PLAN

											MA	λΥ											JUN	IE	
S/N	TASKS LIST.	Action Party	11	. 12	13	14	15	16	17	18	19 2	20	21 2	3 2	4 25	26	27	28	29	30	31	1	2	3	4
	PRE-SHUTDOWN ACTIVITIES																								
13	FAILED BEARING EXTRACTION & REPLACEMENT																								
14	Visit site and inspect all equipment to be disconnected	NEMS/ PIEKLE		D																					
15	Prepare Work method statement & JHA, complete PTW form and sign	NEMS	D																						
16	Isolate all process lines using manual valves	Asset																							
17	Commence disconnection of accessories	Asset		D																					
18	Commence decoupling of shaft and extraction of bearings 4 numbers	NEMS/ PIEKLE				D																			
19	Exermine shaft for straightness and source for replacement	NEMS/ PIEKLE NEMS/							D																
20	Assemble hubs and install bearings 4 numbers	PIEKLE)								
	Carry out shaft& blades alignments																	D							
	Reassemble accessories	Asset																			D			D	
	Commission																				4	D_			L
23	Clear worksite	Asset																							
EQUIF	PMENT & PERSONNEL					LI	EGE	ND																	

1	Alignment tools		Plan								
2	Extraction tools		Ongoing								
3	Others including hand tools		Completed								
4	5 personnel		Agreed start date								

5	6	REMARKS
		Shaft observed badly cut, will
		require
		replacement. Replacement shaft
		being sourced from OEM
D		
	D	

