Permanent Monitoring Installation Report



Field Ticket #	RGS1808070422		EOT	792.8 m MD	
Client	Santos Ltd		Tubing Size	2-3/8in 4.7 lb/ft	
Well Name	RM50-11-1		Casing Size	7in 23lb/ft	
Well Location	Roma		SHP	0 psi	
Rig	Wild Desert 4		ВНР	1100 psi	
Customer Rep	Adam Riches		SHT	20 °C	
Service Eng	K.Rowbotham		внт	45 °C	
Activity	Date	Time	Activity	Date	Time
Depart Base	06-Aug-18	22:30	Job End	07-Aug-18	5:45
Job Start	07-Aug-18	0:45	Return Base	07-Aug-18	6:00
Gauge Use	Pump Control		Surface Card	Not required	
Gauge Depth	766.60 m		Telemetry	Analogue	
Gauge Type	4-20mA 0-1.5k psi, 105 DegC		Surface Output	4-20mA	
Pres Range	0-1500 psia		Cable Splice Depth	N/A	
Temp Range	N/A		Tubing Hanger	1/4in NPT - 1/4in Swagelok	
Max Devi	0.0°		Wellhead Outlet	AnTech Type CS/N 18-1536	
TEC Cable	0.25" x 11mm Encap		Encapsulation	Square 11mm	
Serial Number	0001102545-2		Manufacturer	Draka	
Conductor	16 AWG Solid Copper		Material	Polypropylene	
Tube OD	0.25"		Pres Rating	15 kpsi	
Material	316L SS		Temp Rating	150 DegC	
Gauge	Analogue		Pres Sensor	Piezoresistive	
Serial Number	LC00065		Calibration Range	0 -1500 psia	
Depth	766.60 m		Temp Sensor	N/A	
OD	1"		Temp Range	N/A	
Vibration	N/A		Vibration Range	N/A	
Gauge Carrier	Gauge Carrier Cannon Clamp Type with Vibration Sleeve				
Running OD		4.600"			
Serial Number		N/A			
Cross Coupling Protectors		2-3/8in - 3-1/2in Wiper Blade Style Stainless Steel			
Running OD		4.000"			
Qty Installed		82			
Bands and Clips Material		0.25" x 0.75" w-7/8" Buckle 316SS			
Qty Installed		164			

Comments: Gauge Carrier installed 2 full joints above PCP. 4-20mA Analogue gauge installed. RIH installing 82 banded CCP. Installed 2 \times 1/4in NPT fittings in the hanger and pressure tested. Nippled down and installed Rod lock and AnTech wellhead outlet.



	Sequence of Events				
Date	Time	Description			
06/08/2018	22:30	Depart Roma			
23:30		Arrive location			
		Unload and spot equipment.			
07/08/2018	0:45	Safety meeting with crew.			
	1:00	Pick up Sheave and make up BHA			
1:20		Make up gauge carrier and gauge to completion.			
		RIH first 4 joints then increase back tension on spooling unit.			
		Installed 82 banded cross coupling protectors.			
3:30		Make up hanger.			
		Strip encapsulation and pass cable through tubing hanger and tighten TEC seals.			
	4:00	Land hanger and start pressure test to 1500 psi.			
		Rig down floor.			
		Nippled down.			
	5:00	Land and nipple up rod-lock.			
		Pressure test rod lock to 300/3000 psi.			
	5:30	Install AnTech wellhead outlet.			
	5:45	Final gauge reading 1100 psia.			
		Prepare report.			
	6:00	Depart location for Roma.			