Permanent Monitoring Installation Report



			1		1112110
Field Ticket #	RGS1907080604		EOT	795.1 m MD	
Client	Santos Ltd		Tubing Size	2-3/8in 4.7 lb/ft	
Well Name	RM50-19-1		Casing Size	7in 23lb/ft	
Well Location	Roma		SHP	0 psi	
Rig	Savanna 71		ВНР	1011 psi	
Customer Rep	Chris Krammer		SHT	20 °C	
Service Eng	K. Rowbotham		ВНТ	45 °C	
Activity	Date	Time	Activity	Date	Time
Depart Base	08-Jul-19	19:30	Job End	09-Jul-19	6:00
Job Start	08-Jul-19	21:45	Return Base	09-Jul-19	6:15
Gauge Use	Pump Control		Surface Card	Not required	
Gauge Depth	761.02 m		Telemetry	Analogue	
Gauge Type	4-20mA 0-1.5k psi, 105 DegC		Surface Output	4-20mA	
Pres Range	0-1500 psia		Cable Splice Depth	N/A	
Batch	Mar-19 Gauge	e Ver2	Tubing Hanger	1/4in NPT - 1/	⁷ 4in Swagelok
Max Devi	0.0°		Wellhead Outlet	AnTech Type C	S/N 18-1173
TEC Cable	0.25" x 11mm	Encap	Encapsulation	Square 11mm	1
Serial Number	1013665687		Manufacturer	Draka	
Conductor	16 AWG Solid Copper		Material	Polypropylene	
Tube OD	0.25"		Pres Rating	15 kpsi	
Material	316L SS		Temp Rating	150 DegC	
Gauge	Analogue		Pres Sensor	Piezoresistive	
Serial Number	LC00379		Calibration Range	0 -1500 psia	
Depth	761.02 m		Temp Sensor	N/A	
OD	1"		Temp Range	N/A	
Vibration	N/A		Vibration Range	N/A	
Gauge Carrier		Cannon Clamp	Type with Vibration S	leeve	
Running OD		4.600"			
Serial Number		N/A			
Cross Coupling Protectors		2-3/8in - 3-1/2in Wiper Blade Style Stainless Steel			
Running OD		4.000"			
Qty Installed		79			
Bands and Clips Material		0.25" x 0.75" w-7/8" Buckle 316SS			
Qty Installed		160			

Comments: Gauge Carrier installed 2 full joints above PCP. 4-20mA Analogue gauge installed. RIH installing 79 banded CCP. Installed 2 x 1/4in NPT fittings in the hanger and pressure tested. Nippled down and installed Rod lock and AnTech wellhead outlet.



Permanent Monitoring Installation Report

Sequence of Events					
Date	Time	Description			
08-Jul-19	19:30	Travel to location.			
	20:30	Arrive location. Spot equipment.			
	21:45	Safety meeting with crew.			
	23:00	Pick up Sheave and make up BHA.			
	23:15	Make up gauge carrier and gauge to completion.			
		RIH first 4 joints then increase back tension on spooling unit.			
		Installed 79 banded cross coupling protectors.			
9-Jul-19	1:45	Make up hanger.			
		Strip encapsulation and pass cable through tubing hanger and tighten TEC seals.			
	2:00	Land hanger and start pressure test to 1500 psi.			
		Rig down floor.			
		Nippled down.			
	4:00	Land and nipple up rod-lock.			
		Pressure test rod lock to 300/3000 psi.			
	5:45	Install AnTech wellhead outlet.			
	6:00	Final gauge reading 1011 psia.			
		Prepare report.			
	6:15	Depart location for Roma.			
		Arrive at Roma.			