## **Permanent Monitoring Installation Report**



			1		
Field Ticket #	RGS2305290633		EOT	924.0 m MD	
Client	Santos Ltd		Tubing Size	2-7/8in 6.5 lb/ft	
Well Name	Bottle Tree 16		Casing Size	7in 23lb/ft	
Well Location	Arcadia Valley		SHP	0 psi	
Rig	MPK 8		ВНР	864 psi	
Customer Rep	Luke Owen		SHT	20 °C	
Service Eng	Kurt Rowbotham		ВНТ	45 °C	
Activity	Date	Time	Activity	Date	Time
Depart Base	27-May-23	15:30	Job End	29-May-23	13:05
Job Start	28-May-23	23:30	Return Base	29-May-23	13:30
Gauge Use	Pump Control		Surface Card	Not required	
Gauge Set Depth	754.49 m		Telemetry	Analogue	
Gauge Manufacturer	AnTech		Surface Output	4-20mA	
Pres Range	0-1500 psia		Max Temp Rating	105°C	
Cable Splice Depth	N/A		Tubing Hanger	2x1/4in NPT-1/4in Swagelok	
Max Devi	0.0°		Wellhead Outlet	AnTech Type C	S/N 19-057424
TEC Cable	0.25" Tube x 11mm Encap		Encapsulation	Square 11mm	
Serial Number	2000022705		<b>Encapsulation Type</b>	Polypropylene	
Conductor	16 AWG Solid Copper		Insulation	Double Insulated	
Tube OD	0.25"		Pres Rating	15 kpsi	
Material	316L SS		Temp Rating	150 DegC	
Gauge	4-20mA Analogue Pressure		Pres Sensor	Piezoresistive	
Serial Number	20-018998		Calibration Range	0 -1500 psia	
Gauge Set Depth	754.49 m		Temp Sensor	N/A	
OD	3/4"		Temp Range	N/A	
Vibration	N/A		Vibration Range	N/A	
Pres Range	0-1500 psia		Max Temp Rating	105°C	
Corrosion Protection	Yes		Protection Type	Titanium Gauge	
Gauge Batch	Nov-20		Burn-In Tested	No	
Gauge Carrier	Gauge Carrier Welded Pup Joint Gauge Carrier Annulus Gauge Port				
Running OD		3.985"			
Length		1.77m			
Serial Number		N/A			
Cross Coupling Protectors		2-3/8in - 3-1/2in Wiper Blade Style Stainless Steel			

Running OD 4.216"

Qty Installed 8

Bands and Clips Material 0.25" x 0.75" w-7/8" Buckle 316SS

Qty Installed 18



## **Permanent Monitoring Installation Report**

Sequence of Events				
Date	Time	Description		
27-May-23	15:30	Travel to Bottle Tree Camp.		
28-May-23	23:00	Travel to location.		
	23:15	Arrive location. Spot equipment.		
29-May-23		Safety meeting with crew.		
	2:00	Pick up Sheave and make up BHA.		
	2:15	Make up gauge carrier and gauge to completion.		
		RIH first 4 joints then increase back tension on spooling unit.		
		Installed 70 Cannon clamp protectors.		
		Installed 8 banded cross coupling protectors.		
	9:30	Make up hanger.		
		Strip encapsulation and pass cable through tubing hanger and tighten TEC seals.		
	9:45	Land hanger and start pressure test to 1500 psi.		
		Pressure test rod lock to 300/3000 psi.		
	12:45	Install AnTech wellhead outlet.		
	13:05	Final gauge reading 864 psia.		
	13:15	Prepare report.		
	13:30	Depart location for camp.		
	13:45	Arrive at camp.		