## **Permanent Monitoring Installation Report**



Field Ticket #	RGS1908270813		EOT	700.16 m MD	
Client			Tubing Size	2-7/8in 6.5 lb/ft	
Well Name	<u>-</u> .		Casing Size	7in 23lb/ft	
Well Location			SHP	0 psi	
Rig	Easternwell 27		ВНР	960 psi	
Customer Rep	L. Hay		SHT	20 °C	
Service Eng	J. Hollingworth		внт	35 °C	
Activity	Date	Time	Activity	Date	Time
Depart Base	26-Aug-19	9:30	Job End	27-Aug-19	8:10
Job Start	26-Aug-19	21:00	Return Base	27-Aug-19	14:00
Gauge Use	Pump Control		Surface Card	Not required	
Gauge Depth	681.66 m		Telemetry	Analogue	
Gauge Type	4-20mA 0-1.5k psi, 105 DegC		Surface Output	4-20mA	
Pres Range	0-1500 psia		Cable Splice Depth	N/A	
Batch	Jun-19 Gauge Ver2		Tubing Hanger	1/4in NPT - 1/4in Swagelok	
Max Devi	0.0°		Wellhead Outlet	AnTech Type C S/N 19-013197	
TEC Cable	0.25" x 11mm	Encap	Encapsulation	Square 11mm	ı
Serial Number	7020109970/20		Manufacturer	Draka	
Conductor	16 AWG Solid Copper		Material	Polypropylene	
Tube OD	0.25"		Pres Rating	15 kpsi	
Material	316L SS		Temp Rating	150 DegC	
Gauge	Analogue		Pres Sensor	Piezoresistive	
Serial Number	LC00475		Calibration Range	0 -1500 psia	
Depth	681.66 m		Temp Sensor	N/A	
OD	1"		Temp Range	N/A	
Vibration	N/A		Vibration Range	N/A	
Gauge Carrier Cannon Clamp Type with Vibration Sleeve					
Running OD		5.08"			
Serial Number		N/A			
Cross Coupling Protectors		2-3/8in - 3-1/2in Wiper Blade Style Stainless Steel			
Running OD		4.50"			
Qty Installed		74			
Bands and Clips Material		0.25" x 0.75" w-7/8" Buckle 316SS			
Qty Installed		148			
r			<u> </u>		

Comments: Gauge Carrier installed 1 full joints above PCP. 4-20mA Analogue gauge installed. RIH installing 74 banded CCP. Installed  $2 \times 1/4$  in NPT fittings in the hanger and pressure tested. Nippled down and installed Rod lock and AnTech wellhead outlet.





Sequence of Events					
Date	Time	Description			
26-Aug-19	9:30	Travel to location.			
	11:30	Arrive location. Standby at Camp			
	20:50	Called to Rig. Spot equipment.			
	22:00	Safety meeting with crew.			
	22:15	Pick up Sheave and make up BHA.			
22:40	Make up gauge carrier and gauge to completion.				
		RIH first 4 joints then increase back tension on spooling unit.			
		Installed 74 banded cross coupling protectors.			
27-Aug-19	2:50	Make up hanger.			
	3:15	Strip encapsulation and pass cable through tubing hanger and tighten TEC seals.			
	3:30	Land hanger and start pressure test to 3000 psi.			
7:30	Rig down floor.				
	Nippled down.				
	Land and nipple up rod-lock.				
	7:45	Pressure test rod lock to 300/1500 psi.			
	8:00	Install AnTech wellhead outlet.			
	8:10	Final gauge reading 960 psia.			
	8:15	Prepare report.			
	8:45	Travel to Camp			
		Depart camp for Roma.			
		Arrive at Roma.			