Permanent Monitoring Installation Report



Field Ticket #	RGS1807150319		EOT	827.1 m MD		
Client	Santos Ltd		Tubing Size	2-3/8in 4.7 lb/ft		
Well Name	RM50-20-1		Casing Size	7in 23lb/ft		
Well Location	Roma		SHP	0 psi		
Rig	Wild Desert 4		ВНР	1144 psi		
Customer Rep	Trevor Schulze		SHT	20 °C		
Service Eng	K.Rowbotham		ВНТ	45 °C		
Activity	Date	Time	Activity	Date	Time	
Depart Base	14-Jul-18	23:00	Job End	15-Jul-18	8:30	
Job Start	15-Jul-18	0:00	Return Base	15-Jul-18	8:45	
Gauge Use	Pump Control		Surface Card	Not required		
Gauge Depth	800.52 m		Telemetry	Analogue		
Gauge Type	4-20mA 0-1.5k psi, 105 DegC		Surface Output	4-20mA		
Pres Range	0-1500 psia		Cable Splice Depth	N/A		
Temp Range	N/A		Tubing Hanger	1/4in NPT - 1/4in Swagelok		
Max Devi	0.0°		Wellhead Outlet	AnTech Type	CS/N 18-1176	
TEC Cable	0.25" x 11mm Encap		Encapsulation	Square 11mm		
Serial Number	0001507869		Manufacturer	Draka		
Conductor	16 AWG Solid Copper		Material	Polypropylene		
Tube OD	0.25"		Pres Rating	15 kpsi		
Material	316L SS		Temp Rating	150 DegC		
Gauge	Analogue		Pres Sensor	Piezoresistive		
Serial Number	LC00129		Calibration Range	0 -1500 psia		
Depth	800.52 m		Temp Sensor	N/A		
OD	1"		Temp Range	N/A		
Vibration	N/A		Vibration Range	N/A		
Gauge Carrier	Gauge Carrier		Cannon Clamp Type with Vibration Sleeve			
Running OD	g OD		4.600"			
Serial Number		N/A				
Cross Coupling Protectors		2-3/8in - 3-1/2in Wiper Blade Style Stainless Steel				
Running OD		4.000"				
Qty Installed		85				
Bands and Clips Material		0.25" x 0.75" w-7/8" Buckle 316SS				
Qty Installed		170				

Comments: Gauge Carrier installed 2 full joints above PCP. 4-20mA Analogue gauge installed. RIH installing 85 banded CCP. Installed 2 x 1/4in NPT fittings in the hanger and pressure tested. Nippled down and installed Rod lock and AnTech wellhead outlet.



Sequence of Events				
Date	Time	Description		
14/07/2018	23:00	Depart Roma		
15/07/2018	0:00	Arrive location		
		Unload and spot equipment.		
	1:15	Safety meeting with crew.		
	1:45	Pick up Sheave and make up BHA		
	2:10	Make up gauge carrier and gauge to completion.		
		RIH first 4 joints then increase back tension on spooling unit.		
		Installed 85 banded cross coupling protectors.		
	4:15	Make up hanger.		
		Strip encapsulation and pass cable through tubing hanger and tighten TEC seals.		
	4:30	Land hanger and start pressure test to 1500 psi.		
		Rig down floor.		
	Nippled down.			
7:15		Land and nipple up rod-lock.		
		Pressure test rod lock to 300/3000 psi.		
	8:15	Install AnTech wellhead outlet.		
	8:30	Final gauge reading 1144 psia.		
	8:35	Prepare report.		
	8:45	Depart location for Roma.		