## **Permanent Monitoring Installation Report**



Field Ticket #	RGS19112009	73	ЕОТ	867.1 m MD		
Client	Santos Ltd		Tubing Size	2-3/8in 4.7 lb/ft		
Well Name	RM90-15-1		Casing Size	7in 23lb/ft		
Well Location	Roma		SHP	14 psi		
Rig	WildDesert 4		BHP	1201 psi		
Customer Rep	T.Schulze		SHT	20 °C		
Service Eng	G.Humphreys		BHT	45 °C		
	•					
Activity	Date	Time	Activity	Date Time		
Depart Base	20-Nov-19	5:00	Job End	20-Nov-19 10:00		
Job Start	20-Nov-19	6:20	Return Base	20-Nov-19 11:00		
Gauge Use	Pump Contro	I	Surface Card	Not required		
Gauge Depth	831.22 m		Telemetry	Analogue		
Gauge Type	4-20mA 0-1.5k psi, 105 DegC		Surface Output	4-20mA		
Pres Range	0-1500 psia		Cable Splice Depth	N/A		
Batch	Nov 19		Tubing Hanger	1/4in NPT - 1/4in Swagelok		
Max Devi	0.0°		Wellhead Outlet	AnTech Type C S/N19-028046		
TEC Cable	0.25" x 11mm Encap		Encapsulation	Square 11mm		
Serial Number	1015094256		Manufacturer	Draka		
Conductor	16 AWG Solid Copper		Material	Polypropylene		
Tube OD	0.25"		Pres Rating	15 kpsi		
Material	316L SS		Temp Rating	150 DegC		
Gauge	Analogue		Pres Sensor	Piezoresistive		
Serial Number	LC00650		Calibration Range	0 -1500 psia		
Depth	831.22 m		Temp Sensor	N/A		
OD	1"		Temp Range	N/A		
Vibration	N/A		Vibration Range	N/A		
Gauge Carrier	Gauge Carrier Cannon Clamp Type with Vibration Sleeve					
Running OD		4.600"	,,			
Serial Number		N/A				
Cross Coupling Protectors		2-3/8in - 3-1/2in Wiper Blade Style Stainless Steel				
Running OD		4.000"				
Qty Installed		87				
Bands and Clips Material		0.25" x 0.75" w-7/8" Buckle 316SS				
Qty Installed		176				

Comments: Gauge Carrier installed 2 full joints above PCP. 4-20mA Analogue gauge installed. RIH installing 87 banded CCP. Installed 2  $\times$  1/4in NPT fittings in the hanger and pressure tested. Nippled down and installed Rod lock and AnTech wellhead outlet.



## **Permanent Monitoring Installation Report**

Sequence of Events				
Date	Time	Description		
20-Nov-19		Depart Base		
6:00		Arrive at location		
	Wildesert Rig Crew to perform Gauge install.			
		Pick up Sheave and make up BHA.		
		Make up gauge carrier and gauge to completion.		
		RIH first 4 joints then increase back tension on spooling unit.		
		Installed 87 banded cross coupling protectors.		
	6:30	Make up hanger.		
		Strip encapsulation and pass cable through tubing hanger and tighten TEC seals.		
	6:45	Land hanger and start pressure test to 1500 psi.		
		Rig down floor.		
		Nippled down.		
		Land and nipple up rod-lock.		
		Pressure test rod lock to 300/3000 psi.		
	9:10	Install AnTech wellhead outlet.		
9:30	Final gauge reading 1201 psia.			
		Prepare report.		
	10:00	Depart location for Roma.		
		Arrive at Roma.		