Permanent Monitoring Installation Report



Field Ticket #	RGS1912180830		EOT	1090.2 m MD		
Client	Santos Ltd		Tubing Size	2-3/8in 4.7 lb/ft		
Well Name	RM40-152-1		Casing Size	5-1/2in 17lb/ft		
Well Location	Roma		SHP	0 psi		
Rig	WildDesert 4		ВНР	1702 psi		
Customer Rep	A.Riches		SHT	20 °C		
Service Eng	G.Matson / A.Hamilton		ВНТ	45 °C		
Activity	Date	Time	Activity	Date	Time	
Depart Base	18-Dec-19	3:00	Job End	18-Dec-19	9:00	
Job Start	18-Dec-19	4:00	Return Base	18-Dec-19	10:00	
Gauge Use	Pump Control		Surface Card	Not required		
Gauge Depth	1056.37 m		Telemetry	Analogue		
Gauge Type	4-20mA 0-3k psi, 105 DegC		Surface Output	4-20mA		
Pres Range	0-3000 psia		Cable Splice Depth	N/A		
Batch	Sep 19 BI		Tubing Hanger	1/4in NPT - 1/4in Swagelok		
Max Devi	0.0°		Wellhead Outlet	AnTech Type C	S/N 19-037234	
TEC Cable	0.25" x 11mm Encap		Encapsulation	Square 11mm		
Serial Number	1015198358		Manufacturer	Draka		
Conductor	16 AWG Solid Copper		Material	Polypropylene		
Tube OD	0.25"		Pres Rating	15 kpsi		
Material	316L SS		Temp Rating	150 DegC		
Gauge	Analogue		Pres Sensor	Piezoresistive		
Serial Number	LC00560		Calibration Range	0 -3000 psia		
Depth	1056.37 m		Temp Sensor	N/A		
OD	1"		Temp Range	N/A		
Vibration	N/A		Vibration Range	N/A		
Gauge Carrier	Gauge Carrier Cannon Clamp Type with Vibration Sleeve					
Running OD	Running OD		4.286"			
Serial Number		N/A				
Cross Coupling Protectors		2-3/8in - 3-1/2in Wiper Blade Style Stainless Steel				
Running OD		4.000"				
Qty Installed		110				
Bands and Clips Material		0.25" x 0.75" w-7/8" Buckle 316SS				
Qty Installed		222				

Comments: Gauge Carrier installed 2 full joints above PCP. 4-20mA Analogue gauge installed. RIH installing 110 banded CCP. Installed 2 \times 1/4in NPT fittings in the hanger and pressure tested. Nippled down and installed Rod lock and AnTech wellhead outlet.



Permanent Monitoring Installation Report

Sequence of Events			
Date	Time	Description	
		Wildesert Rig Crew to perform Gauge install.	
		Pick up Sheave and make up BHA.	
		Make up gauge carrier and gauge to completion.	
		RIH first 4 joints then increase back tension on spooling unit.	
		Installed 110 banded cross coupling protectors.	
18-Dec-19	3:00	Depart Base	
	4:00	Arrive at location	
	4:30	Make up hanger.	
	5:00	Strip encapsulation and pass cable through tubing hanger and tighten TEC seals.	
	5:30	Land hanger and start pressure test to 1500 psi.	
	6:00	Rig down floor.	
	6:30	Nippled down.	
	7:00	Land and nipple up rod-lock.	
	7:30	Final gauge reading 1460.92 psia.	
	7:50	Pressure test rod lock to 300/3000 psi	
	8:20	Install AnTech wellhead outlet.	
	8:30	Prepare report.	
	9:00	Depart location for Roma.	
	10:00	Arrive at Roma.	