## **Permanent Monitoring Installation Report**



				-	
Field Ticket #	RGS1906202050		EOT	758.0 m MD	
Client	Santos Ltd		Tubing Size	2-3/8in 4.7 lb/ft	
Well Name	Maisey 116		Casing Size	7in 23lb/ft	
Well Location	Roma		SHP	0 psi	
Rig	WildDesert 4		ВНР	1052 psi	
Customer Rep	T. Robitaille		SHT	20 °C	
Service Eng	G.Humphreys		ВНТ	45 °C	
Activity	Date	Time	Activity	Date	Time
Depart Base	20-Jun-19	16:30	Job End	20-Jun-19	21:30
Job Start	20-Jun-19	17:30	Return Base	20-Jun-19	21:45
Gauge Use	Pump Control		Surface Card	Not required	
Gauge Depth	723.63 m		Telemetry	Analogue	
Gauge Type	4-20mA 0-1.5k psi, 105 DegC		Surface Output	4-20mA	
Pres Range	0-1500 psia		Cable Splice Depth	N/A	
Batch	March 19		Tubing Hanger	1/4in NPT - 1/	′4in Swagelok
Max Devi	0.0°		Wellhead Outlet	AnTech Type C	S/N 19-004129
TEC Cable	0.25" x 11mm	Encap	Encapsulation	Square 11mm	ı
Serial Number	7020095410/50		Manufacturer	Draka	
Conductor	16 AWG Solid Copper		Material	Polypropylene	
Tube OD	0.25"		Pres Rating	15 kpsi	
Material	316L SS		Temp Rating	150 DegC	
Gauge	Analogue		Pres Sensor	Piezoresistive	
Serial Number	LC00337		Calibration Range	0 -1500 psia	
Depth	723.63 m		Temp Sensor	N/A	
OD	1"		Temp Range	N/A	
Vibration	N/A		Vibration Range	N/A	
Gauge Carrier	Gauge Carrier Cannon Clamp Type with Vibration Sleeve				
Running OD		4.600"			
Serial Number		N/A			
Cross Coupling Protectors		2-3/8in - 3-1/2in Wiper Blade Style Stainless Steel			
Running OD		4.000"			
Qty Installed		75			
Bands and Clips Material		0.25" x 0.75" w-7/8" Buckle 316SS			
Qty Installed		152			

Comments: Gauge Carrier installed 2 full joints above PCP. 4-20mA Analogue gauge installed. RIH installing 75 banded CCP. Installed 2 x 1/4in NPT fittings in the hanger and pressure tested. Nippled down and installed Rod lock and AnTech wellhead outlet.



## **Permanent Monitoring Installation Report**

	Sequence of Events				
Date	Time	Description			
20-Jun-19		Wildesert Rig Crew to perform Gauge install.			
		Pick up Sheave and make up BHA.			
		Make up gauge carrier and gauge to completion.			
		RIH first 4 joints then increase back tension on spooling unit.			
		Installed 75 banded cross coupling protectors.			
16:30		Depart Base			
		Arrive at location			
	17:45	Make up hanger.			
		Strip encapsulation and pass cable through tubing hanger and tighten TEC seals.			
	18:00	Land hanger and start pressure test to 1500 psi.			
		Rig down floor.			
		Nippled down.			
	20:15	Land and nipple up rod-lock.			
		Pressure test rod lock to 300/3000 psi.			
		Install AnTech wellhead outlet.			
	21:20	Final gauge reading 1051.6 psia.			
		Prepare report.			
	21:45	Depart location for Roma.			
		Arrive at Roma.			