Permanent Monitoring Installation Report



Field Ticket #	RGS1910131344		EOT	700.6 m MD		
Client			Tubing Size	2-7/8in 6.5 lb/ft		
Well Name	<u>.</u>		Casing Size	7in 23lb/ft		
Well Location			SHP	0 psi		
Rig	EWE 27		ВНР	946 psi		
Customer Rep	L. Hay		SHT	20 °C		
Service Eng	J. Hollingwort	h	внт	30 °C		
Activity	Date	Time	Activity	Date	Time	
Depart Base	13-Oct-19	6:00	Job End	13-Oct-19	17:00	
Job Start	13-Oct-19	9:15	Return Base	13-Oct-19	19:30	
Gauge Use	Pump Control		Surface Card	Not required		
Gauge Depth	683.25 m		Telemetry	Analogue		
Gauge Type	4-20mA 0-1.5k psi, 105 DegC		Surface Output	4-20mA		
Pres Range	0-1500 psia		Cable Splice Depth	N/A		
Batch	Jun-19 Gauge Ver2		Tubing Hanger	1/4in NPT - 1/4in Swagelok		
Max Devi	0.0°		Wellhead Outlet	AnTech Type C	S/N 19-027849	
TEC Cable	0.25" x 11mm Encap		Encapsulation	Square 11mm		
Serial Number	7020109970/60		Manufacturer	Draka		
Conductor	16 AWG Solid Copper		Material	Polypropylene		
Tube OD	0.25"		Pres Rating	15 kpsi		
Material	316L SS		Temp Rating	150 DegC		
Gauge	Analogue		Pres Sensor	Piezoresistive		
Serial Number	LC00610		Calibration Range	0 -1500 psia		
Depth	683.25 m		Temp Sensor	N/A		
OD	1"		Temp Range	N/A		
Vibration	N/A		Vibration Range	N/A		
Gauge Carrier	Cannon Clamp Type with Vibration Sleeve					
Running OD		5.08"				
Serial Number		N/A				
Cross Coupling Protectors		2-3/8in - 3-1/2in Wiper Blade Style Stainless Steel				
Running OD		4.50"				
Qty Installed		72				
Bands and Clips Material		0.25" x 0.75" w-7/8" Buckle 316SS				
Qty Installed		145				

Comments: Gauge Carrier installed 1 full joints above PCP. 4-20mA Analogue gauge installed. RIH installing 72 banded CCP. Installed $1 \times 1/4$ in NPT fittings in the hanger and pressure tested. Nippled down and installed Rod lock and AnTech wellhead outlet.



Permanent Monitoring Installation Report

Sequence of Events				
Date	Time	Description		
13-Oct-19	6:00	Travel to location & Standby at Camp.		
	7:45	Arrive location. Spot equipment.		
	9:30	Pick up Sheave and make up BHA.		
	9:45	Make up gauge carrier and gauge to completion.		
		RIH first 4 joints then increase back tension on spooling unit.		
		Installed 72 banded cross coupling protectors.		
	12:00	Make up hanger.		
	12:15	Strip encapsulation and pass cable through tubing hanger and tighten TEC seals.		
	12:30	Land hanger and start pressure test to 1500 psi.		
		Nippled down.		
	15:45	Land and nipple up rod-lock.		
	16:15	Pressure test rod lock to 250/1500 psi.		
	16:45	Install AnTech wellhead outlet.		
	17:00	Final gauge reading 946 psia. 14.1mA		
	17:10	Prepare report.		
	17:30	Depart location for Camp.		
		Depart camp for Roma Base.		