## **Permanent Monitoring Installation Report**



Field Ticket #	RGS1908130942		EOT	655.1 m MD		
Client	Senex Energy Limited		Tubing Size	2-7/8in 6.4 lb/ft		
Well Name	<u>.</u> ,		Casing Size	7in 23lb/ft		
Well Location	Wandoan		SHP	0 psi		
Rig	Easternwell 27		ВНР	919 psi		
<b>Customer Rep</b>	R. Dzivinski		SHT	20 °C		
Service Eng	K. Rowbotham		внт	30 °C		
Activity	Date	Time	Activity	Date	Time	
Depart Base	11-Aug-19	18:00	Job End	13-Aug-19	13:10	
Job Start	13-Aug-19	3:00	Return Base	13-Aug-19	0:00	
Gauge Use	Pump Control		Surface Card	Not required		
Gauge Depth	635.93 m		Telemetry	Analogue		
Gauge Type	4-20mA 0-1.5k psi, 105 DegC		Surface Output	4-20mA		
Pres Range	0-1500 psia		Cable Splice Depth	N/A		
Batch	Jun-19 Gauge Ver2		Tubing Hanger	1/4in NPT - 1/4in Swagelok		
Max Devi	0.0°		Wellhead Outlet	AnTech Type C S/N 19-013196		
TEC Cable	0.25" x 11mm Encap		Encapsulation	Square 11mm		
Serial Number	7020109970/20		Manufacturer	Draka		
Conductor	16 AWG Solid Copper		Material	Polypropylene		
Tube OD	0.25"		Pres Rating	15 kpsi		
Material	316L SS		Temp Rating	150 DegC		
Gauge	Analogue		Pres Sensor	Piezoresistive		
Serial Number	LC00494		Calibration Range	0 -1500 psia		
Depth	635.93 m		Temp Sensor	N/A		
OD	1"		Temp Range	N/A		
Vibration	N/A		Vibration Range	N/A		
Gauge Carrier	Cannon Clamp Type with Vibration Sleeve					
Running OD	Running OD		5.08"			
Serial Number		N/A				
Cross Coupling Protectors		2-3/8in - 3-1/2in Wiper Blade Style Stainless Steel				
Running OD		4.50"				
Qty Installed		70				
Bands and Clips Material		0.25" x 0.75" w-7/8" Buckle 316SS				
Qty Installed		140				

Comments: Gauge Carrier installed 1 full joints above PCP. 4-20mA Analogue gauge installed. RIH installing 70 banded CCP. Installed 2  $\times$  1/4in NPT fittings in the hanger and pressure tested. Nippled down and installed Rod lock and AnTech wellhead outlet.



Sequence of Events				
Date	Time	Description		
11-Aug-19	18:00	Travel to location.		
	20:00	Arrive location. Standby at Camp		
12-Aug-19		Standby at camp.		
13-Aug-19	1:30	Called to Rig. Spot equipment.		
	3:00	Safety meeting with crew.		
	3:15	Pick up Sheave and make up BHA.		
	3:30	Make up gauge carrier and gauge to completion.		
		RIH first 4 joints then increase back tension on spooling unit.		
		Installed 70 banded cross coupling protectors.		
	8:00	Make up hanger.		
		Strip encapsulation and pass cable through tubing hanger and tighten TEC seals.		
	8:15	Land hanger and start pressure test to 3000 psi.		
		Rig down floor.		
		Nippled down.		
	11:30	Land and nipple up rod-lock.		
	12:00	Pressure test rod lock to 300/1500 psi.		
	12:50	Install AnTech wellhead outlet.		
	13:00	Final gauge reading 919 psia.		
	13:10	Prepare report.		
	13:15	Travel to Camp		
		Depart camp for Roma.		
		Arrive at Roma.		