Permanent Monitoring Installation Report



Field Ticket #	RGS1905222300		EOT	1263.7 m		
Client			Tubing Size	2-7/8in 6.5 lb/ft		
Well Name	FV11-74-21		Casing Size	5-1/2in 20lb/ft		
Well Location	Fairview		SHP	0 psi		
Rig	Sav. 68		ВНР	1780 psi		
Customer Rep	C.Gustafson		SHT	0 °C		
Service Eng	G. Humphreys		внт	0 °C		
Activity	Date	Time	Activity	Date	Time	
Depart Base	21-May-19	6:00	Job End	22-May-19	23:10	
Job Start	21-May-19	2:30	Return Base	22-May-19	23:20	
Gauge Use	Pump Control		Surface Card	Not required		
Gauge Depth	1251.61		Telemetry	Analogue		
Gauge Type	4-20mA 0-3k psi, 105 DegC		Surface Output	4-20mA		
Pres Range	0-3000 psia		Cable Splice Depth	N/A		
Batch	Feb-19		Tubing Hanger	3/8in NPT - 1/4in Swagelok		
Max Devi	<15°		Wellhead Outlet	AnTech Type C-18-022025		
TEC Cable	0.25" x 11mm Encap		Encapsulation	Square 11mm		
Serial Number	702009307/50		Manufacturer	Draka		
Conductor	16 AWG Solid Copper		Material	Polypropylene		
Tube OD	0.25"		Pres Rating	15 kpsi		
Material	316L SS		Temp Rating	150 DegC		
Gauge	Analogue		Pres Sensor	Piezoresistive		
Serial Number	LC00289		Calibration Range	0 -3000 psia		
Depth	1251.61 m		Temp Sensor	N/A		
OD	1"		Temp Range	N/A		
Vibration	N/A		Vibration Range	N/A		
Gauge Carrier	Gauge Carrier We		Welded Pup Joint			
Running OD	D		4.286"			
Serial Number		N/A				
Cross Coupling Protectors		2-3/8in - 2-7/8in Wiper Blade Style Stainless Steel				
Running OD		4.216"				
Qty Installed		132				
Bands and Clips Material		0.25" x 0.75" w-7/8" Buckle 316SS				
Qty Installed		266				

Comments: Gauge Carrier Pup Joint installed 2 full joints above PSN. 4-20mA Analogue gauge installed. RIH installing 132 banded CCP. Installed $2 \times 1/4$ in NPT fittings in the hanger and pressure tested. Nippled down and installed Rod lock and AnTech wellhead outlet.



Permanent Monitoring Installation Report

	Sequence of Events				
Date	Time	Description			
21-May-19		Standby at camp.			
14:00		Arrive location.			
		Unload and spot equipment. Drift and measure gauge carrier 1.88m, 1.22m to Gauge Port.			
	14:45	Safety meeting with crew.			
		Pick up Sheave and make up BHA.			
	15:00	Make up gauge carrier and gauge to completion.			
		RIH first 4 joints then increase back tension on spooling unit.			
		Installed 132 banded cross coupling protectors.			
	20:00	Strip encapsulation and pass cable through tubing hanger and tighten TEC seals.			
	20:10	Land hanger and start pressure test to 1500 psi.			
		Rig down floor.			
		Nipple down BOPs.			
22:00	Land and nipple up rod-lock.				
	Pressure test rod lock to 300/3000 psi.				
		Install AnTech wellhead outlet.			
23:00		Final gauge reading 1779.8psia			
		Prepare report.			
	23:20	Depart location for Camp.			