## **Permanent Monitoring Installation Report**



Field Ticket #	RGS1905161822		EOT	839.0 m MD		
Client			Tubing Size	2-3/8in 4.7 lb/ft		
Well Name			Casing Size	7in 23lb/ft		
Well Location			SHP	0 psi		
Rig	WildDesert 4		ВНР	1171 psi		
<b>Customer Rep</b>	Tony Robitaille		SHT	20 °C		
Service Eng	·		внт	45 °C		
Activity	Date	Time	Activity	Date	Time	
Depart Base	16-May-19	15:00	Job End	16-May-19	19:45	
Job Start	16-May-19	16:45	Return Base	16-May-19	20:15	
Gauge Use	Pump Control		Surface Card	Not required		
Gauge Depth	807.41 m		Telemetry	Analogue		
Gauge Type	4-20mA 0-1.5k psi, 105 DegC		Surface Output	4-20mA		
Pres Range	0-1500 psia		Cable Splice Depth	N/A		
Batch	Mar 19" Rev 2		Tubing Hanger	1/4in NPT - 1/4in Swagelok		
Max Devi	0.0°		Wellhead Outlet	AnTech Type C S/N 19-004136		
TEC Cable	0.25" x 11mm Encap		Encapsulation	Square 11mm		
Serial Number	7020095410/20		Manufacturer	Draka		
Conductor	16 AWG Solid Copper		Material	Polypropylene		
Tube OD	0.25"		Pres Rating	15 kpsi		
Material	316L SS		Temp Rating	150 DegC		
Gauge	Analogue		Pres Sensor	Piezoresistive		
Serial Number	LC00322		Calibration Range	0 -1500 psia		
Depth	807.41 m		Temp Sensor	N/A		
OD	1"		Temp Range	N/A		
Vibration	N/A		Vibration Range	N/A		
Gauge Carrier		Cannon Clamp	mp Type with Vibration Sleeve			
Running OD	g OD		4.600"			
Serial Number		N/A				
Cross Coupling Protectors		2-3/8in - 3-1/2in Wiper Blade Style Stainless Steel				
Running OD		4.000"				
Qty Installed		85				
Bands and Clips Material		0.25" x 0.75" w-7/8" Buckle 316SS				
Qty Installed		172				

Comments: Gauge Carrier installed 2 full joints above PCP. 4-20mA Analogue gauge installed. RIH installing 85 banded CCP. Installed 2  $\times$  1/4in NPT fittings in the hanger and pressure tested. Nippled down and installed Rod lock and AnTech wellhead outlet.



## **Permanent Monitoring Installation Report**

Sequence of Events				
Date	Time	Description		
		Wildesert Rig Crew to perform Gauge install.		
		Pick up Sheave and make up BHA.		
		Make up gauge carrier and gauge to completion.		
		RIH first 4 joints then increase back tension on spooling unit.		
		Installed 85 banded cross coupling protectors.		
16-May-19	15:00	Depart Base		
	16:00	Arrive at location		
	16:45	Make up hanger.		
		Strip encapsulation and pass cable through tubing hanger and tighten TEC seals.		
	17:15	Land hanger and start pressure test to 1500 psi.		
		Rig down floor.		
		Nippled down.		
	18:45	Land and nipple up rod-lock.		
		Pressure test rod lock to 300/3000 psi.		
	19:30	Install AnTech wellhead outlet.		
	19:45	Final gauge reading 1170.55 psia.		
		Prepare report.		
	20:15	Depart location for Roma.		
	21:15	Arrive at Roma.		