

Summary report

Wellbore: 15/9-F-1 C

Period: 2016-06-28 00:00 - 2016-06-29 00:00

Status:	normal
Report creation time:	2018-05-03 13:51
Report number:	14
Days Ahead/Behind (+/-):	2.2
Operator:	Statoil
Rig Name:	MÆRSK INSPIRER
Drilling contractor:	Maersk Drilling
Spud Date:	2014-02-21 14:30
Wellbore type:	
Elevation RKB-MSL (m):	54.9
Water depth MSL (m):	91
Tight well:	Y
HPHT:	Y
Temperature (I):	
Pressure (I):	
Date Well Complete:	2014-03-15

Dist Drilled (m):	-999.99
Penetration rate (m/h):	-999.99
Hole Dia (I):	
Pressure Test Type:	formation integrity test
Formation strength (g/cm3):	1.6
Dia Last Casing (I):	

Depth at Kick Off mMD:	
Depth at Kick Off mTVD:	
Depth mMd:	-999.99
Depth mTVD:	
Plug Back Depth mMD:	3100
Depth at formation strength mMD:	3059
Depth At Formation Strength mTVD:	2874.4
Depth At Last Casing mMD:	4087.1
Depth At Last Casing mTVD:	3178

Summary of activities (24 Hours)

- Milled 10 3/4 in subsea casing hanger
- RIH w/ spear BHA, attempted to catch 10 3/4 x 9 5/8 csg fish

Summary of planned activities (24 Hours)

- RIH w/ csg cutter, cut 9 5/8 csg
- RIH w/ spear, pull 10 3/4 x 9 5/8 casing above cut
- RIH w/ spear, pull 9 5/8 remaining casing
- Install 13 3/8 EZSV plug
- Place sement plug in 13 3/8 csg

Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
00:00	00:45	0	plug abandon -- mill	ok	R/B stand of DP. Broke connection w/ 150KNM. Inspect TDS after milling operation. Broke saversub w/ 100KNM
00:45	01:30	0	plug abandon -- mill	ok	M/U saversub to TDS. R/B stand of DP
01:30	02:45	0	plug abandon -- mill	ok	POOH w/ milling BHA to surface, inspect same, cleaned magnets, 6 kg metal recovered from magnet (very fine swarf). Some wear observed on the cutting faces of mill
02:45	03:45	0	plug abandon -- mill	ok	M/U BHA w/ new milling assembly
03:45	04:15	0	plug abandon -- mill	ok	M/U 2ea stands of DP, M/U TDS, established circulation
04:15	12:00	141	plug abandon -- mill	ok	Milling out 10 3/4in casing hanger. @ 100-120 RPM 1-3 WOB, 2000 LPM, 3-11 Knm, 5-7 BAR String stalled out several times @ 24Knm. +/-25 overpull to free pipe. Milled from 140.98m to 141.10m. Very slow progress
12:00	14:45	141	plug abandon -- mill	ok	Continued milling out 10 3/4in casing hanger. @ 100-120 RPM 1-3 WOB, 2000 LPM, 3-11 Knm, 5-7 BAR String stalled out several times @ 24Knm. +/-25 overpull to free pipe. Milled from 141.10m to 141.23m. Improved progress. Got traces of H2S of 12 ppm
14:45	16:15	141	plug abandon -- mill	ok	Picked of btm and circulated clean while discussing way forward. Data indicated that mill has passed the hanger, estimated 20cm below planned milling depth, it was decided to POOH w/ milling BHA and attempt to pull csg
16:15	16:30	141	plug abandon -- mill	ok	Performed Pre-job Meeting
16:30	17:00	141	plug abandon -- mill	ok	Unable to break out connection. Broke out double and layed out same.
17:00	17:15	141	plug abandon -- mill	ok	DROP check on TDS
17:15	18:15	85	plug abandon -- mill	ok	POOH from 110m to 12 m, all connections over torqued
18:15	18:30	0	plug abandon -- mill	ok	Pulled mill and magnet assy, 1,5kg fine swarf recovered from magnets. Cleaned magnets, checked mill in gauge, observed normal wear on cutting faces
18:30	18:45	0	plug abandon -- mill	ok	Layed out mill assy to deck
18:45	19:00	0	plug abandon -- mill	ok	Cleaned and cleared rig floor
19:00	19:15	0	plug abandon -- other	ok	Performed Pre-job Meeting prior to P/U BHA
19:15	21:00	0	plug abandon -- trip	ok	M/U spear BHA #19
21:00	21:30	135	plug abandon -- trip	ok	RIH spear BHA on DP to 135m spear depth. L/D single for spaceout
21:30	21:45	135	plug abandon -- trip	ok	M/U TDS to string. Recorded weights. Weight Up 76T, Weight Down 74T, Free rotation 75T, 3RPM, 0,5KNM
21:45	22:15	140	plug abandon -- other	ok	RIH while pumping @ 300LPM. Tagged hanger w/ 12,25 guide sleeve @ 140m, spear depth @ 153,4m. Attempted to engage spear. No success.
22:15	23:00	0	plug abandon -- other	ok	POOH w/ spear BHA #19, inspected spear, ok. Set spear in catch mode.
23:00	23:45	140	plug abandon -- other	ok	RIH w/ spear BHA #20 until 12,25 guide sleeve is just above hanger @ 140m
23:45	00:00	140	plug abandon -- other	ok	Attempted to engage spear to fish. No success. Tagged hanger with 12,25 guide sleeve and set down 5T