O&M; Work Order WO-4471

Asset: WND-2 (Kutch wind farm). Gearbox oil and vibration inspection.

Scheduled maintenance requires 4 hours of downtime within the next 24 h.

Item	Detail
Crew	Vestas service team B
Permit	PTW-2291
Isolation	Full turbine string