

Element B

Previous and Future Solutions

The art teacher had tried no prior solutions to fix the problem, due to her short tenure at Eleanor Roosevelt High, (about 2 years) and was hoping for it to be resolved on its own. Despite this, no solution arose and the humidity continued to affect the clay and paper. However, after looking through the internet many solutions were brought up. Such solutions include using a dehumidifier, avoid storing the paper and clay near heating vents, or storing the paper and clay within waterproof cases. But due to the rules in the school, the teacher was unable to put such devices in the classroom. The Student engineers are trying to create a solution that will be:

- Mobile
- Efficient
- Cheap
- Easily maintainable..

These are the general standards that student engineers are requiring. As a whole class, the students engineers came up with different ideas as a solution this problem that incorporate these ideas.