

Element H: Prototype Testing and Data Collection Plan

Testing Details Requirement

1ex The prototype must be able to be activated when it is worn.

- 1) Put the belt on and then try to hold down the button to turn on and off.



2ex The belt must be able to close and function correctly with the prototype.

2) Put the pouch on the belt and then put on the belt and try to loop all the way.



3ex The prototype must remain intact when dropped from waist height.

3) Drop the belt from belt height and then try to turn on and off the prototype.



Fail: Belt or prototype is unable to function correctly.

Pass: Both belt and prototype are able to function correctly at the same time.

Goal: Have the belt and especially the prototype to both function correctly at the same time.