

Element A: Presentation and Justification of the Problem:

We need to create a system to blow debris away from the mill drill bit so as to not impede its path and to increase the accuracy of the mill's drill bit. This will also help maintain the mill by putting less stress on its parts and drill bits.