

Element L:

Major improvements start of the designing phase. A more detailed touch up on the final design of the design matrix should've been done to allow for a more efficient product. Craftsmanship was limited due to a heavy time constraint. Cuts were uneven, edges were rough, and lines were crooked. This could all be improved with better care and more experience. Materials were limited to what was found in the workshop. The wood used was rough, the walls were thin, and a plastic top for safety was not implemented due to the lack of materials.

For steps of improvement to be implemented. Lots of the materials would have to be replaced for better quality, like to base and wall materials. Redesign would aid in reaching the goal lines. Recalculations on the wall to maximize spin could be used to improve distance and a better exit for accuracy. The wall adjustability could be reinstated, along with a more user friendly input. A scrapped idea of a lever to lightly push the frisbees in was scrapped. Craftsmanship could smooth out areas like weirdly shaped cuts and messy hot gluing. More specific test plans to air weak points and allow for more depth into places for improvement.