

Programmability
Size
Power supply
Weight capacity
Mobility

Programmability - Low priority
Size - Medium Priority
Power supply - High Priority
Weight capacity - High Priority
Mobility - Medium Priority

First we would place our plant in the tray and then we would make sure everything was hooked up correctly. Once we were positive that everything was corrected; we hooked up the buzzer and the timer. The rollers would start turning the burlap over the tray and under it, which in the actual test would give it an adequate amount of sunlight.

Based on our testing data, we found that many people said that we should've had a bigger motor which means it would have most likely worked because our motors were unable to turn the needed material.

Our discussion from our tables concluded that if we were supplied a bigger motor it would likely work, all of the people at the design-a-thon thought that it was creative and successful if we had a motor.

Get a bigger motor to operate properly then close in the motor and electronics to prevent them from getting wet. Then finally we will find a way to lower the rate of wear on the string, then we will put bearings on the rollers to reduce friction.