TAMIL NABU FIRE - RESCUE SERVICES FIRE SERVICE LICENSE

(Finder Section 13 of Francis Nadio Fire Service Act 1985 readwith Tamil Nadio Fire Service (Rales 1990 Appendix IV)

LICENCE NO. 486-2023 L.Dis. No. 7181/C1/2023

.08, 2023Date:

Useruse is herein granted under section 13 of the Tamil Nadu Fire Service Act, 1985, For Stelling/Storing / Processing Pressing/ Transporting of Fire Works / Crackers / Petroleum items / 139G Gos Cylinders / Explosives / other items. REBEL FOODS PVT LTD. (mention whichever is applicable) within the jurisdiction of THIRUCHIRAPPALLI Municipality/ Panchayat / Corporation at the pressises NO.73EG, FIRST FLOOR, SALAI ROAD, THILLAI NAGAR Taluk / Town THIRUCHIRAPPALLL District THIRUCHIRAPPALLL Subject to the conditions noted thereon and such other conditions as may be prescribed. Inspected by- Asst. District Officer, Trichy On 12.08.2023 This license is valid for one year from the date of issue.

CONDITIONS

As per Cot. 13 of Appendix V to the Rules under Section 13 of the Act.

- 1. Fire extinguishers installed in the premises should be maintained property.
- 2. Height of the Building 13.00 Mtrs, No. of Floors GF+2 Floors
- 3. All Provided fire fighting measures to be maintained properly and periodically.
- 4. Regular License has to be obtained from the Competent authority.
- 5. All Fixed installation should be maintained properly as per NBC-2016.
- 6. Register of Fire extinguishers and Register of mock drill should be maintained as per form 1 & III respectively.
- 7. (Off site emergency) Mock drill should be conducted every year.
- 8. Elementary fire fighting training should be given to the employees from fire service

9. A Board hearing the phone number of the Fire & Rescue station and other emergency number should be displayed in the premises.

10. House keeping should be great and chiff

(Office Scal with Date.)

2 4 AUG 2023

REREL FOODS PVT LTD.

No. 73E/3, First Floor, Salai Road,

Thilliat Nagar

Trichy- 18.

In.

Cupy to: Deputy Director, Central Region, Tricky.

Scanned with CamScanner

Fire & Rescue Service.