

Release Notes: JN-AN-1246 DK006: JN5189 / JN5188 / K32W061 / K32W041

Zigbee 3.0 Sensors

These release notes provide information on the SDK compatibility, memory usage and change history for the JN-AN-1246 Zigbee 3.0 Sensors Application Note.

1 Public v2003- 23-Dec-2020

Public release for DK006: JN5189 / JN5188 / K32W061 / K32W041.

1.1 Public v2003: Compatibility

The software provided with this Application Note has been tested with the following evaluation kits and SDK versions. The supplied makefiles are configured to compile for K32W061 chips on the K32W061DK6 SDK which was also used to create the pre-built binaries, there is information on the main Application Note document on how to compile for different chips/SDKs.

Product Type	Part Number	Version	Supported Chips
JN518x Development Kit	JN518x-DK006	-	JN5189 / JN5188
IoT_ZTB Development Kit	IoT_ZTB-DK006	-	K32W061 / K32W041
MPCXpresso –Toolchain		v11.2.1 build 4149	JN5189 / JN5188 K32W061 / K32W041
Development Kit – SDK	K32W061DK6	v2.6.2 MR2	JN5189 / JN5188 K32W061 / K32W041

1.2 Public v2003: Memory Usage

The applications of this Application Note have the following memory footprints:

```
text data bss dec filename

167312 1584 17616 186512 LightSensor_OM15081R2

191776 1744 19984 213504 LightSensor_NtagIcode_Ota_OM15081R2

168920 1688 18160 188768 LTOSensor_OM15081R2

193200 1856 20512 215568 LTOSensor_NtagIcode_Ota_OM15081R2

170244 1596 17600 189440 OccupancySensor_OM15082

195580 1748 19968 217296 OccupancySensor NtagIcode Ota OM15082
```

1.3 Public v2003: End Device RAM Retention

retain	spare	kb	banks fi	ilename
18120	6456	24	4567	LTOSensor NtagIcode Ota OM15081R2
15080	1304	16	567	OccupancySensor OM15082
17480	7096	24	4567	OccupancySensor NtagIcode Ota OM15082
15080	1304	16	567	LightSensor OM15081R2
17480	7096	24	4567	LightSensor NtagIcode Ota OM15081R2
15736	648	16	567	LTOSensor OM15081R2

1.4 Public v2003: New Features

None.

1.5 Public v2003: Bug Fixes

None.

1.6 Public v2003: Known Issues

None.

2 Public v2002- 21-Aug-2020

Public release for DK006: JN5189 / JN5188 / K32W061 / K32W041.

2.1 Public v2002: Compatibility

The software provided with this Application Note has been tested with the following evaluation kits and SDK versions. The supplied makefiles are configured to compile for K32W061 chips on the K32W061DK6 SDK which was also used to create the pre-built binaries, there is information on the main Application Note document on how to compile for different chips/SDKs.

Product Type	Part Number	Version	Supported Chips
JN518x Development Kit	JN518x-DK006	-	JN5189 / JN5188
IoT_ZTB Development Kit	IoT_ZTB-DK006	-	K32W061 / K32W041
MPCXpresso –Toolchain		v11.2.0 build 4120	JN5189 / JN5188 K32W061 / K32W041
Development Kit – SDK	K32W061DK6	v2.6.1 MR1	JN5189 / JN5188 K32W061 / K32W041

2.2 Public v2002: Memory Usage

The applications of this Application Note have the following memory footprints:

```
text data bss dec filename

164912 1552 17520 183984 LightSensor_OM15081R2

189312 1712 19888 210912 LightSensor_NtagIcode_Ota_OM15081R2

166520 1640 18064 186224 LTOSensor_OM15081R2

190800 1824 20416 213040 LTOSensor_NtagIcode_Ota_OM15081R2

167844 1564 17504 186912 OccupancySensor_OM15082

193180 1716 19872 214768 OccupancySensor_NtagIcode Ota_OM15082
```

2.3 Public v2002: End Device RAM Retention

```
retain spare kb banks filename
17992 6584 24 ----4567 LTOSensor_NtagIcode_Ota_OM15081R2
14952 1432 16 -----567 OccupancySensor_OM15082
17352 7224 24 ----4567 OccupancySensor_NtagIcode_Ota_OM15082
14952 1432 16 -----567 LightSensor_OM15081R2
17352 7224 24 ----4567 LightSensor_NtagIcode_Ota_OM15081R2
15592 792 16 -----567 LTOSensor_OM15081R2
```

2.4 Public v2002: New Features

None.

2.5 Public v2002: Bug Fixes

None.

2.6 Public v2002: Known Issues

None.

3 Public v2001- 17-Apr-2020

Public release for DK006: JN5189 / JN5188 / K32W061 / K32W041.

3.1 Public v2001: Compatibility

The software provided with this Application Note has been tested with the following evaluation kits and SDK versions. The supplied makefiles are configured to compile for K32W061 chips on the K32W061DK6 SDK which was also used to create the pre-built binaries, there is information on the main Application Note document on how to compile for different chips/SDKs.

Product Type	Part Number	Version	Supported Chips
JN518x Development Kit	JN518x-DK006	-	JN5189 / JN5188
IoT_ZTB Development Kit	IoT_ZTB-DK006	-	K32W061 / K32W041
MPCXpresso –Toolchain		v11.1.1 build 3241	JN5189 / JN5188 K32W061 / K32W041
Development Kit – SDK	K32W061DK6	v2.6.0 RFP RC5	JN5189 / JN5188 K32W061 / K32W041

3.2 Public v2001: Memory Usage

The applications of this Application Note have the following memory footprints:

```
text data bss dec filename

165812 1548 17520 184880 LightSensor_OM15081R2

190280 1704 19872 211856 LightSensor_NtagIcode_Ota_OM15081R2

167268 1644 18064 186976 LTOSensor_OM15081R2

191552 1824 20416 213792 LTOSensor_NtagIcode_Ota_OM15081R2

168604 1556 17504 187664 OccupancySensor_OM15082

194008 1720 19856 215584 OccupancySensor_NtagIcode Ota_OM15082
```

3.3 Public v2001: End Device RAM Retention

```
retain spare kb banks filename

14952 1432 16 ----567 LightSensor_OM15081R2

17336 7240 24 ---4567 LightSensor_NtagIcode_Ota_OM15081R2

15592 792 16 ----567 LTOSensor_OM15081R2

17992 6584 24 ----4567 LTOSensor_NtagIcode_Ota_OM15081R2

14952 1432 16 ----567 OccupancySensor_OM15082

17336 7240 24 ----4567 OccupancySensor NtagIcode Ota OM15082
```

3.4 Public v2001: New Features

None.

3.5 Public v2001: Bug Fixes

artf734822: OTA end request error due to server power off during OTA process

When server power off then power on, device will restart the OTA, but the flash driver needs to reinit as well.

3.6 Public v2001: Known Issues

None.

4 Public v2000- 5-Mar-2020

Public release for DK006: JN5189 / JN5188 / K32W061 / K32W041.

4.1 Public v2000: Compatibility

The software provided with this Application Note has been tested with the following evaluation kits and SDK versions. The supplied makefiles are configured to compile for JN5189 chips on the JN5189DK6 SDK which was also used to create the pre-built binaries, there is information on the main Application Note document on how to compile for different chips/SDKs.

Product Type	Part Number	Version	Supported Chips
JN518x Development Kit	JN518x-DK006	-	JN5189 / JN5188
IoT_ZTB Development Kit	IoT_ZTB-DK006	-	K32W061 / K32W041
MPCXpresso –Toolchain		v11.1.0 build 3209	JN5189 / JN5188 K32W061 / K32W041
Development Kit – SDK	JN5189DK6	v2.6.0 build 110	JN5189 / JN5188 K32W061 / K32W041

4.2 Public v2000: Memory Usage

The applications of this Application Note have the following memory footprints:

```
text data bss dec filename
165780 1548 17328 184656 LightSensor_OM15081R2
190120 1704 19696 211520 LightSensor_NtagIcode_Ota_OM15081R2
167236 1644 17888 186768 LTOSensor_OM15081R2
191388 1812 20240 213440 LTOSensor_NtagIcode_Ota_OM15081R2
168572 1556 17328 187456 OccupancySensor_OM15082
193848 1720 19680 215248 OccupancySensor_NtagIcode Ota_OM15082
```

4.3 Public v2000: End Device RAM Retention

```
retain spare kb banks filename

14760 1624 16 ----567 LightSensor_OM15081R2

17160 7416 24 ---4567 LightSensor_NtagIcode_Ota_OM15081R2

15416 968 16 ----567 LTOSensor_OM15081R2

17816 6760 24 ----4567 LTOSensor_NtagIcode_Ota_OM15081R2

14776 1608 16 ----567 OccupancySensor_OM15082

17160 7416 24 ----4567 OccupancySensor_NtagIcode Ota_OM15082
```

4.4 Public v2000: New Features

None – first release.

4.5 Public v2000: Bug Fixes

None - first release.

4.6 Public v2000: Known Issues

None – first release.

Important Notice

How To Reach Us

Home Page:

nxp.com

Web Support:

nxp.com/support

Information in this document is provided solely to enable system and software implementers to use NXP products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits based on the information in this document. NXP reserves the right to make changes without further notice to any products herein.

NXP makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does NXP assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in NXP data sheets and/or specifications can and do vary in different applications, and actual performance may vary over time. All operating parameters, including "typicals," must be validated for each customer application by customer's technical experts. NXP does not convey any license under its patent rights nor the rights of others. NXP sells products pursuant to standard terms and conditions of sale, which can be found at the following address: nxp.com/SalesTermsandConditions.

While NXP has implemented advanced security features, all products may be subject to unidentified vulnerabilities. Customers are responsible for the design and operation of their applications and products to reduce the effect of these vulnerabilities on customer's applications and products, and NXP accepts no liability for any vulnerability that is discovered. Customers should implement appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP, the NXP logo, NXP SECURE CONNECTIONS FOR A SMARTER WORLD, COOLFLUX, EMBRACE, GREENCHIP, HITAG, ICODE, JCOP, LIFE VIBES, MIFARE, MIFARE CLASSIC, MIFARE DESFire, MIFARE PLUS, MIFARE FLEX, MANTIS, MIFARE ULTRALIGHT, MIFARE4MOBILE, MIGLO, NTAG, ROADLINK, SMARTLX, SMARTMX, STARPLUG, TOPFET, TRENCHMOS, UCODE, Freescale, the Freescale logo, AltiVec, CodeWarrior, ColdFire+, the Energy Efficient Solutions logo, Kinetis, Layerscape, MagniV, mobileGT, PEG, PowerQUICC, Processor Expert, QorlQ, QorlQ Qonverge, SafeAssure, the SafeAssure logo, StarCore, Symphony, VortiQa, Vybrid, Airfast, BeeKit, BeeStack, CoreNet, Flexis, MXC, Platform in a Package, QUICC Engine, Tower, TurboLink, EdgeScale, EdgeLock, elQ, and Immersive3D are trademarks of NXP B.V.

All other product or service names are the property of their respective owners. AMBA, Arm, Arm7, Arm7TDMI, Arm9, Arm11, Artisan, big.LITTLE, Cordio, CoreLink, CoreSight, Cortex, DesignStart, DynamIQ, Jazelle, Keil, Mali, Mbed, Mbed Enabled, NEON, POP, RealView, SecurCore, Socrates, Thumb, TrustZone, ULINK, ULINK2, ULINK-ME, ULINK-PLUS, ULINKpro, µVision, Versatile are trademarks or registered trademarks of Arm Limited (or its subsidiaries) in the US and/or elsewhere. The related technology may be protected by any or all of patents, copyrights, designs and trade secrets. All rights reserved. Oracle and Java are registered trademarks of Oracle and/or its affiliates. The Power Architecture and Power.org word marks and the Power and Power.org logos and related marks are trademarks and service marks licensed by Power.org.

© NXP B.V. 2020. All rights reserved.

For more information, please visit: http://www.nxp.com

For sales office addresses, please send an email to: salesaddresses@nxp.com

Date of release: 23-Dec-2020 Document identifier: JN-AN-1246

