

PRIMARY \*\* VGA1 DAC A \*\* I2C1 SECONDARY \*\* VGA2 DAC\_B \*\* I2CO. WIDCAR \*\* WIR 7114 TOCS 9pin DIN \*\* RGB2 I2C2. See PDS for Hookur

P73-A00-X01

Created SCH from P78-X16 for I/O Netlist only

CREATED NX16 MEMORY, DECOUPLING FROM P78

D73-300-V03

ADDED MEM & CORE FROM P70 PS FOR ISL6529 SAA7114 DECAPS ADDED AND CHANGED TO 0402

P73-A00-X04

PCB Footprint for RAM added

P73-A00-X05

C620, C621 Removed Extra Mem Decaps removed

P73-A00-X06

PCB Footprint for Inductor, Stacked DB15, ISL6529 added PCB Footprint for L305, L307, L308, L316-L324 changed to 0603 from 0805. Added X-Comp R750, R751.

D72-300-V07

P73-A00-X08

U700-Parallel ROM and C700 decap Removed for space P73-A00-X09

0603 to 0402 Package Changes for 49 components

P73-A00-X10

Design Review Updates

0603 to 0402 Package Changes for 33 components

0805 to 0603 Package Changes for 17 components

0402 to 0603 Package Changes for 10 components

Removed 25 components

P73-A00-X11

Swaps in Memory termination RN201, RN203, RN205, RN207

P73-A00-X12

C606, C615 TH replacements. Removed for want of space.

P73-A00-X13

Memory bus swaps on 1/11/02-Swap 2

P73-A00-X14

Memory his swans on 1/12/02-Swan 3

P73-A00-X15

Memory bus byte swaps as per NV17-Ball

P73-A00-X16

Memory bus byte and bit swaps as per layout

TV Filter moved to VGA2 page with more routing notes

P73-A00-X17

The C397 C311 C318 changed to 0603 from 0402 for two trace routing near GPU break out.

P300-2 Mounting pins removed from CGND P73-A00-X18

Added X Components C824 to C830 to FBVDDO

## PAGE OVERVIEW

1 top (this) page

2 1. AGP interface, core decoupling

3 2.a NV17 Frame Buffer

4 3.a Dual DAC, 1st VGA

5 3.b Dual DAC, 2nd VGA

6. 3.c TMDS NV17

7 4.a Frame Buffer 0..31

8 4.b Frame Buffer 32...63

9 5. TV-out, video capture, stereo

10 6. Power supply

11 7. BIOS. Strapping

## P73, NV17, 4/8Mx16 DDR, 32/64MB, Dual RGB, TV-out, Video Capture, AGP4X

Stuff Option

COMMON

NO STUFF

PCI DEVICE ID = 0X172 FOR GF4-MX420-XX



P73-A00-X19

R610, R612 for FBVDDQ re-fixed to have <5K for Rfb

Added X Components C831 to C832 to FBVDDO

P73-A00-X20- X-Rel Candidate

Clean-up for Agile upload

Memory de-coupling values modified as per layout.

P73-A00-X21- ECO-3893

Q600 Should be FET istead of BJT Transistor.

P73-A00-X22-

Corrected NV17-S sku in the table in this page

The RED and GREEN signal to TV filter and COUT.

P73-A01-X02

Corrected by swapping CVBS YOUT and COUT at DIN

Type 3 Compensation Values for ISL6529 changed C616---NC---47nF

R614---NS---8.06K

R611---16.2K---6.65K

C619---33nF----1.8nF

AGPSTOP to 3.3V R616 -47R inseries to 12V for ISL6529 is too high, changed to 4.7F

P73-A01-X03-Final Netlist

R616 -4.7R inseries to 12V for ISL6529 is changed to OR

R624 - Added 2.2R inseries to 5V for ISL6529.

TST.6529 Compensation Res to be Type 2 with

Snubber coponents stuffed. Values under test

P73-A01-X04-For X-Rel

The Type 2 Compensation works better than Type 3 Compensation C616. R614 No Stuff, R614 Nostuff, C618 3300pf, R611 16.2K, C619 33pF R616 0R

R626 2 2R C617 2200PE

The Type 3 Compensation works better than Type 2 Compensation in the new layout with new values tried at Intersi

C616-47nF, R614-10R, C618 1000pf, R611-10K, C619 1500pF

MS-8878 BASE ON P73 MODIFY

Page 1. Add CE1 and RE1 for EMI solution. Add compability with M/B.

rename , C22 to C144,R4 to R111,R5 to R112,R6 to R113,U1 to U101 change NET name, U100.AH17 to BUF\_PCIRST\_ also at the R112 and C144.

Page 4. U300.9, U300.10, U300.1, U300.2 and U300.7 pin connect to GND.

Page 5. remove VGA2 function.

Page 9. Remove SAA7114H function and ADD AV-OUT & S OUT conector.

remove L500, C500, C505, C506, C538, C539, C507, C508

Page 10. C613,C604,C605,C614,L600 and L601 change to DIP type,ADD C620 , Q1 change to AOS4800

Page 11. R704~R719, R726~R733, R745, R746 PAD size change to 0603 type and Add R747 10k ohm. Add parallel bios function.

R746,R747 stuff ( 00 )

Page 6 . Add Fan power function.

MS-8878 VER:310 MODIFY

Page 2. Add 74XCT74 buffer for PCI\_RST function.

Page 5. Add 75ohm and bypass Cap. for TV-OUT function

Page 9. Swap S-OUT.3 and S-OUT.4 net name.

Page 10. Change DIP type CAP, footprint.

Page 11. Change U1000.22 net name.

Item\tQuantity\tReference\tValue\tAssembly\tMAIN\tNVPN\tSource Package\tAVL1\tAVL2\tAVL3\tAVL4\tAVL5

VIDCAP Video In or Video Capture VGA2 2nd VGA Components and Conenctor **DSUB** Standard single VGA Connector TV Second DAC channel goes to Svideo connector as TV Out TVO 4pin DIN for TV Only 1117 Fixed 1117 linear regulator for A3.3V 1117 ADJ Adjustable 1117 linear regulator for A3.3V NO 1117 Connect A3.3V to 3.3V. No 1117 regulator. CLAMP1 VGA1 Sync/I2C Clamping diodes **RGB PROT** RGB Protection diodes on primary DAC outputs CLAMP2 VGA2 Sync/I2C Clamping diodes **RGB2 PROT** RGB Protection diodes on secondary DAC outputs CLAMP3 VIDCAP I2C/Video In Clamping diodes **TVCLAMP** TV Red/Green Clamping diodes GPU GPU ONLY NV17-S **IDSTRAP OPTION-172H** MEMORY Memory only Memory PS output 2.8V M2-8V M2-5V Memory PS output 2.5V


Common to all assemblies and 1st VGA comps


Not present in any assembly

Meaning

140-10073-0000-A01 602-10073-0000-A01








3.c TMDS\_NV17
Micro-Star International Co., LTD. Micro-Star Internation


MS-8847 base on P73 modify


Size Document Number


TMDS\_NV17


(John Friday, September 20, 2002 | Street | 5 of














| Micro-Star International Co., LTD. | MS-8847 base on P73 modify | Document Number | Dual DAC, 2nd VGA | to Friday, September 20, 2002 | Sheet 11 of