# GTX650 Standard Operation Procedure Revision: 1.55

Doc. No:

Date: Mar. 26, 2013

Page: 10 Grade:

Rev.	Modified Chapters	Modification Description	Issued Dept.	Issued by	Revised Date
1.00		First Release	GRMA	Ariel_wang	Sep.10,2012
1.01		Add new P/N(YV0381-A01)	GRMA	Ariel_wang	Sep.10,2012
1.02		Add new P/N(YV03B0-A03)	GRMA	Ariel_wang	Sep.24,2012
1.03		Add new P/N(YV03B1-A03)	GRMA	Ariel_wang	Sep.24,2012
1.04		Add new P/N(YV03B2-A03)	GRMA	Ariel_wang	Sep.24,2012
1.05		Add new P/N(YV0382-A01)	GRMA	Ariel_wang	Sep.24,2012
1.06		Add new PCBA(YV0382-A11)	GRMA	Ariel_wang	Sep.24,2012
1.07		Add new P/N(YV0383-A01)	GRMA	Ariel_wang	Oct.22,2012
1.08		Add new P/N(YV03B3-A01)	GRMA	Ariel_wang	Oct.29,2012
1.09		Add new P/N(YV03K0-A02)	GRMA	Ariel_wang	Nov.21,2012
1.10		Add new P/N(YV03K1-A02)	GRMA	Ariel_wang	Nov.21,2012
1.11		Add new P/N(YV03I0-A03)	GRMA	Ariel_wang	Nov.26,2012
1.12		Add new PCBA(YV03B2-A15)	GRMA	Ariel_wang	Dec.5,2012
1.13		Add new P/N(YV03I1-A04)	GRMA	Ariel_wang	Dec.18,2012
1.14		Add new PCBA(YV0380-X03)	GRMA	Ariel_wang	Dec.24,2012
1.15		Add new PCBA(YV03K0-U04)	GRMA	Ariel_wang	Dec.26,2012
1.16		Add new PCBA(YV03K1-U04)	GRMA	Ariel_wang	Dec.26,2012
1.17		Add new PCBA(YV0381-A11)	GRMA	Ariel_wang	Jan.4,2013
1.18		Add new PCBA(YV03I0-U04)	GRMA	Ariel_wang	Jan.4,2013
1.19		Add new P/N(YV03R0-A02)	GRMA	Ariel_wang	Jan.15,2013
1.20		Add new P/N(YV03R1-A02)	GRMA	Ariel_wang	Jan.15,2013
1.21		Add new P/N(YV03Q0-A02)	GRMA	Ariel_wang	Jan.15,2013
1.22		Add new P/N(YV03Q1-A02)	GRMA	Ariel_wang	Jan.22,2013
1.23		Add new PCBA(YV03K0-A24)	GRMA	Ariel_wang	Jan.29,2013
1.24		Add new PCBA(YV03B2-U05)	GRMA	Ariel_wang	Feb.5,2013
1.25		Add new PCBA(YV03I0-A34)	GRMA	Ariel_wang	Feb.25,2013
1.26		Add new PCBA(YV03R1-A13)	GRMA	Ariel_wang	Mar.4,2013
1.27		Add new PCBA(YV03R0-A14)	GRMA	Ariel_wang	Mar.4,2013
1.28		Add new PCBA(YV03K1-A15)	GRMA	Ariel_wang	Mar.11,2013
1.29		Add new PCBA(YV03I1-A16)	GRMA	Ariel_wang	Mar.11,2013
1.30		Add new P/N(YV0430-A01)	GRMA	Ariel_wang	Mar.19,2013
1.31		Add new P/N(YV0431-A01)	GRMA	Ariel_wang	Mar.19,2013
1.32		Add new PCBA(YV03Q0-A13)	GRMA	Ariel_wang	Mar.29,2013
1.33		Add new PCBA(YV03Q3-A02)	GRMA	Jory_yuan	Apr.24,2013

Authorize by Review by Originator By Ariel
--

Form No: T2-009-01 Rev.01

# GTX650 Standard Operation Procedure

Doc. No:

Date: Dec. 26, 2013 Rev.: 1.55 Page: 1

1.34         Add new PCBA(YV03K1-U16)         GRMA         Jory_yuan         May.7.2013           1.35         Add new PCBA(YV03K0-U24)         GRMA         Jory_yuan         May.9.2013           1.36         Add new PCBA(YV0430-A11)         GRMA         Jory_yuan         May.14.2013           1.37         Add new PCBA(YV04D0-A01)         GRMA         Jory_yuan         May.14.2013           1.38         Add new P/N(YV04D0-A01)         GRMA         Jory_yuan         July.03.2013           1.40         Add new PCBA(YV03B2-A35)         GRMA         Jory_yuan         Sep.22.2013           1.41         Add new PCBA(YV0431-U12)         GRMA         Jory_yuan         Sep.22.2013           1.42         Ad new PCBA(YV03K1-A27)         GRMA         Jory_yuan         Nov.6.2013           1.43         Add new PCBA(YV03Q3-A12)         GRMA         Jory_yuan         Nov.6.2013           1.44         Add new PCBA(YV03G4-A11)         GRMA         Jory_yuan         Nov.13.2013           1.45         Add new PCBA(YV03K0-A35)         GRMA         Jory_yuan         Nov.20.2013           1.47         Add new PCBA(YV03K1-A39)         GRMA         Jory_yuan         Nov.27.2013           1.48         Add new P(N(YV03K2-A03)         GRMA         Jory_yuan </th <th></th> <th></th> <th></th> <th></th> <th></th>					
1.36         Add new PCBA(YV0430-A11)         GRMA         Jory_yuan         May.14.2013           1.37         Add new PCBA(YV0431-A11)         GRMA         Jory_yuan         May.14.2013           1.38         Add new P/N(YV04D0-A01)         GRMA         Jory_yuan         Jun.06.2013           1.39         Add new PCBA(YV03B2-A35)         GRMA         Jory_yuan         July.03.2013           1.40         Add new PCBA(YV04W0-A01)         GRMA         Jory_yuan         Sep.22.2013           1.41         Add new PCBA(YV0431-U12)         GRMA         Jory_yuan         Sep.22.2013           1.42         Ad new PCBA(YV03K1-A27)         GRMA         Jory_yuan         Sep.22.2013           1.43         Add new PCBA(YV03Q3-A12)         GRMA         Jory_yuan         Nov.6.2013           1.44         Add new PCBA(YV03Q4-A11)         GRMA         Jory_yuan         Nov.13.2013           1.45         Add new PCBA(YV03K0-A35)         GRMA         Jory_yuan         Nov.20.2013           1.46         Add new PCBA(YV03K1-A39)         GRMA         Jory_yuan         Nov.27.2013           1.48         Add new PCBA(YV03K2-A03)         GRMA         Jory_yuan         Nov.27.2013           1.49         Add new PCBA(YV03K3-A01)         GRMA         Jory_yu	1.34	Add new PCBA(YV03K1-U16)	GRMA	Jory_yuan	May.7.2013
1.37         Add new PCBA(YV0431-A11)         GRMA         Jory_yuan         May.14.2013           1.38         Add new P/N(YV04D0-A01)         GRMA         Jory_yuan         Jun.06.2013           1.39         Add new PCBA(YV03B2-A35)         GRMA         Jory_yuan         July.03.2013           1.40         Add new PCBA(YV04W0-A01)         GRMA         Jory_yuan         Sep.22.2013           1.41         Add new PCBA(YV03K1-U12)         GRMA         Jory_yuan         Sep.22.2013           1.42         Ad new PCBA(YV03K1-A27)         GRMA         Jory_yuan         Nov.6.2013           1.43         Add new PCBA(YV03Q3-A12)         GRMA         Jory_yuan         Nov.6.2013           1.44         Add new PCBA(YV03Q4-A11)         GRMA         Jory_yuan         Nov.13.2013           1.45         Add new PCBA(YV03K0-A35)         GRMA         Jory_yuan         Nov.20.2013           1.46         Add new PCBA(YV03K1-A39)         GRMA         Jory_yuan         Nov.27.2013           1.48         Add new PCBA(YV03K2-A03)         GRMA         Jory_yuan         Nov.27.2013           1.49         Add new PCBA(YV03K3-A01)         GRMA         Jory_yuan         Dec.11.2013           1.50         Add new PCBA(YV03K1-A49)         GRMA         Jory_yua	1.35	Add new PCBA(YV03K0-U24)	GRMA	Jory_yuan	May.9.2013
1.38         Add new P/N(YV04D0-A01)         GRMA         Jory_yuan         Jun.06.2013           1.39         Add new PCBA(YV03B2-A35)         GRMA         Jory_yuan         July.03.2013           1.40         Add new P/N(YV04W0-A01)         GRMA         Jory_yuan         Sep.22.2013           1.41         Add new PCBA(YV0431-U12)         GRMA         Jory_yuan         Sep.22.2013           1.42         Ad new PCBA(YV03K1-A27)         GRMA         Jory_yuan         Sep.22.2013           1.43         Add new PCBA(YV03Q3-A12)         GRMA         Jory_yuan         Nov.6.2013           1.44         Add new PCBA(YV03Q4-A11)         GRMA         Jory_yuan         Nov.13.2013           1.45         Add new PCBA(YV03K0-A35)         GRMA         Jory_yuan         Nov.20.2013           1.46         Add new PCBA(YV03K1-A39)         GRMA         Jory_yuan         Nov.27.2013           1.47         Add new PCBA(YV03K2-A03)         GRMA         Jory_yuan         Nov.27.2013           1.48         Add new P/N(YV03K3-A01)         GRMA         Jory_yuan         Dec.11.2013           1.50         Add new PCBA(YV03K1-A49)         GRMA         Jory_yuan         Dec.11.2013           1.51         Add new PCBA(YV04W0-A12)         GRMA         Jory_yuan	1.36	Add new PCBA(YV0430-A11)	GRMA	Jory_yuan	May.14.2013
1.39         Add new PCBA(YV03B2-A35)         GRMA         Jory_yuan         July.03.2013           1.40         Add new P/N(YV04W0-A01)         GRMA         Jory_yuan         Sep.22.2013           1.41         Add new PCBA(YV0431-U12)         GRMA         Jory_yuan         Sep.22.2013           1.42         Ad new PCBA(YV03K1-A27)         GRMA         Jory_yuan         Sep.22.2013           1.43         Add new PCBA(YV03Q3-A12)         GRMA         Jory_yuan         Nov.6.2013           1.44         Add new PCBA(YV03Q4-A11)         GRMA         Jory_yuan         Nov.13.2013           1.45         Add new PCBA(YV03K0-A35)         GRMA         Jory_yuan         Nov.20.2013           1.46         Add new PCBA(YV03K1-A39)         GRMA         Jory_yuan         Nov.27.2013           1.47         Add new PCBA(YV03K2-A03)         GRMA         Jory_yuan         Nov.27.2013           1.48         Add new P/N(YV03K3-A01)         GRMA         Jory_yuan         Dec.11.2013           1.50         Add new PCBA(YV03K1-A49)         GRMA         Jory_yuan         Dec.11.2013           1.51         Add new PCBA(YV04W0-A12)         GRMA         Jory_yuan         Dec.18.2013           1.52         Add new PCBA(YV03B2-A45)         GRMA         Jory_yua	1.37	Add new PCBA(YV0431-A11)	GRMA	Jory_yuan	May.14.2013
1.40         Add new P/N(YV04W0-A01)         GRMA         Jory_yuan         Sep.22.2013           1.41         Add new PCBA(YV0431-U12)         GRMA         Jory_yuan         Sep.22.2013           1.42         Ad new PCBA(YV03K1-A27)         GRMA         Jory_yuan         Sep.22.2013           1.43         Add new PCBA(YV03Q3-A12)         GRMA         Jory_yuan         Nov.6.2013           1.44         Add new PCBA(YV03Q4-A11)         GRMA         Jory_yuan         Nov.13.2013           1.45         Add new PCBA(YV03K0-A35)         GRMA         Jory_yuan         Nov.13.2013           1.46         Add new PCBA(YV03K1-A39)         GRMA         Jory_yuan         Nov.27.2013           1.47         Add new PCBA(YV03Q4-A02)         GRMA         Jory_yuan         Nov.27.2013           1.48         Add new P/N(YV03K2-A03)         GRMA         Jory_yuan         Dec.11.2013           1.50         Add new PCBA(YV03K1-A49)         GRMA         Jory_yuan         Dec.11.2013           1.51         Add new PCBA(YV03B2-A45)         GRMA         Jory_yuan         Dec.18.2013           1.52         Add new PCBA(YV0380-A18)         GRMA         Jory_yuan         Dec.25.2013           1.54         Add new PCBA(YV03K1-B02)         GRMA         Jory_yuan	1.38	Add new P/N(YV04D0-A01)	GRMA	Jory_yuan	Jun.06.2013
1.41         Add new PCBA(YV0431-U12)         GRMA         Jory_yuan         Sep.22.2013           1.42         Ad new PCBA(YV03K1-A27)         GRMA         Jory_yuan         Sep.22.2013           1.43         Add new PCBA(YV03Q3-A12)         GRMA         Jory_yuan         Nov.6.2013           1.44         Add new PCBA(YV03Q4-A11)         GRMA         Jory_yuan         Nov.13.2013           1.45         Add new PCBA(YV03K0-A35)         GRMA         Jory_yuan         Nov.20.2013           1.46         Add new PCBA(YV03K1-A39)         GRMA         Jory_yuan         Nov.27.2013           1.47         Add new PCBA(YV03K2-A03)         GRMA         Jory_yuan         Nov.27.2013           1.48         Add new P/N(YV03K2-A03)         GRMA         Jory_yuan         Dec.11.2013           1.50         Add new PCBA(YV03K1-A49)         GRMA         Jory_yuan         Dec.11.2013           1.51         Add new PCBA(YV04W0-A12)         GRMA         Jory_yuan         Dec.18.2013           1.52         Add new PCBA(YV03B2-A45)         GRMA         Jory_yuan         Dec.25.2013           1.53         Add new PCBA(YV03K1-B02)         GRMA         Jory_yuan         Mar.19.2014	1.39	Add new PCBA(YV03B2-A35)	GRMA	Jory_yuan	July.03.2013
1.42         Ad new PCBA(YV03K1-A27)         GRMA         Jory_yuan         Sep.22.2013           1.43         Add new PCBA(YV03Q3-A12)         GRMA         Jory_yuan         Nov.6.2013           1.44         Add new PCBA(YV03Q4-A11)         GRMA         Jory_yuan         Nov.13.2013           1.45         Add new PCBA(YV03K0-A35)         GRMA         Jory_yuan         Nov.13.2013           1.46         Add new PCBA(YV03K1-A39)         GRMA         Jory_yuan         Nov.20.2013           1.47         Add new PCBA(YV03Q4-A02)         GRMA         Jory_yuan         Nov.27.2013           1.48         Add new P/N(YV03K2-A03)         GRMA         Jory_yuan         Nov.27.2013           1.49         Add new P/N(YV03K3-A01)         GRMA         Jory_yuan         Dec.11.2013           1.50         Add new PCBA(YV03K1-A49)         GRMA         Jory_yuan         Dec.11.2013           1.51         Add new PCBA(YV03B2-A45)         GRMA         Jory_yuan         Dec.18.2013           1.52         Add new PCBA(YV03B0-A18)         GRMA         Jory_yuan         Dec.25.2013           1.54         Add new PCBA(YV03K1-B02)         GRMA         Jory_yuan         Mar.19.2014	1.40	Add new P/N(YV04W0-A01)	GRMA	Jory_yuan	Sep.22.2013
1.43         Add new PCBA(YV03Q3-A12)         GRMA         Jory_yuan         Nov.6.2013           1.44         Add new PCBA(YV03Q4-A11)         GRMA         Jory_yuan         Nov.13.2013           1.45         Add new PCBA(YV03K0-A35)         GRMA         Jory_yuan         Nov.13.2013           1.46         Add new PCBA(YV03K1-A39)         GRMA         Jory_yuan         Nov.20.2013           1.47         Add new PCBA(YV03Q4-A02)         GRMA         Jory_yuan         Nov.27.2013           1.48         Add new P/N(YV03K2-A03)         GRMA         Jory_yuan         Nov.27.2013           1.49         Add new P/N(YV03K3-A01)         GRMA         Jory_yuan         Dec.11.2013           1.50         Add new PCBA(YV03K1-A49)         GRMA         Jory_yuan         Dec.11.2013           1.51         Add new PCBA(YV04W0-A12)         GRMA         Jory_yuan         Dec.18.2013           1.52         Add new PCBA(YV03B2-A45)         GRMA         Jory_yuan         Dec.18.2013           1.53         Add new PCBA(YV0380-A18)         GRMA         Jory_yuan         Dec.25.2013           1.54         Add new PCBA(YV03K1-B02)         GRMA         Jory_yuan         Mar.19.2014	1.41	Add new PCBA(YV0431-U12)	GRMA	Jory_yuan	Sep.22.2013
1.44         Add new PCBA(YV03Q4-A11)         GRMA         Jory_yuan         Nov.13.2013           1.45         Add new PCBA(YV03K0-A35)         GRMA         Jory_yuan         Nov.13.2013           1.46         Add new PCBA(YV03K1-A39)         GRMA         Jory_yuan         Nov.20.2013           1.47         Add new PCBA(YV03Q4-A02)         GRMA         Jory_yuan         Nov.27.2013           1.48         Add new P/N(YV03K2-A03)         GRMA         Jory_yuan         Nov.27.2013           1.49         Add new P/N(YV03K3-A01)         GRMA         Jory_yuan         Dec.11.2013           1.50         Add new PCBA(YV03K1-A49)         GRMA         Jory_yuan         Dec.11.2013           1.51         Add new PCBA(YV03B2-A45)         GRMA         Jory_yuan         Dec.18.2013           1.52         Add new PCBA(YV03B0-A18)         GRMA         Jory_yuan         Dec.25.2013           1.53         Add new PCBA(YV03K1-B02)         GRMA         Jory_yuan         Mar.19.2014	1.42	Ad new PCBA(YV03K1-A27)	GRMA	Jory_yuan	Sep.22.2013
1.45         Add new PCBA(YV03K0-A35)         GRMA         Jory_yuan         Nov.13.2013           1.46         Add new PCBA(YV03K1-A39)         GRMA         Jory_yuan         Nov.20.2013           1.47         Add new PCBA(YV03Q4-A02)         GRMA         Jory_yuan         Nov.27.2013           1.48         Add new P/N(YV03K2-A03)         GRMA         Jory_yuan         Nov.27.2013           1.49         Add new P/N(YV03K3-A01)         GRMA         Jory_yuan         Dec.11.2013           1.50         Add new PCBA(YV03K1-A49)         GRMA         Jory_yuan         Dec.11.2013           1.51         Add new PCBA(YV04W0-A12)         GRMA         Jory_yuan         Dec.18.2013           1.52         Add new PCBA(YV03B2-A45)         GRMA         Jory_yuan         Dec.18.2013           1.53         Add new PCBA(YV0380-A18)         GRMA         Jory_yuan         Dec.25.2013           1.54         Add new PCBA(YV03K1-B02)         GRMA         Jory_yuan         Mar.19.2014	1.43	Add new PCBA(YV03Q3-A12)	GRMA	Jory_yuan	Nov.6.2013
1.46         Add new PCBA(YV03K1-A39)         GRMA         Jory_yuan         Nov.20.2013           1.47         Add new PCBA(YV03Q4-A02)         GRMA         Jory_yuan         Nov.27.2013           1.48         Add new P/N(YV03K2-A03)         GRMA         Jory_yuan         Nov.27.2013           1.49         Add new P/N(YV03K3-A01)         GRMA         Jory_yuan         Dec.11.2013           1.50         Add new PCBA(YV03K1-A49)         GRMA         Jory_yuan         Dec.11.2013           1.51         Add new PCBA(YV04W0-A12)         GRMA         Jory_yuan         Dec.18.2013           1.52         Add new PCBA(YV03B2-A45)         GRMA         Jory_yuan         Dec.18.2013           1.53         Add new PCBA(YV0380-A18)         GRMA         Jory_yuan         Dec.25.2013           1.54         Add new PCBA(YV03K1-B02)         GRMA         Jory_yuan         Mar.19.2014	1.44	Add new PCBA(YV03Q4-A11)	GRMA	Jory_yuan	Nov.13.2013
1.47         Add new PCBA(YV03Q4-A02)         GRMA         Jory_yuan         Nov.27.2013           1.48         Add new P/N(YV03K2-A03)         GRMA         Jory_yuan         Nov.27.2013           1.49         Add new P/N(YV03K3-A01)         GRMA         Jory_yuan         Dec.11.2013           1.50         Add new PCBA(YV03K1-A49)         GRMA         Jory_yuan         Dec.11.2013           1.51         Add new PCBA(YV04W0-A12)         GRMA         Jory_yuan         Dec.18.2013           1.52         Add new PCBA(YV03B2-A45)         GRMA         Jory_yuan         Dec.18.2013           1.53         Add new PCBA(YV0380-A18)         GRMA         Jory_yuan         Dec.25.2013           1.54         Add new PCBA(YV03K1-B02)         GRMA         Jory_yuan         Mar.19.2014	1.45	Add new PCBA(YV03K0-A35)	GRMA	Jory_yuan	Nov.13.2013
1.48         Add new P/N(YV03K2-A03)         GRMA         Jory_yuan         Nov.27.2013           1.49         Add new P/N(YV03K3-A01)         GRMA         Jory_yuan         Dec.11.2013           1.50         Add new PCBA(YV03K1-A49)         GRMA         Jory_yuan         Dec.11.2013           1.51         Add new PCBA(YV04W0-A12)         GRMA         Jory_yuan         Dec.18.2013           1.52         Add new PCBA(YV03B2-A45)         GRMA         Jory_yuan         Dec.18.2013           1.53         Add new PCBA(YV0380-A18)         GRMA         Jory_yuan         Dec.25.2013           1.54         Add new PCBA(YV03K1-B02)         GRMA         Jory_yuan         Mar.19.2014	1.46	Add new PCBA(YV03K1-A39)	GRMA	Jory_yuan	Nov.20.2013
1.49         Add new P/N(YV03K3-A01)         GRMA         Jory_yuan         Dec.11.2013           1.50         Add new PCBA(YV03K1-A49)         GRMA         Jory_yuan         Dec.11.2013           1.51         Add new PCBA(YV04W0-A12)         GRMA         Jory_yuan         Dec.18.2013           1.52         Add new PCBA(YV03B2-A45)         GRMA         Jory_yuan         Dec.18.2013           1.53         Add new PCBA(YV0380-A18)         GRMA         Jory_yuan         Dec.25.2013           1.54         Add new PCBA(YV03K1-B02)         GRMA         Jory_yuan         Mar.19.2014	1.47	Add new PCBA(YV03Q4-A02)	GRMA	Jory_yuan	Nov.27.2013
1.50         Add new PCBA(YV03K1-A49)         GRMA         Jory_yuan         Dec.11.2013           1.51         Add new PCBA(YV04W0-A12)         GRMA         Jory_yuan         Dec.18.2013           1.52         Add new PCBA(YV03B2-A45)         GRMA         Jory_yuan         Dec.18.2013           1.53         Add new PCBA(YV0380-A18)         GRMA         Jory_yuan         Dec.25.2013           1.54         Add new PCBA(YV03K1-B02)         GRMA         Jory_yuan         Mar.19.2014	1.48	Add new P/N(YV03K2-A03)	GRMA	Jory_yuan	Nov.27.2013
1.51         Add new PCBA(YV04W0-A12)         GRMA         Jory_yuan         Dec.18.2013           1.52         Add new PCBA(YV03B2-A45)         GRMA         Jory_yuan         Dec.18.2013           1.53         Add new PCBA(YV0380-A18)         GRMA         Jory_yuan         Dec.25.2013           1.54         Add new PCBA(YV03K1-B02)         GRMA         Jory_yuan         Mar.19.2014	1.49	Add new P/N(YV03K3-A01)	GRMA	Jory_yuan	Dec.11.2013
1.52         Add new PCBA(YV03B2-A45)         GRMA         Jory_yuan         Dec.18.2013           1.53         Add new PCBA(YV0380-A18)         GRMA         Jory_yuan         Dec.25.2013           1.54         Add new PCBA(YV03K1-B02)         GRMA         Jory_yuan         Mar.19.2014		Add new PCBA(YV03K1-A49)	GRMA	Jory_yuan	Dec.11.2013
1.53         Add new PCBA(YV0380-A18)         GRMA         Jory_yuan         Dec.25.2013           1.54         Add new PCBA(YV03K1-B02)         GRMA         Jory_yuan         Mar.19.2014	1.51	Add new PCBA(YV04W0-A12)	GRMA	Jory_yuan	Dec.18.2013
1.54 Add new PCBA(YV03K1-B02) GRMA Jory_yuan Mar.19.2014	1.52	,	GRMA	Jory_yuan	Dec.18.2013
`	1.53	Add new PCBA(YV0380-A18)	GRMA	Jory_yuan	Dec.25.2013
1.55 Add new P/N(YV04D1-A01) GRMA Jory_yuan Mar.26.2014	1.54	Add new PCBA(YV03K1-B02)	GRMA	Jory_yuan	Mar.19.2014
	1.55	Add new P/N(YV04D1-A01)	GRMA	Jory_yuan	Mar.26.2014

GTX650 Standard Operation Procedure Doc. No:

Date: Dec. 26, 2013 Rev.: 1.55 Page: 2

## 1.Objectives

Create test procedure.

2.Scope

Model: GTX650

## 3.Test Item

- 3.1 Diagnostic test in Tiny Linux
- 3.2 3DMark06(contain HDMI test)
- 3.3 Temperature test

## **4.**Relevant Document

None.

**5.Definition**: 1. If the model name contains P, please test HDCP function.

Ex: EAH\*\*\*/HTDP/512M/A

- 2. If you test HDMI already, it's unnecessary to test HDCP. The HDMI contains HDCP function.
- 3. System Memory: 1GB for a single GPU test station; please add an additional 512MB of system memory for each additional GPU used for the test configuration
- 4. GTX650 Test Program in 64-bit Tiny Linux system.

## **6. Operation Procedures:**

#### 6.1 Attention

- 6.1.1 To avoid damaging devices or M/B, please turn off A/C power then unplug VGA card.
- 6.1.2 While unplugging the card, do it in upright direction to avoid damaging slot & golden finger.
- 6.1.3 If any problem happens, please inform test supervisor. Base on ATX power specification, +5V standby voltage is existed while AC power is connecting. For safety reason, please turn off main power during break time or idling test.
- 6.1.4 Some test items should be tested under Windows 7 environment. (Please install windows test environment by yourself).

GTX650

Standard Operation Procedure

Doc. No:

Date: Dec. 26, 2013 Rev.: 1.55 Page: 3

#### **6.2** Fixture connect

- 6.2.1 Install Intel P7 CPU & CPU Fan.
- 6.2.2 Install DDR3 Memory to DIMM1~4. (a minimum memory of 2GB for Linux test)
- 6.2.3 Plug USB Mouse and PS/2 Keyboard into MB.
- 6.2.4 Plug VGA Card GTX650 into PCIEX16\_1.
- 6.2.5 If this card has 6 PIN or 8 PIN of Power supply, please connect power con of VGA card & Power supply via bundled power cable.

(6 PIN of Power supply to 6 PIN of VGA card)

(8 PIN of Power supply to 8 PIN of VGA card)

6.2.6 Connect SATA HDD & SATA con via SATA cable



- 6.2.7 Plug 4PIN 12V power(a minimum power of 1200W) cable into CON12V.
- 6.2.8 Plug ATX Power on Power(a minimum power of 1200W) Connector.




GTX650 Standard Operation Procedure Doc. No:

Date: Dec. 26, 2013 Rev.: 1.55 Page: 4

### 6.3 Certain test.

## 6.3.1 Diagnostic test in 64-bit LINUX system

6.3.1.1 Please connect LCD monitor & card's DVI CON via a **DVI-I** (M)-**DVI(F)+VGA(F)** cable.



- 6.3.1.2 Press Power Switch then turn on power button.
- 6.3.1.3 Press "Del" to enter CMOS setup menu while boot screen is displaying.

EXIT -> Load Setup Defaults. Power Main Advanced Exit Options Exit system setup Exit & Save Changes Exit & Discard Changes after saving the changes. Discard Changes F10 key can be used for this operation. Load Setup Defaults Select Screen Select Item Enter Go to Sub-screen F1 General Help F10 Save and Exit (C)Copyright 1985-2002, American Megatrends,

6.3.1.4 Run test program in 64-bit Tiny linux system.

Please download TinyLinux11.12.rar from sip and copy the all file and folder of TinyLinux11.12 to DOS system root directory, then run dos2lin.bat goto Tinylinux system, Path:c:/dos2lin/dos2lin.bat

Path:gtx650\yv0380a0.sh or yv0383a0.sh or yv0380x0.sh or yv0380a1.sh

 $Path: gtx6501 \setminus yv0381a0. sh \ or \ yv0381a1. sh$ 

Path:gtx6502\yv03b0a0.sh

Path:gtx6503\yv03b1a0.sh or yv03b2a1.sh

 $Path:gtx6504 \setminus yv03b2a0.sh \quad or \quad yv03b3a0.sh \quad or \quad yv03b2u0.sh \quad or \quad yv03b2a3.sh \quad or \quad yv03b2a4.sh$ 

Path:gtx6505\yv0382a0.sh or yv0382a1.sh

Path:gtx6506\yv03k0a0.sh or yv03k1a0.sh or yv03k0u0.sh or yv03k1u0.sh or yv03k0a2.sh or yv03k1a1.sh or yv03k1u1.sh or yv03k0u2.sh or yv04d0a0.sh or yv03k0a3.sh or yv03k1a3.sh or yv03k1a4.sh

Path:gtx6507\yv03i0a0.sh or yv03i1a0.sh or yv03i0u0.sh or yv03i0a3.sh or yv03i1a1.sh or yv04w0a0.sh or yv04w0a1.sh

Path:gtx6508\yv03r0a0.sh or yv03r1a0.sh or yv03r0a1.sh or yv03r1a1.sh Path:gtx6509\yv03q0a0.sh or yv03q1a0.sh or yv03q0a1.sh or yv03q3a0.sh

## GTX650 Standard Operation Procedure

Doc. No:

Date: Dec. 26, 2013 Rev.: 1.55 Page: 5

Path:gtx650a\yv0430a0.sh or yv0430a1.sh

Path:gtx650b\yv0431a0.sh or yv0431a1.sh or yv0431u1.sh

Path:gtx650c\yv03k1a2.sh or yv03k1b0.sh

Path:gtx650d\yv03q3a1.sh or yv03q4a1.sh or yv03q4a0.sh

Path:gtx650e\yv03k2a0.sh Path:gtx650f\yv03k3a0.sh Path:gtx650g\yv04d1a0.sh

Please enter into the file of gtx650 enter the following command: cd ./gtx650

Then, please run ./yv0380a0.sh or ./yv0381a0.sh ./yv03b0a0.sh ./yv03b1a0.sh

./yv03b2a0.sh ./yv0382a0.sh ./yv0382a1.sh ./yv0383a0.sh ./yv03b3a0.sh ./yv03k0a0.sh ./yv03k1a0.sh yv03k1u1.sh ./yv03i0a0.sh ./yv03b2a1.sh or or ./yv0380x0.sh or ./yv0381a1.sh or ./yv03i0u0.sh or ./yv03r0a0.sh or ./yv03r1a0.sh or ./yv03q0a0.sh or ./yv03q1a0.sh or ./yv03k0a2.sh or ./yv03b2u0.sh or ./yv03i0a3.sh or ./yv03r0a1.sh or ./yv03r1a1.sh or ./yv03k1a1.sh or ./yv03i1a1.sh ./yv0430a0.sh o./yv0431a0.sh or./yv0430a1.sh or./yv0431a1.sh or./yv04d0a0.sh ./yv03q0a1.sh or ./yv03q3a0.sh or ./yv03k0u2.sh

### 6.3.5 Memory test

If you want to test memory, please run ./mats -e xx

Where,-c xx----- only xx% of frame buffer is detected.

#### 6.3.6 BIOS flash

Please use the following command to flash bios and notice the size of character.

Command: ./nvflash xxx.rom -4 -5 -6 -A -y

./biosinfo or ./nvflash –v (you can find BIOS Version)

#### Notice:


If you can not flash bios because of the bios locked, please use ./nvflash.exe -r to unlock bios. And then, please use ./nvflash.exe -w to lock bios after updating latest bios.

6.3.7 After finish linux testing, please enter Windows 7 environment to test 3DMark.

### 6.3.2 3DMark test(contain HDMI test)

- 6.3.2.1 Please install 3DMark program by yourself.
- 6.3.2.2 Please connect VGA card to LCD via HDMI cable or Display Port cable.






# GTX650 Standard Operation Procedure

Doc. No:


Date: Dec. 26, 2013 Rev.: 1.55 Page: 6

#### **HDMI** Port

- 6.3.2.3 Please install VGA card driver in Windows(You must use latest individual driver of this card).
- 6.3.2.4 Please run 3DMark06 base on this card (please test 1 cycle).
- 6.3.2.5 Press "Select" to enter Select test menu. You can choose "HDR1" for default setting.



6.3.2.6 Press "Demo" to enter Demo menu. You can choose "Sounds" for default setting.



- 6.3.2.7 Please pay attention to check if there is flickering, discolor, crash and so on. If there's no problem, it can be judged OK!
- 6.3.2.8 Please listen to voice carefully to check whether it outputs sounds. If not, HDMI test fail.

GTX650 Standard Operation Procedure Doc. No:

Date: Dec. 26, 2013 Rev.: 1.55 Page: 7



6. 3.2.9 If test OK, please test temperature test.

GTX650 Standard Operation Procedure Doc. No:


Date: Dec. 26, 2013 Rev.: 1.55 Page: 8

## **6.4** Temperature test


- 6.4.1 Please copy Thermaltool(1.0.05) to Windows by yourself.
- 6.4.2 Please run ThermalTest.exe.



6.4.3 If test ok, show pass.



6.4.4 If test fail, show fail.



- 6.4.5 If test OK, please NTF test.
- 6.4.6 3D Temperature limit data.

YV0380-A0\*&X0\*/YV0383-A0\* is 70 degrees.

YV0381-A0\*&A1\* is 79 degrees

YV0382-A0\*/A1\* /YV03B3-A0\* is 76 degrees

YV03Q0-A0\* /YV03Q1-A0\* is 65 degrees

GTX650 Standard Operation Procedure Doc. No:

Date: Dec. 26, 2013 Rev.: 1.55 Page: 9

# 7.Appendix

NO "		10110 5	0 "	0	<b>.</b>
NO#	Equipment Description	ASUS Part#	Supplier	Quantity	Remarks
1	Dell 30 inches (3008WFP) (Buying a local LCD by yourself)			1	Political Politi
2	USB MOUSE			1	
3	PS/2 KEYBOARD			1	
4	ATX POWER SUPPLY(a minimum power of 500W)			1	
5	Intel CPU Intel(R) Core(TM)2 CPU		local	1	E11200
6	Heat sink + FAN	22-240000160		1	
7	DDR3 1333 2G	20-TT2605618	local	4	
8	TEST HDD			1	
9	SATA HDD Cable	14-000107070	ASUS	1	
10	PCIEX16 VGA CARD			1	
11	Dual link DVI cable (Buying a local DVI cable by yourself)			1	O
12	HDMI extend cable (Buying a local HDMI cable by yourself)			1	
13	P7H55-M/USB3 MB	80- MIBBKA-*		1	
14	Display port cable (Buying a local Display port cable by yourself)			1	
15	D-SUB extend cable (Buying a local D-SUB cable by yourself)			1	