PCI-EXPRESS EDGE CONNECTOR

+12<u>V_BUS</u>

MC1 _____C1 470uF ____10UF


+12V_BUS

+3.3V

C5 C6 1uF_6.3V 1uF_6.3V

CAP CER 10UF 20% 16V X5R (1206)1.8MM H MAX


CAP CER 10UF 10% 6.3V X5R (0805)1.4MM MAX THICK







ACTIVE LOW


 \uparrow ANALOG GROUND














DIVIDER RESISTORS	DDR2	GDDR3
MVREF TO 1.8V	100R	40.2R
MVREF TO GND	100R	100R
































The 7-pin MiniDIN footprint allows one of the two MiniDINs:
- 7-pin Svideo/Composite MiniDIN P/N 6071001500G
- 4-pin Svideo MiniDIN P/N 6070001000G









Title

Schematic No.

RH RV610 256/128MB DDR2-BGA84 32/16Mx16 VIVO HDM (VGA5-4D1V59xx-00A

Friday, June 29, 2007

Date:

REVISION HISTORY

NOTE: This schematic represents the PCB, it does not represent any specific SKU. For Stuffing options (component values, DNI ,? please consult the product specific BOM. Please contact ATI representative to obtain latest BOM closest to the application desired.

Rev 32

Sch Rev	PCB Rev	Date	REVISION DESCRIPTION	
		2006.12.01	UPDATE SCHEM. BOM MANAGEMENT.	
		2006.12.14	UPDATE SCHEMATIC TO NETLIST WITH NO ERRORS	
		2006.12.18	DORINA UPDATE MEM SWAP	
		2006.12.19	REMOVE TP ON MEM - TO BE REPLCED BY 0.8MM PADS ON ALL LINES	
С		2006.12.20	CHANGED B67 to PN 5260014800G AND C76 to PN 4172010500G	
0	00A	2006.12.21	J2 REMOVED	
→		2007.01.15	NC626 removed (VDDC output cap). LDO output resistor (R879, R880) moved closer to LDO. MVDD LDO input resistors changed to 1R. Debug header changed to include Gen1/2 switch. HDMI caps removed. Added thermal shutdown option to power sequencing.	
		2007.01.16	REMOVE BACK BIAS, REMOVE MC624	
		2007.01.17	REMOVE R5515, R5516, R5521, R5524 REMOVE R94	
В		2007.01.22	ADDED H3, H4, H5	
		2007.01.22	DECAP CHANGES ON PAGE 3	
		2007.01.23	HEATSINK GROUNDING ADJUSTED	
		2007.01.23	DORINA - HEATSINK GNDING PINS ADJUSTED	
		2007.01.24	RM JTAG + SMA CLOCK CONNECTIONS TO EASE LAYOUT CONGESTION	
		2007.01.24	ADDED C300, C301, C302 (STITCHING CAPS) TO IMPROVE DDC LINES	
Α		2007.01.24	FIXED ORCAD NETLIST PROBLEM; NO EFFECTIVE CHANGE.	
		2007.01.24	ADD Q102 TO SOLVE A11 VDDR3 LEAKAGE PROBLEM.	
1	00B	2007.01.25	CHNG REF DES OF VDDR3 LEAKAGE BLOCK TO Q/R-90	
2	00C	2007.02.09		
		5	4 3 2 1	

