


U1J BL51 SP\_RX0P SP\_RX0N SP\_TX0P BH48 SP\_TX0N BH46 XBF48 SP\_RX2P SP\_RX2N SP\_TX2P SP\_TX2N BB44 SP\_RX3P SP\_RX3N SP\_TX3P AY42x SP\_TX3N AY41x BD48 BC49 SP\_RX4P SP\_RX4N SP\_TX4P AY45× SP\_TX4N AY44× BB52 SP\_RX5P SP\_RX5N XBB48 SP\_RX6P SP\_RX6N SP\_TX6P AW45 SP\_TX6N AW44 AY52 SP\_RX7P SP\_RX7N SP\_TX7P AU42 SP\_TX7N AU41 AY48 SP\_RX8P SP\_RX8N SP\_TX8P AU45 SP\_TX8N AU44 AW51 SP\_RX9P SP\_RX9N SP\_TX9P AT42 SP\_TX9N AT41 AV48 SP\_RX10P SP\_RX10N SP\_TX10P AT45× SP\_TX10N AT44× SP\_RX11P SP\_RX11N SP\_TX11P AR42× SP\_TX11N AR41× AT48 SP\_RX12P SP\_RX12N SP\_TX12P AR45 SP\_TX12N AR44 AR51 SP\_RX13P SP\_RX13N SP\_TX13P AN43 SP\_TX13N AN41 AP48 SP\_RX14P SP\_RX14N SP\_TX14P AN45 SP\_TX14N AN44 AN51 SP\_RX15P SP\_RX15N SP\_TX15P AM42 SP\_TX15N AM41 BM47 SP\_REFCLKP SP\_CALRP AH39 AH38 AH38


Date: Tuesday, May 27, 2008


**AMD** 


regarding the schemate are conseque, no notating in continue to a specific section of the continue of the schemate are consequences resulting specific section of decident sequencially sharp consequences resulting specific section of the schemate in collected result.


| Title RH PCIE RV770 512MB GDDR3 DUAL DL-DVI-I VO F | Ploc No. 105-B501xx-00






















- 4-pin Svideo MiniDIN P/N 6070001000G







AMD			Title  RH PCIE RV770 512MB GDDR3 DUAL DL-DVI-I VO FH			Schematic No. 105-B501xx-00	Date: Tuesday, May 27, 2008	
Allo			REVISION HISTORY	NOTE:	This schematic represent For Stuffing options (com Please contact AMD repre	schematic represents the PCB, it does not represent any specific SKU.  Stuffing options (component values, DNI, ? please consult the product specific BOM se contact AMD representative to obtain latest BOM closest to the application desired.		Rev 2
Sch Rev	PCB Rev	Date	REVISION DESCRIPTION					
0	A00	07/10/11	Initial design for RV770 GDDR3					
1	00в	08/02/25	Improvement: 1) Add 1 uF CAP on memory reset, Pg5 2) MVDDC current leakage board workaround; Pg13 3) MVDD Themal Protection, Pg 13 4) Improvement on Hot Plug protection Pg13 5) 12V_BUS & 12V_EXT Input Switch Circuit Page 13					
2	00	08/03/27	1.Correct PTC comparator power connection.     2. Add Fuse NF1200 on page 13					
		5	4		3	2		

