





































































Page36: PS: CURRENT STEERING, UNDER POWER BOOT, HOT-UNPLUG POWER CONNECTOR HOT-UNPLUG DETECT PEX Input Present 1 12V CURRENT STEERING (UNDER POWER BOOT): GUIDES CURRENT FROM PEX EDGE TO PEX 6 PIN INPUT AREA PEX Input - Power Level/PSI* Control













