

CONFIDENTIAL REPORTEDATY TO ADVINCED MEDO DEVICES INC.


TOOR TAkement diston Devices (spir) the unbains properly of MAD, and the provided only the critical southern or devictions and the provided only the critical southern or devictions and with AMD for extending reports. First deviction or devictions are devictions and the first an extending reports and the first an extending of the critical southern or devictions and the first an extending of the critical southern or provided are provided and any implied warrancy of mechanicality or first that the critical southern or provided and any implied warrancy of mechanicality or first that the critical southern or provided and any implied warrancy of mechanicality or first that the critical southern or provided and any implied warrancy of mechanicality or first that the critical southern or provided and any implied warrancy of mechanicality or first that the critical southern or provided any implied warrancy of mechanicality or first that the critical southern or provided any implied warrancy of mechanicality or first that the critical southern or provided any implied warrancy of mechanicality or first that the critical southern or provided any implied warrancy of mechanicality or first that the critical southern or provided any implied warrancy of mechanicality or first that the critical southern or provided any implied warrancy of mechanical southern or provided any implied warrancy or provided any implied warrancy or provided any implied warrancy or provided any implied


Recommended caps: (see BOM for qualified values/vendors) 10uF . X6S. 0805. 6.3V. 1.4MM MAX THICK 1uF, X6S, 0402, 6.3V 100nF. X7R. 0402 10nF , X7R, 0402 Place close to ASIC R116 _____ 182R R120 _____ 499R C1120 | 100nF_6.3V C1121 | 100nF_6.3V R122 499R R121 499R AP10 R111 _____ 182R C1124 | 100nF_6.3V | C1125 | 100nF_6.3V AR23 AP23 AP11 R126 _____ 499R R125 _____ 499R C1126 | 100nF_6.3V | C1127 | 100nF_6.3V AP24 AP12 R127 _____ 499R {15} {15} 2X3M 2X3P TXCBM_DPB3N TXCBP_DPB3P R132 ____ 499R C1132 100nF_6.3V C1133 100nF_6.3V {15} {15} T2X4M T2X4P TX3M_DPB2N TX3P_DPB2P R134 _____ 499R R133 ____ 499R (15) +T2P√DD 2X5M C1134 100nF_6.3V C1135 1100nF_6.3V B889 BLM15BD121SN1 TX4M_DPB1N TX4P_DPB1P R135 499R 2PVDD = C102 1uF_6.3V AK27 2XVDDC_1 2XVDDC_2 AG15 DP_CALR R128 _____ 150R Al 27 DP_GND DP_CALR GND_T2PVSS ±LTVDD18 +DPAB PVDD B887 BLM15BD121SN1 AL14 Overlap footprints (13) LVT_EN >> 1 S12304DS AH17_ AG17_ AJ26 AH26 C112 C113 MC113 1uF_6.3V 10uF_X6S 4.7uF_6.3V AP19 AR19 AN21 AN24 AN25 AN28 AP21 AP26 AR21 AR26 AJ24 AM22 AM24 AM26 AM27 GND TPVSS +1.8V RV630 F1.1V RV635 R109 0R B888 BLM15BD121SN1 +LTVDD33 Overlap footprints AN19 AN20 DPB_VDDR_ C105 100nF_6.3V AN16 AN17 DPB_VSSR_ DPB_VSSR_ DPB_VSSR_ DPB_VSSR_ DPB_VSSR_ V T10F_X6S HC117 10uF_X6S 4.7uF_6.3V C114 + C115 C107 : 1uF_6.3V = C116 1uF_6.3V AN18 AR18 +3.3V 2XVSSR 14 R40 R41 4.7K 4.7K DAC/CRT (15) CRT1DDCDATA (15) CRT1DDCCLK DDC2DATA DDC2CLK A_DAC1_G {15}
A_DAC1_GB {15} TR40 4.7K BUO (16) CRT2DDCDATA (16) CRT2DDCCLK DDC3DATA_DP3_AUXN DDC3CLK_DP3_AUXP - A_DAC1_B {15}
- A_DAC1_BB {15} BUO DDC4DATA_DP4_AUXN DDC4CLK_DP4_AUXP HSYNC_DAC1 {7,15} VSYNC_DAC1 {7,15} RSET R1030 499R GND_AVSSQ (16) HPD1 >>-HPD1 RSET AVDE C1020 C1021 C1022 100F 1000F_6.3V 1uF_6.3V NS1020 NS_VIA 2 0 1 V GND_AVSSQ AVSSC B884 BLM15BD121SN1 What happens to all the JTAG resistors especially R7 and also the TRs? I2C DEVICE ADDRESS' ON DDC2 VDD10 NS1021 NS_VIA DEVICE ADDRESS LM63 x100 1100 VSS1D DMINUS DPLUS TS_FDO (18) TS FDO → HSYNC_DAC2 {7,16}


VSYNC_DAC2 {7,16} VREFG A_DAC2_Y {17}


A_DAC2_C {17}


A_DAC2_COMP {17} COM R2SET R2030 715R GND_A2VSSQ XTALIN XTALOUT R2SET B883 BLM15BD121SN1 +A2VDDQ A2VDD0 C2022 1uF_6.3V C2021 100nF_6.3V A2VSSQ VDD2D +VDD2DI ♥ GND_A2VSSQ VSS2D +A2VDD B2030 26R_600mA +3.3V C2030 C2031 C2032 10nF 100nF_6.3V C2033 MC2033 10uF_X6S 4.7uF_6.3V Overlap footprints XTALIN S EY82 27_MHZ 1 Commerce Valley Drive East XTALOUT_S Markham, Ontario C85 220F Occ No. 105-B380xx-00 Title RV635 GDDR3 - ASIC MAIN


















CORE REGULATOR VDDC



+VDDC=0.8*(1+(ER1592 / ER1597))







COMPIGENTIAL & PROPRETARY TO ADVANCED MICRO SERVICES IN CONTROLL AS EAST OF THE ADVANCED MICRO SERVICES IN A stody problated. Use of this inhursive and disagree for any propretary of the Control of the Contr Advanced Micro Devices Inc.


AMD 1 Commerce Valley Drive East

Date: Wednesday, March 26, 2008

Sheet 11 of 21

105-B380xx-00

Rev 1





CONFEDENTIAL A PROPERTIANY TO ADVANCED MECHO ENCICLS MET
2007 Alleance Micro Deservices Inc.
1007 Alleance Micro Deservices Inc.
1007 Alleance Micro Devices Inc.
1007 Commerce Valley Drive East
with ADI to be caused in propose, Their desirbation or desirates
of the Time of the Commerce Valley Drive East
with ADI ADI Advanced Micro Devices Inc.
1007 Commerce Valley Drive East
with ADI ADI Advanced Micro Devices Agreement
with ADI ADI Advanced Micro Devices Agreement
with ADI ADI ADI ADI ADI ADI ADI ADI ADI
Markham, Charleto
Date: Wednesday, March 26, 2008
Rev 1

Title RV635 GDDR3 - MVDD SMPS 01


Title RV635 GDDR3 - MVDD SMPS 01

Power up Sequencing








CONFIDENTIAL & PROPRETARY TO ADVANCED MICROS REVIEWS AND A





Optional regulator for +1.1V Vout = 1.1V


























CONFIDENTIAL A PROPERTY OF ANY ACCOUNT OF STATE OF THE PROPERTY OF ANY ACCOUNT OF STATE OF ST

