# C116, NV18, 8MX16DDR, 128MB, Video IN/OUT, DVI -I, VGA

## Page Overview

1 18P112 OVERVIEW

2 NV18 AGP Section and AGP connector

3 NV18 FRAMEBUFFER Interface

4 MEMORY 128MB, 8Mx16DDR Bits 0..31

5 MEMORY 128MB, 8Mx16DDR Bits 32..63

6 MEMORY 128MB, 8Mx16DDR Bits 64..95

7 MEMORY 128MB, 8Mx16DDR Bits 96..127

8 NV18 STRAPPING, I/O Interface

BIOS, FAN CONTROL, THERMAL SENSOR

9 NV18 DACA, DACB output, SYNC amplifier

PLL Section

10 DACB MULTIPLEXER

11 PRIMARY DISPLAY Filter and Connector

12 SECONDARY DISPLAY Filter and Connector

13 NV18 INTERNAL TMDS Power and Output

TMDS Backdrive circuit

14 PRIMARY DISPLAY DVI-I option

Hotplug detection and Connector

15 VIDEO CAPTURE Philips 7114 I/O

16 VIDEO IN/OUT, Filter and Connector

17 VIDEO INTERNAL Input

Filter and Connector

18 1394 TEXAS TSB41AB2, PowerRails,

I/O, Internal and external connector

19 POWER SUPPLY

NVVDD, MEM\_VDD, A3V3, TMDS3V3, TMDSPLL

20 MECHANICS, and FBVDD

### HISTORY:

A00

00: INITIAL VERSION

X01 Remove R117, C87, C131, C143 for CKE

Change C736, C743 to 18pf capacitors.

Remove C1099 - additional Capacitor for AGPVREFcg

Changed AGPVREFcg circuit.

## C116 Base on P112 to Modify.

1. Change page 4~7 & page 18 Reference.

2. Change J1 foot print from silm type to stand D-SUB.

3. Remove I1394 function.

-4.Page 2, change voltage C75.1 & Q2.E from 3V3 to A3V3.

5. Page 8, Add Twin Bios for MSI function.

6.Page 16 ,replace INTERNAL VIDEO CAPTURE CONNECTOR.

7.Page 17 ,ADD C874 & C1098 ALE CAP. (DUAL-LAY)

8.Page 18 , Add H/W Monitor founction for MSI .


9.Page 2 change Q508, Q509 footprint from SOT23 to SOT-6 U200 package.

#### 00A change to version 100.

1. DACA and DACB signal swap.

600-10116-000X-A00

MICIA MAKES NO WARRANTIES, EXPRESSED, MPLED, STATUTIORY OR OTHERWISE WITH RESPECT TO THE MATERIALS, AND EXPRESSLY DISCLAMS ALL MPLED WARRANTIES OF NON-PRINGEMENT, MERCHANTIABILITY AND PRINCES PROPRIED LIAR PLAPED.



## AGP spacing rules

