# IQC 檢驗重點

料號

10TA1-609512-00R

品名規格

PWM uP9512RQGJ UPI SMD VQFN5x5-40L

## 零件樣品圖:



外觀文字面檢驗重點:

1. uP9512R: Part Number(不可變)


2&4. S&F: uPI internal trace code(可變)


3. G or X: 封裝廠(不可變)


5. 831: Data Code(可變)

6. ●: PIN1(不可變)

# 機構尺寸工程圖:







#### Note

1. Package Outline Unit Description:

BSC: Basic. Represents theoretical exact dimension or dimension target

MIN: Minimum dimension specified.

MAX: Maximum dimension specified.

REF: Reference. Represents dimension for reference use only. This value is not a device specification.

TYP. Typical. Provided as a general value. This value is not a device specification.

- 2. Dimensions in Millimeters.
- 3. Drawing not to scale.
- 4. These dimensions do not include mold flash or protrusions. Mold flash or protrusions shall not exceed 0.15mm.


# IQC電氣、機構檢驗重點:

- 1. 量測各部尺寸須與規格值相符.
- 2. 檢視產品外觀,表面無異物,且不得有任何破損及變形.
- 3. 電氣特性檢驗:


Parameter	Symbol	Test Conditions	Min	Тур	Max	Unit
Supply Input						
5VCC POR Threshold	POR <sub>5VCC</sub>	5VCC rising	4	4.3	4.5	٧
5VCC POR Hysteresis	HYS <sub>5VCC_POR</sub>			300		mV
Quiescent Current	l <sub>Q</sub>	EN = high , No switching		7		mA
Shutdown Current	I <sub>SD</sub>	EN = 0V		300		uA

4. 包裝方式如下,詳細請查閱data sheet.


# Tape & Reel Drawing



### Carrier Tape



#### Packing Illustration



#### μ-EDX 有害物質檢測:

 $\mu$ -EDX 需依照HCSR 有害物質管制規範實施檢測,並參照IQC EDX Test Guide 規範。