


ATI Technologies Inc.

1 Commerce Valley Divise East Mandam, Cristicio (2005) 852-2800 (2005)




ATI Technologies Inc.


1 Commerce Valley Drive East
Marketin, Ontario
Canada, 1,37 776
(806) 862-2600

Title
RH RV505CE 256MB DDR2 LP 4L
Son
Document Number 105-A85831-00A
Cate: Monday, July 24, 2006

Steet 2 of 17



RH RV505CE 256MB DDR2 LP 4L 105-A85831-00A




ATI Technologies Inc.

1 Commerce Valley Drive East
Markhum, Ortanio
Ceredad, 1377/36
(p0) 902-2000


RH RV505CE 256MB DDR2 LP 4L


Stan
C
Document Number 105-A85831-00A
Rev 0 105-A85831-00A


## Channel A













+VDDC=1.2V







## **CHANNEL A: RANK 0 128MB DDR2** [5] M\_QSA[7..0] «>> [5] M\_MDA[63..0] 《>> [5] M\_MAA[14..0] >> VDDQ1 VDDQ2 VDDQ3 VDDQ4 VDDQ6 VDDQ7 VDDQ8 VDDQ8 VDDQ10 CLKA#0 K8 CLKA0 CLKA#1 X K8 CLKA1 JB CKEAO >> → +MVDD B201 [5] 120R\_300mA M Possible alternate 5150005600G M B202 120R\_300mA Possible alternate 5150005600G B203 120R\_300mA Possible alternate 5150005600G B204 120R\_300mA Possible alternate 5150005600G VDDL VSSDL VDDL VSSDL VDDL VSSDL VDDL VSSDL M\_QSA2 F7 R211 10R E8 VSSQ1 VSSQ2 VSSQ3 VSSQ4 VSSQ5 VSSQ6 VSSQ7 VSSQ8 VSSQ9 VSSQ10 M\_QSA1 R214 10R M\_QSA7 R216\_\_\_\_\_\_10R M\_QSA4 R218 \_\_\_\_\_ 10R R212 ~~ VSS1 VSS2 VSS3 VSS4 VSS5 VSS1 VSS2 VSS3 VSS4 VSS5 R202 4.99K R204 4.99K R206 4.99K + C463 100nF R208 4.99K C413 100nF C438 100nF C406 C407 C408 C409 C410 1uF\_6.3V 1uF\_6.3V 1uF\_6.3V 1uF\_6.3V 402 402 R222 56R 402 R209 4.99K R219 4.99K R225 10R ATI Technologies Inc. 1 Commerce Valley Drive East Markham, Ontario Canada, L3T 7X6 (905) 882-2600 R210 4.99K R226 10R R220 4.99K RH RV505CE 256MB DDR2 LP 4L Size Document Number 105-A85831-00A Date: Monday, July 24, 2006 | Sheet

