MS-V080 -- G72 7300GS, 128/256 MB 64bit DDR2-84pin, DVI-I,HDMI

P381: G72, DDR2 MEMORY 16Mx16

Base on P381_ A04 (V056-V3.0)modify

Page8, removed mini-din 4pin. add mini-din 7pin support HDTV

Page 13: PowerSupplyI: NVVDD, A3V3 add mlcc 10U/16V 1206 5pcs
remove L5 L6 R7 R8 R9 ,D9

Page 9: ADD 預留 R593,R594,R595,R596 FOR EMI

Page 14: ADD 預留 R655,R656,R657,R658 FOR EMI

Page 12: Remove C8 EL Cap and change Q1 MOSFET package to T0252

MSI	Micro-Star International Co., LTD.	
	<Title> Over view	
	Size: Custom / Document Number: <Doc> MS-V080	Rev: 0A
	Date: Tuesday, September 05, 2006 / Sheet 1 of 15	

PEX-Interface



GPU: FB-Interface



Micro-Star International Co., LTD.	
<Title>	FB-Interface
Size: Custom	Document Number: MS-V080 (<Doc>) Rev: 0A
Date: Tuesday, September 05, 2006	Sheet 3 of 15

Memory Bit 0..31

PLACE ALL DISCRETE COMPONENTS AS NEAR AS POSSIBLE TO MEMORY







Place these caps next to plane transitions





X-cap for CMD



Micro-Star International Co., LTD.			
<Title> Memory Bit 0..31			
Size: Custom	Document Number: <Doc> MS-V080		Rev: 0A
Date: Tuesday, September 05, 2006	Sheet 4 of 15		

Memory Bit 32..63

PLACE ALL DISCRETE COMPONENTS AS NEAR AS POSSIBLE TO MEMORY



Micro-Star International Co., LTD.		
<Title> Memory Bit 32..63		
Size: Custom	Document Number: <Doc> MS-V080	Rev: 0A
Date: Tuesday, September 05, 2006	Sheet 5 of 15	

DAC-A, DB15 Connector



Micro-Star International Co., LTD.			
<Title> DAC-A, DB15 Connector			
Size: Custom	Document Number: <Doc> MS-V080		Rev: 0A
Date: Tuesday, September 05, 2006	Sheet: 6 of 15		

DAC-B



Micro-Star International Co., LTD.	
<Title>	DAC-B
Size: Custom	Document Number <Doc>: MS-V080
Rev	0A
Date: Tuesday, September 05, 2006	Sheet 7 of 15

Internal TMDS, DVI-Connector



Micro-Star International Co., LTD.			
<Title> Internal TMDS, DVI-Connector			
Size: Custom	Document Number <Doc>: MS-V080		Rev: 0A
Date: Tuesday, September 05, 2006	Sheet 8 of 15		

MIOA, MIOB Interface



Micro-Star International Co., LTD.	
<Title>	MIOA, MIOB Interface
Size: Custom	Document Number <Doc>: MS-V080
Rev: 0A	
Date: Tuesday, September 05, 2006	Sheet 9 of 15

STRAPS, Mechanical Parts



Bit	Signal	Values	
00:	PCI_AD_SWAP	0 REVERSED 1 NORMAL	
01:	SUB_VENDOR	0 NO_BIOS 1 READ FROM BIOS	
02:	RAM_CFG_0	0000 8MX16DDR2,64bit 0001 RFU 0010 16MX16DDR2,64bit INFINEON 0011 16MX16DDR2,64bit HYNIX 0100 RFU 0101 RFU 0110 32MX16DDR2,64bit INFINEON 0111 32MX16DDR2,64bit Hynix	1000 RFU 1001 RFU 1010 16MX16DDR2,32bit INFINEON 1011 16MX16DDR2,32bit HYNIX 1100 RFU 1101 RFU 1110 RFU 1111 32MX16DDR2,32bit HYNIX
03:	RAM_CFG_1		
04:	RAM_CFG_2		
05:	RAM_CFG_3		
06:	CRYSTAL_0	00 13.500 MHz 01 14.31818 MHz 10 27.000 MHz 11 UNKNOWN	
22:	CRYSTAL_1		
07:	TV_MODE_0	00 SECAM 01 NTSC 10 PAL 11 CRT	
08:	TV_MODE_1		
09:	AGP_3G_8x	0 AGP8x ENABLED 1 AGP8x DISABLED	
10:	AGP_SBA	0 SBA ENABLED 0 SBA DISABLED	
11:	AGP_FASTWR	0 FW ENABLED 0 FW DISABLED	
12:	PCI_DEVID_0	1100 (default 0x00FC)	
13:	PCI_DEVID_1		
20:	PCI_DEVID_2		
21:	PCI_DEVID_3		
14:	BUS_TYPE	0 PCI 1 AGP	
15:	FP_IFACE	0 24bit 1 12bit (DEFAULT)	
23:	FB_0	00 64M 01 128M 10 256M (DEFAULT) 11 512M	
24:	FB_1		
25:	BR	0 BRIDGE DISABLED 1 BRIDGE ENABLED	
26:	BR_128M	BR BITS IGNORED IF BRIDGE IS DISABLED	
27:	BR_AGP		
28:	BR_IO		
29:	ROM_TYPE_0	00 PARALLEL 01 SERIAL_AT25F 10 SERIAL_SST45VF 11 LPC	
30:	ROM_TYPE_1		
16:	USER_0	0000 (DEFAULT)	
17:	USER_1		
18:	USER_2		
19:	USER_3		
	PEX_PLL_EN_TERM100		
	3GIO_PADCFG_LUT_ADDR[0]		
	3GIO_PADCFG_LUT_ADDR[1]		
	host2ov_slot_clock_configuration		



MSI	Micro-Star International Co., LTD.		
<Title>	STRAPS		
Size: Custom	Document Number: <Doc> MS-V080		Rev: 0A
Date: Tuesday, September 05, 2006	Sheet 10 of 15		

XTAL, GPIO, BIOS, FAN, JTAG, THERMAL,SPIDF



Micro-Star International Co., LTD.	
<Title>	XTAL, GPIO, BIOS, FAN
Size: Custom	Document Number <Doc>: MS-V080
Rev: 0A	
Date: Tuesday, September 05, 2006	Sheet 11 of 15

PowerSupplyI: NVVDD, PLLVDD



Micro-Star International Co., LTD.	
NVVDD, PLLVDD	
Size: Custom	Document Number: MS-V080
Rev: 0A	
Date: Tuesday, September 05, 2006	Sheet 12 of 15

PowerSupplyII: 5V, DDC5V, F3V3, FBVDDQ,1V8

5V , DDC5V



F3V3





FBVDDQ



1.8V 320mA



Vout=Vref(1+Rbot/Rtop)

Vout=1.25(1+1.1K/2.49K)=1.8V

Micro-Star International Co., LTD.		
5V, DDC5V, F3V3, FBVDDQ		
Size: Custom	Document Number: MS-V080	Rev: 0A
Date: Tuesday, September 05, 2006	Sheet 13 of 15	

Hotplug Detection

Capacitance of HDMI_SDA_C & HDMI_SCL_C nets to Power/GND planes must be less than 50pF (try to make it lower)

TMDS AC termination PLACE CLOSE TO THE SII.



Micro-Star International Co., LTD.		
HDMI LINK Sil 1930		
Size: Custom	Document Number: MS-V080	Rev: 0A
Date: Tuesday, September 05, 2006	Sheet 14 of 15	


U507 SST89V54RD2
VQFP44 Package
AK4113VF
SN74CBTD3305C
uPA672T_DUAL
AHC1G000DCK_SC70
NC7SZ04M5
Micro-Star International Co., LTD.
Micro controller &Audio DAC
MS-V080
Size: Custom
Document Number
Rev 0A
Date: Tuesday, September 05, 2006
Sheet 15 of 15