

I2C Configuration Table

| I2C | Function | I2C Slave Address(7-bit mode) | | | | | | |
|-----------|--------------------|---|--|--|--|--|--|--|
| | eMCP DCDC | FAN53526 I2C Adress:0x60 (Write:0xC0 Read:0xCl) PM3003A I2C Adress:0x60 (Write:0xC0 Read:0xCl) RT5738 I2C Adress:0x53 (Write:0xA6 Read:0xA7) | | | | | | |
| BLSP2_I2C | 2nd Charger IC | BQ25970-Default NC I2C Adress:0x?? (Write:0x?? Read:0x??) | | | | | | |
| | Smart PA | CS35L35 I2C Adress:0x40 (ADR=0 Write:0x80 | | | | | | |
| | HPUE | TPS61280 I2C Adress:0x75 (Write:0xEA Read:0xEB) | | | | | | |
| | Sar Sensor | CY8C4024FNI-S412 | | | | | | |
| BLSP3_I2C | TP | GT917D I2C Adress:0x5D (Write:0xBA | | | | | | |
| BLSP6_I2C | NFC | PN553 I2C Adress:0x28 (Write:0x50 | | | | | | |
| CCI_I2C0 | Dedicated Cam I2C0 | S5K2L7SA-Rear Main CAM I2C Adress:0x2D (Write:0x5A Read:0x5B) | | | | | | |
| CCI_I2C1 | Dedicated Cam I2C1 | S5K4H7YX-Front Cam | | | | | | |
| 1 | ALS&PS | TMD27253 I2C Adress:0x39 (Write:0x72 | | | | | | |
| LPI_I2C | eCompass | AK09918C I2C Adress:0x0C (Write:0x18 | | | | | | |

SPI Configuration Table

| SPI | Function |
|-----------|----------------------|
| BLSP1_SPI | FPS interface |
| BLSP4_SPI | DTV interface |
| LPI_SPI | A+G sensor interface |

I2S Configuration Table

| I2S | Function |
|------------|----------------------------|
| I2S_2 | Smart PA CS35L35 interface |
| I2S_1_MCLK | Smart PA CS35L35 mclk |

| Company: Huaqin | | | | |
|--------------------------|------|----|---|--|
| I2C Configuration Table | | | | |
| Teller | 1.0 | | | |
| Saturday, December 09, 2 | 17 2 | 46 | - | |

| Sheet | Content | Sheet | Content |
|-------|------------------------------|-------|------------------------|
| 01. | Block Diagram | 24. | AUDIO_MIC_RCV_SPK |
| 02. | I2C Configuration Table | 25. | AUDIO_HEADSET |
| 03. | Table of Content | 26. | SENSORS_MOTOR |
| 04. | GPIO MAP | 27. | LCD_TP |
| 05. | SDM630 Control/UFS/SDC1/SDC2 | 28. | REAR_CAM/FLASH |
| 06. | SDM630 LPDDR4 | 29. | FRONT_CAM/CAM_POWER |
| 07. | SDM630 CSI/DSI | 30. | SIM_SD_KEY_LINK_BATT |
| 08. | SDM630 GPIO (Internal Codec) | 31. | DTV |
| 09. | | 32. | NFC |
| 10. | SDM630 Power (Other, LP4X) | 33: | PRIMARY_ANTENNA |
| 11. | SDM630 Ground | 34: | PA & PA THERMAL |
| 12. | PM660 CLKs/Control_GND | 35: | TRX_LB |
| 13. | PM660 Buck Converter | 36: | TRX_MHB |
| 14. | PM660 LDO Circuits | 37: | DIVERSITY_ANT |
| 15. | PM660 Charger_FG | 38: | DRX_MB_HB |
| 16. | | 39: | DRX_LB |
| 17. | PM660L Buck and LDO | 40: | SDR660_MSS |
| 18. | PM660L CODEC | 41: | SDR660_PWR |
| 19 | PM660L Display | 42: | SDR660_DA/PRX/DRX/FBRX |
| 20. | eMCP | 43: | |
| 21. | 30W CHARGE | 44: | WIFI_2.4G_5G & BT |
| 22. | Wipower | 45: | GPS |
| 23. | Test Points | 46: | WCN3980 |

| Company: Huaqin | | _ |
|------------------|-----|---|
| Table of Content | | _ |
| Teller | 1.0 | _ |
| | | |


| GPIO | MAP | SDM63 | 0 GPIO | Configuration | ' | |
|------|---------|-------------------|---------|-------------------------|-------------|--|
| | GPIO_0 | BLSP_SPI_MOSI_1 | GPIO_42 | NC | GPIO_84 | UIM2_CLK |
| | GPIO_1 | BLSP_SPI_MISO_1 | GPIO_43 | NC | GPIO_85 | UIM2_RESET |
| | GPIO_2 | BLSP_SPI_CS1_N_1 | GPIO_44 | NC | GPIO_86 | UIM2_PRESENT |
| D | GPIO_3 | BLSP_SPI_CLK_1 | GPIO_45 | NC | GPIO_87 | UIM1_DATA |
| | GPIO_4 | BLSP_UART_TX_2 | GPIO_46 | CAMO_RST_N | GPIO_88 | UIM1_CLK |
| | GPIO_5 | BLSP_UART_RX_2 | GPIO_47 | CAM1_RST_N | GPIO_89 | UIM1_RESET |
| | GPIO_6 | BLSP_I2C_SDA_2 | GPIO_48 | CAM2_RST_N | GPIO_90 | UIM1_PRESENT |
| | GPIO_7 | BLSP_I2C_SCL_2 | GPIO_49 | NC | GPIO_91 | UIM_BATT_ALARM |
| | GPIO_8 | BLSP_SPI_MOSI_3 | GPIO_50 | CAM_AF_VDD_EN | GPIO_92 | NC |
| | GPIO_9 | BLSP_SPI_MISO_3 | GPIO_51 | CAM_AVDD_EN | GPIO_93 | NC |
| | GPIO_10 | BLSP_SPI_CS_N_3 | GPIO_52 | NC | GPIO_94 | NC |
| | GPIO_11 | BLSP_SPI_CLK_3 | GPIO_53 | LCD0_RESET_N | GPIO_95 | NC |
| | GPIO_12 | NC | GPIO_54 | SD_CARD_DET_N | GPIO_96 | WDOG_DISABLE |
| | GPIO_13 | KEYPAD_LED_PWM | GPIO_55 | DP_EN_N | GPIO_97 | NC |
| c | GPIO_14 | BLSP_I2C_SDA_4 | GPIO_56 | USBC_ORIENTATION | GPIO_98 | NC |
| | GPIO_15 | BLSP_I2C_SCL_4 | GPIO_57 | FORCED_USB_BOOT | GPIO_99 | QLINK_REQUEST |
| | GPIO_16 | BLSP_UART_TX_5 | GPIO_58 | USB_PHY_PS | GPIO_100 | QLINK_ENABLE |
| | GPIO_17 | BLSP_UART_RX_5 | GPIO_59 | MDP_VSYNC_P | GPIO_101 | RFFE1_DATA - SDR660 debug |
| | GPIO_18 | BLSP_UART_CTS_N_5 | GPIO_60 | NC | GPIO_102 | RFFE1_CLK - SDR660 debug |
| | GPIO_19 | BLSP_UART_RFR_N_5 | GPIO_61 | NC | GPIO_103 | RFFE2_DATA - (41)QAT3533 |
| 1 | GPIO_20 | FP_SUB_RESET | GPIO_62 | NC | GPIO_104 | RFFE2_CLK - (41)QAT3533 |
| | GPIO_21 | SMB_STAT | GPIO_63 | NC | GPIO_105 | NC |
| | GPIO_22 | BLSP_I2C_SDA_6 | GPIO_64 | NC | GPIO_106 | NC |
| | GPIO_23 | BLSP_I2C_SCL_6 | GPIO_65 | NC | GPIO_107 | RFFE4_DATA-(45)QSW8574,(48)RF1656SR |
| | GPIO_24 | CDC_SWR_CLK | GPIO_66 | TS_RESET_N | GPIO_108 | RFFE4_CLK -(45)QSW8574,(48)RF1656SR |
| Ω | GPIO_25 | CDC_SWR_DATA | GPIO_67 | TS_INT_N | GPIO_109 | RFFE5_DATA-(52)QAT3514, (52)QAT3550,(47) QAT3522 |
| | GPIO_26 | WSA_SPKR_SD_N_1 | GPIO_68 | ACC_GYRO_DATA_AVA_INT_N | GPIO_110 | RFFE5_CLK-(52)QAT3514, (52)QAT3550,(47)QAT3522 |
| | GPIO_27 | NC | GPIO_69 | ACC_GYRO_MOT_INT_N | GPIO_111 | RFFE6_DATA - (46)QET4101 ch0, (41)QPA4361 |
| | GPIO_28 | NFC_IRQ | GPIO_70 | MAG_INT_N | GPIO_112 | RFFE6_CLK - (46)QET4101 ch0, (41)QPA4361 |
| | GPIO_29 | NFC_EN | GPIO_71 | ALSP_INT_N | GPIO_113 | NC |
| | GPIO_30 | NFC_DWL_REQ | GPIO_72 | FP_INT_N_1 | LPI_GPIO_0 | LPI_SPI_1_CS1_N |
| H | GPIO_31 | NFC_ESE_PWR_REQ | GPIO_73 | NC | LPI_GPIO_1 | LPI_PWR_EN |
| | GPIO_32 | CAM_MCLK0 | GPIO_74 | NC | LPI_GPIO_2 | LPI_I2C_3_SDA |
| | GPIO_33 | CAM_MCLK1 | GPIO_75 | NC | LPI_GPIO_3 | LPI_I2C_3_SCL |
| | GPIO_34 | CAM_MCLK2 | GPIO_76 | NC | LPI_GPIO_4 | LPI_SPI_2_CS_N |
| | GPIO_35 | NC | GPIO_77 | AUDIO_USBC_EN2_N | LPI_GPIO_5 | LPI_SPI_2_CLK |
| | GPIO_36 | CCI_I2C_SDA0 | GPIO_78 | WMSS_RESETN | LPI_GPIO_6 | LPI_SPI_2_MOSI |
| | GPIO_37 | CCI_I2C_SCL0 | GPIO_79 | PWM_CNTRL | LPI_GPIO_7 | LPI_SPI_2_MISO |
| | GPIO_38 | CCI_I2C_SDA1 | GPIO_80 | AUDIO_USBC_EN1 | LPI_GPIO_8 | LPI_SPI_1_CS_N |
| | GPIO_39 | CCI_I2C_SCL1 | GPIO_81 | MSS_LTE_COXM_TXD | LPI_GPIO_9 | LPI_SPI_1_CLK |
| | GPIO_40 | NC | GPIO_82 | MSS_LTE_COXM_RXD | LPI_GPIO_10 | LPI_SPI_1_MOSI |
| | GPIO_41 | FL_STROBE_TRIG | GPIO_83 | UIM2_DATA | LPI_GPIO_11 | LPI_SPI_1_MISO |


| LPI_GPIO_12 | LPI_UART_1_TX |
|-------------|------------------|
| LPI_GPIO_13 | LPI_UART_1_RX |
| LPI_GPIO_14 | NC |
| LPI_GPIO_15 | NC |
| LPI_GPIO_16 | NC |
| LPI_GPIO_17 | NC |
| LPI_GPIO_18 | CDC_PDM_CLK |
| LPI_GPIO_19 | CDC_PDM_SYNC |
| LPI_GPIO_20 | CDC_PDM_TX |
| LPI_GPIO_21 | CDC_PDM_RX0 |
| LPI_GPIO_22 | CDC_PDM_RX0_COMP |
| LPI_GPIO_23 | CDC_PDM_RX1 |
| LPI_GPIO_24 | CDC_PDM_RX1_COMP |
| LPI_GPIO_25 | CDC_PDM_RX2 |
| LPI_GPIO_26 | CDC_DMIC_CLK1 |
| LPI_GPIO_27 | CDC_DMIC_DATA1 |
| LPI_GPIO_28 | CDC_DMIC_CLK2 |
| LPI_GPIO_29 | CDC_DMIC_DATA2 |
| LPI_GPIO_30 | LPI_QCA_SB_CLK |
| LPI_GPIO_31 | LPI_QCA_SB_DATA0 |


| PM660 GPIO Configuration | | | | |
|--------------------------|----------------|---------|-------------------|--|
| GPIO_1 | OPTION1 | GPIO_8 | SLB | |
| GPIO_2 | DIV_CLK2 | GPIO_9 | uUSB_TYPEC | |
| GPIO_3 | NC | GPIO_10 | WCSS_VCTRL | |
| GPIO_4 | NFC_CLK_REQ | GPIO_11 | HOMEKEY_FP_PM_INT | |
| GPIO_5 | WLAN_SW_CTRL | GPIO_12 | WIPWR_MODE | |
| GPIO_6 | SLP_CLK | GPIO_13 | PM_A_GPIO_13 | |
| GPIO_7 | UIM_BATT_ALARM | | | |


| РМ6 | PM660A GPIO Configuration | | | | |
|--------|---------------------------|---------|---------------|--|--|
| GPIO_1 | OPTION2 | GPIO_8 | SD_CARD_DET_N | | |
| GPIO_2 | LPI_PWR_EN | GPIO_9 | WCSS_VCTRL | | |
| GPIO_3 | FRONT_CAM_DVDD_EN | GPIO_10 | SLB | | |
| GPIO_4 | REAR_CAM_DVDD_EN | GPIO_11 | LP4x_CTRL | | |
| GPIO_5 | NC | GPIO_12 | LP4x_MODE | | |
| GPIO_6 | FP_VDD_EN | | | | |
| GPIO_7 | KEY_VOL_UP_N | | | | |


| Company: Huaqin | |
|-------------------------|-----|
| GPIO MAP | |
| Teller | 1.0 |
| Sahimlay Dazember (9. 2 | |




























VREG_L16


VDD_L15_16_17_18_19


+ 0.95_1uF_0201_X5R_6.3V_M



















| 24W CHARGE REF 2101-2199 | | |
|--------------------------|---|----------|
| | | |
| | | D |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | G |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | _ |
| | | |
| | | |
| | | ^ |
| | | |
| | Company Huasjn 30W CHARGE | \equiv |
| | Tutur 1.0 Sauren, Osianner 10, 2017 21 | 46 |
| | | |

٦l





Test Points REF 2301-2399







JTAG CONNECTOR













| Company: Huaqin | | |
|-----------------|-----|--|
| Test Points | | |
| Teller | 1.0 | |
| | | |

AUDIO_MIC_RCV_SPK REF 2401-2499









Company: Huasin

AUDIO_MIC_RCV_SPK


Titler

1.0

SMARADE: Discented 02: 207 24 46

AUDIO_HEADSET REF 2501-2599

AUDIO JACK



Company: Huasijn


AUDIO_HEADSET


Tuller


1.0


National Processor IS SV 25 SS


SENSORS_MOTOR REF 2601-2699













Company: Huasijn
SENSORS_MOTOR
Tulber
1.0
1.0
24 44




REAR_CAM/FLASH REF 2801-2899

Rear Cam Inteface




Rear Cam FLASH LED-Dual CCT




SLAVE CAMERA


OV5675-Rear Slave Cam I2C Adress:0x36 (Write:0x6C Read:0x6D)




| Company: Huaqin | | |
|-------------------------|-------|----|
| REAR_CAMFLASH | | |
| Teller | 1.0 | |
| Sahimlay Dazember (9. 2 | 17 28 | 28 |





S5K4H7YX-Front Cam I2C Adress:0x10 (Write:0x20 Read:0x21)





| Camera Power Supply Map | | | |
|-------------------------|------------------------------|-------------------------|----------------|
| | Front CAM | REAR CAM_MAIN | REAR CAM_SLAVE |
| DVDD | 8MLD01-1V2 12/20 MLD02-1V | LD03-1V05 | LD01-1V2 |
| AVDD | LD04-2V8 | | LD05-2V8 |
| IOVDD | VREG_L11A | | |
| AFVDD | / | LDO6-2V8 or VREG_L8B | / |


















| Company: Huaqin | | |
|--------------------------|-------|----|
| FRONT_CAM/CAM_POWER | | |
| Teller | 1.0 | |
| Saturday, December 03, 2 | 17 29 | 46 |













| Company: Huaqin | |
|-----------------------|-----------|
| DTV | |
| Teller | 1.0 |
| Sahintay Dazember (9) | 017 31 48 |


Company: Huaqin
N°C













DRX_MB_HB





Company: Huagin
DRX_MB_HB
Taller 1.0

DRX_LB



SDR660_MSS






Company: Huacijn

SORedo_MSS

Tular

1.0


SDR660_PWR






| Company: Huaqin | | |
|-----------------|-----|--|
| SDR660_PWR | | |
| Teller | 1.0 | |
| | | |

SDR660_DA/PRX/DRX/FBRX




QET4101 & HPUE Boost




Company: Huasin

QET4101

Talker 1.0






Company: Huasijn

GPS

Tuther

1.0

State 10 Powerbor 19 97 45 46



Company: Huaqin
WCH5980
Teller 1.0