

Model : SM-G928W8

Revision : REV0.8

Manufacture Count :

Charge :


## Contact :

Date :

## Routing :

## Resin :

# Setup(2015-05-20)\_HHP




| Activity            | Hours |
|---------------------|-------|
| Reading             | 12    |
| Watching TV         | 8     |
| Playing Video Games | 6     |
| Homework            | 4     |

AON1605(TR7000) : IT'S Wrong Polarity possibility. Check the Pin1  
2007-010848(R10004) : Check! Bottom Surface of Component

Model : SM-G928W8  
Revision : REV0.8  
Manufacture Count :  
Charge :  
Contact :  
Date :  
Routing :  
Resin :

Setup(2015-05-20)\_HHP



AON1605(TR7000) : IT'S Wrong Polarity possibility. Check the Pin1  
2007-010848(R10004) : Check! Bottom Surface of Component