


Model : SM-G928A
Revision : REV 0.8
Manufacture Count :
Charge :
Contact :
Date :
Routing :
Resin :


Setup(2015-05-20)_HHP



AON1605(TR7000) : IT'S Wrong Polarity possibility. Check the Pin1
2007-010848(R10004) : Check! Bottom Surface of Component

Model : SM-G928A
Revision : REV 0.8
Manufacture Count :
Charge :
Contact :
Date :
Routing :
Resin :

Setup(2015-05-20)_HHP



AON1605(TR7000) : IT'S Wrong Polarity possibility. Check the Pin1
2007-010848(R10004) : Check! Bottom Surface of Component