






IREPAIR




Title		UNIQUE POWER	
Author	Anthony	Editor	ref: 10/10




MT6765 / 62	MT6357 CRV
MT6761	MT6357 MRV

Note 21-5: Please connect VS2_LDO1(F15) to VS1_PMU if voltage applied to VCAMD(E17) ≥ 1.3 V




[print guide](#)
[print guide in US/UK/18](#)


Charger







LCM Backlight LED driver




LCD Bias




Flash LED 5V Boost




Ext. buck LPDDR4X/LPDDR4 VDRAM



Ext. buck LPDDR4X VDDQ



LPDDR4X/LPDDR4 VDD1 1.8V LDO



'Schematic design notice of "28_POWER_ThirdParty-Power"


Note 28-1: VDD1 Layout placement please close to BP

Note 28-2: VDD2 Buck Layout placement please close to PMIC MT6507


Note 28-3: VDD3 LDO Layout placement please close to MT6507

IREPAIR


Handset 2nd Microphone




Earphone Audio



Earphone MICPHONE




SPEAKER UP




I2C address 0X58

SPEAKER DOWN



I2C address 0X59

iREPAIR



Note 44-1: Please refer to power supply related page select output voltage properly for LP4XLP4.

Note 44-2: DRAM 2Dx resistor > 240ohm (1%) that must be connected to VDDQ.

Note 44-3: Please refer to eMCP vendor's datasheet or MTK common design notice to get the recommendation bypass cap. value for VDDQ/VDDIO/VDDIO2 power domains of eMMC.


Note 44-4: VDDQ VDDIO decoupling cap. should be DRAM bank.
For other cap for PMAC 3+10uF at PMAC page!
Please also refer to MTK and layout guide for placement.

DRAM type	VDDQ	VDDIO
LP4XLP4	1.0V	1.0V
LP4XLP4	1.0V	1.0V
LP4XLP4	1.0V	1.0V
LP4XLP4	1.0V	1.0V

Note 44-5: R703/R704 could be replaced with 0-ohm / 0402 / 3 for LP4 DRAM

iREPAIR


BATTERY CONNECTOR



IREPAIR



Front Camera - 5M&8M

QTECH9323Y50A-FG50 DC address: (Write 50A, Read 0x0B)



Rear-Main Camera(AF-16M/13M)


QTECH916124B DC address: (Write 0x45, Read 0x41)



Dual CAM

Rear-Slave-FF Camera 2M Depth


TSPVCC00M1-CH470 DC address: (Write 0x0E, Read 0x0F)



Dual CAM







Rear-Slave-FF Camera 2M Macro

Rear camera Union Image(ST-2N637FF-V1) DC address: (Write 0x03, Read 0x01)




iREPAIR

iREPAIR



IREPAIR


SIM and TF



IREPAIR



KEY

Volume Up : HOME Key / GND
Volume Down : KP02L Y GND
DO NOT put pull-up resistor on PWRKEY





iREPAIR






$$V_{op} = V_{max} \cdot \frac{R1 + R2}{R1} = 1.2V \cdot \frac{(20K + 10K)}{10K} = 11.6V$$

LCM Connector MAIN




IREPAIR


Download mode TP






USB Test point



BATTERY Test point





UART




IREPAIR






IREPAIR




RF MT6177




IREPAIR




IREPAIR




IREPAIR



IREPAIR



IREPAIR

The logo for iREPAIR, featuring the word "iREPAIR" in a stylized, italicized font. The "i" is green, and the "REPAIR" is grey with a white outline. A small "1" is positioned below the "R".