f1-15 pad 0 select refactor show block & usage RC 3C ins RUN f2 Lc⁷ D reformat S K complete find smart line action complete F 4C del f9 f10 quickfix G С ٠,< X generate replace search path path 5C М f13 ws1 VCS f12 В esc bootloader enter L2 ralt super ralt **@** C-A-del tab shift <u>L3</u> ctrl alt bksp space <u>L2</u>

Alt+Shift

mouse