
RMS error of x_1
Error [m]
0.06
0.04
0.02
0
0
1
2
3
4
5
6
Proposed method
Previous method
Classic method
Tank empty
Error of x_2
Error [m]
0.02
0
-0.02
-0.04
0
1
2
3
4
5
6
Proposed method
Previous method
Classic method
Tank empty
RMS Error of x_3
Error [deg]
10
5
0
0
1
2
3
4
5
6
Proposed method
Previous method
Classic method
Tank empty
Error of x_4
Error [deg]
0.15
0.1
0.05
0
0
1
2
3
4
5
6
Time [s]
Proposed method
Previous method
Classic method
Tank empty