SERVICE MANUAL

EXPLODED VIEWS


for

MAMIYA C220 Professional


(mFC)





MAMIYA CAMERA CO., LTD. TOKYO JAPAN





-1-
















mFC 4200





PARTS LIST

METHOD OF REQUESTING SPARE PARTS FOR REPAIR USE

When ordering spare parts for repair purposes, mark the request in the following manner after referring to our parts lists.

NOTE:

When ordering spare parts, always type the complete code and numbers in the Parts No. column of the appropriate parts lists.

EXAMPLE:

(Model and nomenclature of camera)

Parts No.	Description	Quantity
mFC 4012	Bottom cover	5
mFC 4125K2	Lever assembly	5 - 1 A
hFC 4381	Friction milled wheel	
pl°C 5116-2-4	Washer	20
3Bs 1.7 x 2.5 BNi	Screw	20
1'B 1.7 x 2.5 B	Screw	20

Parts No.	Common Parts No.	Description	Pcs.	of	Ref.	Remurks
mFC 4011		Camera body	1	x	4	
mPC 4012		Bottom cover	1	9	•	
mFC 4013		Hinge shaft	1	•	3 1	
PD2x3BN1		Screw for mFC 4012	6	•	1	
mFC 4019		Film spool holder	1	•	2	
mFC 4021		Tripod socket	1	•	2	
cFC 4022		Leatherette for Tripod socket	1	• •	1	
mFC 4023		Right strap loop	1	•	2	
PD2x3.5B		Screw for mFC 4023 % 4025	4	•	2	
mFC 4025		Left strap loop	1	Ö	2	
mFC 4026		Name plate	1	•	1	
PD2x5B		Screw for mFC 4021	4	•	2	
FC 4031		Film roller	2	0	5	
FC 4033		Bracket for film roller	2	•	2	
MFC 1034K		T-spring assy.	1	. •	2	
- LFC 4034		T_spring	1	Xª		
LAFC 4035		T-spring roller	1	. x *		
3Ds 1.7x3.5E	en i	Screw for FC 4032 & 4033	4	•	2	
aFC 4042		Catch plate	1		2	
hFC 4043		Screw	2	•	2 .	

Parts No.	Common Parts No.	Description	Pcs.	Term of Ref. sale page	Remarkı
•				-	
FC 4027	mFC 4044	Nut	2	• 2	
rc 4047		Screw	3	• 2	微感形态
FC 4048		Leaf spring	1	• 2	ing the state of t
FC 4051		Mirror	1	• 2	
AFC 4052		Bracket for mirrer	1	o 2	
aFC 4053		Spring for clamp mirror	1	• 2	
4B 1.7x2 BN		Serew for aFC 4053	1	o 2	
3Be 1.7x3 B	(1	Serew for aFC 4052	2	a 2	ing the state of t
PB 1.7x2.5B		Screw for aFC 4052	1	o 2	
mFC 4061K2		Frame, focusing screen	1	• 2.6	
- mFC 4061 K		Frame, focusing screen	1	• 6	
-FC 4062		Pin	2	x	
-dFC 4063		\$cre♥	1	• 6	
- dFC 4064		Nut	1	• 6	
		Vasher	- 1 1	• 6	
- aFC 4065			5	0 2	
aFC 4066		Screw			
mFC 4081		Name plate	1	• 2	
mFC 4082		Bracket	1.	• 2	
PD 1.7x3	BN 1	Screw for mFC 4082	3	• ** 2 *	and the second second
FC 4067	0.1 0.2	Tasber	0 to	• 2	10,58
	0.5				
4w2x0.1		Washer	0 to 2	• 2	
4W2x0.2		Vasher	0 to 2	0 2	
4W2x0.5		Washer	0 to 2	•	
- SFC 4091		Ground glass	1	•• 6	

Parts No.	Common Parts No.	Description	Pc	Term of a. sale	Ref.	Remarks
- FC 4092		Freenel lens	1	l ••	6	
- drc 4093		Ground glass sprin	\$	•	6	
FC 4094		Screw		۰.	6	A Company of the Comp
mFC 4116	9 4	Knob	might if a	L o	1	
mFC 4117	er e	Disk	Apple 1	l o	1	
_ mFC 4119		Boss	:	2 0*	6	
4B 1.7x2		Screw for mFC 4116	,	2 0	1	
mFC 4121K2		Lock lever assy.) 	L o	4.6	
-mFC 4121		Lock lever		٠.	6	and the second s
mFC 4122		Lock pin	Salan Angles	i oʻ	6	
mFC 4123		Pin		l 0°	6	All the service of th
mFC 4162		Pin		L 0°	6	en filosofie en filosofie Portugues en filosofie
mFC 4124		Shoulder screw		L o	4	
mFC 4125K2		Lever assy.		L o	4.6	
- mFC 4125	And the second s	Lever		0.0	6	
■FC 4126		Pin	WAY DIE	L 0*	ć	
3Bs 1.7x2.5	April 1997	Screw for mFC 4125	K2 :	3 0	4	
mFC 4128	en e	Label, "lock, unlo	ck ⁿ	t 0	4	
mFC 4129		Window glass		ı °	1	
mFC 4131K2		Control lever, loc and unlock assembly		0	4.6	
- mFC 4131		Centrol lever		i 0ª	6	
- FC 4132		Hub		l o*	' 0	
FC 4133		Shoulder screw		r	4	
PC 4134	$\frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) \right) = \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right) + \frac{1}{2} \left(\frac{1}{2} \left(\frac{1}{2} \right$	Spring		1 0	6	

Common Parts No. Parts N	le. Description	Pcs.	Term of sale	Ref.	e i grangsen (A
	ere	<u></u>			
FC 4135	Shoulder screw, anchor	. 1	0	4	
mFC 4141	Idle gear	1	c	4	The second of th
FC 4125 mFC 414	12 Shoulder screw	1	0	4	्रिक्षित्र अ नुष्
FC 4151	Gear	1	×		tija (il.) – ktory ji ži to
dFC 4152K	Gear shaft assy.	1	~	4	
dFC 4082 mFC 415	53 Sleeve bearing	1, 1 2 2 1	0	384	
dFC 4154	Sufety collar	1 1	. C	3	
FC 4155K2	Light-tight flap assy	. 1	•	4.6	
-FC 4155	Light-tight flap	1	0*	5	ang at the South of the South o
-FC 4156	. Spring arm	1 ³ (1)	••	ó	
FC 4157	Rivet	2	•	6	
FC 4158	Velveteen	1	••	6	
4B 1.7x2.5	Screw for dFC 4154	1	•	3	
38s 1.7x2.5BNi	Screw for FC 4155 K2	3	•	4	
mFC 4161	Idle lever	1.	C	4	
(mFC 4162)	Pin	1	•	6	mFC 4121F
CFC 4163	Hub	1	•	ó	
=FC 4164K2	Red warming signal	1	0	4.6	
-mFC 4164	Signal arm	1	•	ć.	
■FC 4174	Red signal	1	•	6	
5B 1.7x3	Screw for mFC 4164 K2	1	•	· 4	
mF(4172	Hollow cover	1	0	4	
mFC 4173	Guid plate		•	4	
(mFC 4174)	Red signal	1	0*	6	mFC 4164×2
PD 1.7x2.5B	Serew for mFC 4172	3	•	4	

Common Parts No. Parts No.	Description	Pcs.	Term of sale	Ref.	Remorks
PB 1.7x2B	Screw for mFC 4173	1	•	.· 4	
mFC 4181	unleck lever	1	•	4	
mFC 4187	Shoulder screw	2	•	4	
gFC 4191	Pawl	1	•	3	
dFC 4086 =FC 4192	Shoulder screw	1	•	3	
gFC 4194	Spring for pawl complet	• 1	•	3	. The second of
mFC 4200	Focusing hood	. 1	•	1. 7	
mFC 4211K	Frame assy.	1	•	7	
-mFC 4211	Franc	1	x*		
PC 4212	Bearing	2	x*		
-cFC 4221	Finder frame	1	••	7	
cFC 4222K	Finder frame assy.	1	0*	7	
-cFC 4222	Finder frame	1	x*		
FC 4223	Bearing	2	x*		
-FC 4224	Spring anchor	2	0 *	7	
-cFC 4225	Spring	1	o •	7	
-mFC 4226	Shaft	1	0*	7	
-FC 4227	Shoulder screw	1	0.	7	
-dFC 4228	Screw	2	•	7	
-3Ds 1.7x2.5BNi	Screw for cFC 4221	4	•	7	
-cFC 4231	Finder flap	1	0*	7	
-FC 4232	Arm plate	1	•	7	
-FC 4233	Pin	1	••	7	engan jaga di Arka di Arka Per
-cFC 4234	Spring	1	•	7	
-aFC 4237	Pin	· ,, 2	•	7	
-Rm 1.0	Hivet for FC 4232	2	•	7	

Common Parts No. Parts No.	Description	Pcs.	Term of sale	Ref.	Romarka
mFC 4241	Reur plate	1 -	0.	7	
mFC 4242	Bracket	1	•	7	
mFC 4243	Shaft	1 "	•••	7	
FC 4244	Spring	1	•	* 7	
- aFC 4245	Screw	7	•	7	
- cFC 4246	Stopper plate	1	0.	7.7	
-2.5cel.4x2Cr	serew for cFC 4246	2	••	7	
- uFC 4251	Plate visit in the Single of	1	•	7	
- aFC 4252	Retainer	1	••	7	
aFC 4253	Rivet	6	· •	7	
-aFC 4254	Magnifying glass	1	0*	7	
-mFC 4255	Shaft	5 · · 1	•	7	
- aFC 4256	Spring plate	2	• •	7	
-aFC 4257	Plate	2	•	7	
-mFC 4261	Right plate	1	•	7	
mFC 4262	Left plute	1	• •	7	
-mFC 4263	Bracket	2	0*	7	
-mFC 4264	Shaft	2	•	7	
		2	•	7	
LFC 4265	Spring			•	
mFC 4311K2	Film winding gear assy.		. •	3.6	in in the second of the second
-mFC 4311	Winding shaft	1	. •	6	
-mFC 4334	Winding gear	s 1	••	6	
mFC 4337	Washer	0 to	•	6	
-mFC 4366	Bearing	1	•	6	
	Plate		•	6	
- mFC 4367	PAGE	· · · · · · · · · · · · · · · · · · ·	- 		A Section of the sect

Parte	Na.	Com	ion .s No.	Description	Pcs.	Term of sale	Ref.		Remarks
									<u> </u>
-EPC	4368			Coupler for spool	и (2.1 г. 1	. ••	6		
LEFC	4369			Nut	. 1	•	6		
r pFC	5112	m P C	4312	Ratchet pawl	2	•	6		
pr c	5113	mFC	4313	Shoulder screw	2.	••	6		
pFC	5111	■FC	4314	Ratchet wheel	1	•	1		
pFC	5115	mPC	4315	Spring		•	1		
- eFC	4316			Knob	· (48 - 1	0*	6	v. "	with the same of the
- mFC	4317		\$	Shoulder screw	1	0.	6		
dwP	1794	mFC	4318	Shoulder screw		• •	3		
mFC	4319			Knob cover	1	•	· 1 .		
3De2	x3Cr			Screw for mFC 4319	1	• • ,	1		
BEC	4321K2			Film winding knob as	sy. 1	•	1.6		等度的 表示。
-mFC	4321			Film winding knob	1 .	ς	6		
- mFC	4322			Bracket	1	0*	6		
- mFC	4323			Shaft	#1. 1 1	0.	6		for a second
-mFC	4324			Spring	1	•	ပ်		
mFC	4325K			Winding lever assy.	1	0*	6		
- 1	C 4325			Winding lever	1	* x *			
Last	rc 4326			Boss	•	x*			
eFC	4327			Idle gear	, a	•	3		
mFC	4328			Shoulder screw	 1	•	3		
cFC	4329			Pointer	1	•	4		
4B2	k4			Screw for mFC 4322	2	0.	6		and the second s
gFC 43	331			Pawl	1 1	•	3		and the second second
mFC 4	332			Shoulder screw	1	•	3		
mFC 4	333			Spring	1	•	3		

Farts No.	Common Parts No.	Description	Pcs.	Term of sale	Ref.	Remarks
(mFC 4334)		Winding gear	1	•	6	mFC4311K2
pFC 5116-1	mFC 4335	Washer	1 2	•	1	
pFC 5116-2-4	mFC 4335	Vacher	0 to	o ·	. · · · · · · · · · · · · · · · · · · ·	
(mFC 4337)		Washer	0 to 2	••	6	mFC 4311 K2
cFC 4351		Shoulder screw	1	•	3	the second of the second
mFC 4352		Counter	• 1	•	3	and the second second
_ mFC 4353		Counter base	. 1	x•		
mFC 4354K2		Dividing disk assy.	1		3	
- bFC 4354		Dividing disk	1	: x *		
- hFC 4355		Auxiliary dividing disk	1	x*		
-cFC 4356		Pin	· 1	x.		
-eFC 4357		Pin Pin Add Add Add Williams	1	x•		in the second of
hFC 4358		Spring	1	X.		
mFC 4359		Spring	1	•	3	
FC 4379		Screw	3	··· x•.		
mFC 4361		Lever, counter reset	1	• ,	3	
mFC 4362		Shoulder screw	1	. 0	3	
cFC 4363		Flanged screw, ancher	1	•	3	· 原文 编作 · 参 · · · · · · · · · · · · · · · · ·
mFC 4364		Spring	1	• • • •	3	e Branch (1986)
mFC 4365		Stopper	1	• • /	3	
(mFC 4366)		Bearing	1	• •	6	mFC 4311K2
(mFC 4367)		Plate	1	•	6	mFC4311K2
(gFC 4368)		Coupler for speel	• 1	•	. 6	mFC4311K2
(gFC 4369)		Nut opposite	1	•	6	mFC4311K2
3Bs 1.7x3BN		Screw for mFC 4311K2	2	¹⁰ 10 •	. 3	en de la companya de La companya de la co

Parts No.	Common Parts No.	Description	Pcs.	Term of sale	Ref.		Remarks
							•
MFC 4371K2		Lever, counter rese	t assy. 1	•	3.6		A STATE OF THE STA
mFC 4371		Lever, counter rese	t 1 .	0*	6	VK.	
mFC 4372		Gear	1	•	3		
-mFC 4373		Hub	1	0.4	6		
PD 1.7x3		Screw for mFC 4311K	2 1	0	3		
-FC 4375		Boss		•	6		
cFC 4376		Flamged screw		•	3		
2.5Bs1.4x2.5	.	Screw for mFC 4352	1 1 3 1 4 3 1	•	3		
cFC 4378		Spring	. j 1	. 0	3		
(cFC 4379)		Screw	<u>.</u> %. 3	x*			mFC 4354K2
PB1.7x2.5B		Screw for mFC 4365	, 'a a 2	• .	3		
hFC 4381		Friction milled who	•1 1	•	4		
mFC 4382		Shaft, friction whe	el 1	. •	4		
hFC 4383		Gear	1	. • ;	3		
mFC 4384		Spring		•	4		
mFC 4385		Flanged screw, anch	or 1	•	4		. .
mFC 4386K2		Wind stop lever ass	y. 1	•	3.6		
-mFC 4386		Wind stop lever	1	0*	6		
EFC 4387		Pin ()	1	•	6		
eFC 4344	mFC 4388	Shoulder screw		•	3		
cFC 4389		Spring		0	3		
mFC 4391		Slider bar	1	•	3		
cFC 4393		Spring	1	0	3		
mFC 4394		Shoulder screw		•	3		
dFC 4395		Shoulder screw	1	•	3		
■FC 4396		Latch	e e e e e e e e e e e e e e e e e e e	•	3		

	Common Parts No.	Description	Pes.	Term of sale	Ref.	Remarko
mFC 4397		Shoulder screw	1	•	3	
cFC 4398	· · · · · · · · · · · · · · · · · · ·	Spring			3	
=FC 4411K2		Back cover assy.	1		1.8	en e
- mPC 4411		Back cover	1	· ***	3	
			_	_		
-mFC 4414		Light tight strip	1	o•	8	
-mFC 4421		Film pressure plate	-	•	. 8	
FC 4422		Leaf spring	2	•	8	
FC 4423		Nut	2	•	8	
- mFC 4424		Boss	2	0.0	8	
-FC 4425		Scrov	2	•	8	
-mFC 4427		Label, 120,220	1	0.	8	
-EC 4441		Latch cover	1	•	8	
-mFC 4442		Latch	1	••	8	
mFC 4443		Knob	1	•	8	
FC 4444		Spring	1	0*	8	the second of the second
₽FC 4445		Anchor	735 1	•	8	
FC 4-46		Screw	4	.: 	8	
- mFC 4447		Pin	1	• •	8	
-mFC 4448		Hub	1	•	8	
-cFC 4449		Spring	0 to	•	8	
			1			
mFC 4451		Base plate	1	• •	8	
- mFC 4452		Shoulder rivet	2	•	8	
- mFC 4454		Collag	1	•	8	
- mFC 4455		Light tight strip	1	••	8	
-mFC 4456		Disk, 120,220	1	0*	8	
-mFC 4457		Disk window	1	••	8	

Parte No.	Common Parts No.	Description	Pcs.	Term of sale	Ref.	Remarks
-mFC 4458		Click	1	••	ŧ	
- Rm 1.5		Rivet for mFC 4458	2	••	8	
-mFC 4459		Hub	1	••	8	
-mFC 4715	#	Leatherette	1		٤	
aFC 4723		Light tight etrip	3	•	8	
mFC 4511		Front panel	. 1	×	5	
mFC 4512		Plate, bottom cever	1	•	5	
2.5Dal.7x2BN	1	Screw for mFC 4512	3	•	5	
mFC 4514		Frent cover	1	•	5	100 - 110 -
3Cal.7x2Cr		Serew for mFC 4514	2	•	5	i sa
mFC 4516		Bracket	1	•	5	
mFC 4517		Cable release socket	1	•	5	
mFC 4518		Nut	1	•	5	
2.5Bal.7x3 C	· · · · · · · · · · · · · · · · · · ·	Screw for mFC 4516	2		5	
mFC 4521X		Safety lever, lens cate	h 1	•	5	
- mFC 4521		Safety lever	1	x.		
FC 4522		\nchor screw	1	x*		
aFC 4523		Shoulder screw	. 1	•	5	
FC 4524		Spring	1	. . •	5	
mFC 4531		Wire spring, lens catch		•	5	
cFC 4532		knob	1	•	5	
aFC 4533		Clamp	2	•	5	
aFC 4535		Screw	 4	٥	5	
cFC 4536 - 1		Washer	3	•	5	
		Slide assy.	1		5.6	
mFC 4541K2		Slide	- 1	•	6	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
- MFC 4341		32144	_	_		

Parta No.	Common Parts No.	Description	Pcs.	of sale	Ref.	Romarka
mFC 4542		Button	1	•	6	
					6	
-mFC 4543		Shaft-rivet	1	a.		
mFC 4544		Collar	1	••	6	
cFC 4546		Screw	7 1	•	5	
cFC 4547	*	Screw	1	•	5	Test of the second of the seco
cFC 4548		Spring	1.	0	5	
cFC 4549		Shoulder screw anchor	1	•	5	
mFC 4551		Frame	1	0	5	
3Da2x4Cr		Screw for mFC 4551	4	0	5	
mFC 4561K		Large bellows assy.	1	•	5	
-mFC 4561		Large bellows	1	* x*		
-aFC 4562		Front frame	1	x*		
mFC 4563		Rear frame	1	x.		
AFC 4564K		Small bellows assy.	1	•	5	
-aFC 4564		Small bellows	, 1	x*		
arc 4565		Front frame	1	x*		
-aFC 4566		Rear frame) <u>1</u>	* *		
AFC 4567		Screw	10		5	
2.5Dsl.4x2.	5BN1	Screw for aFC 4564K	4	o j	5	
2.5Hel.4x2.		Screw for mFC 4561K	6	•	5	
mFC 4611		Right panel	1		1	
mFC 4617		Distance scale plate	1	•	1	
		(ft)				
mFC 4617		Distance scale plate (m) (1)	•	(1)	
PD 2x3B		Screw for mFC 4611 & 4621K	2 10	• •	1	The state of the s
PD2x5B		Screw for mFC 4611 & 4621K	2 2	• ·	1 .	

Parts No.	Common Parts No.	Description	Pcs.	Term of sale	Ref.	Remarks
mFC 4621K2		Left panel assy.	1		1.8	
		· ·	_			
-mFC 4621		Left panel	1	••	8	
mFC 4622		Window for counter	1	•	. 8	
-mFC 4624		Window for 120,220 file	1	••	8	A STATE OF THE STA
-mFC 4625		Clamp	. 1	0*	8	1000年 1100年 1100年
-mFC 4627		Plate	1.	••	8	
-mFC 4628		Window for 4827	1	•	8	
mFC 4644		Disk and the second	1	••	8	
-mFC 4645		Knob	1	•	8	
-EFC 4647		Diak	1	••	8	
-mPC 4648		Screw And Advantage	1	0*	8	
-4B 1.7x2.5	3	Screw for mFC 4647 Pin for 4647	1	o* .	. 8 8	
-cFC 4649		· LIU IOL 4041	_			
LmFC 4683		Button	. 1	۰•	8	
mFC 4631K2		Knob assy.	. 2	0	4.8	
-mFC 4631		Knob	2	0 *	8	
- mFC 4632		Shaft	2	x.	R	
- oFC 4633		Core for spool holder	2	• •	8	
mFC 4634		Flange Spring	2 2	0.	8 8	
2.5Cs 1.4x1	.5 Cr	Screw for mFC 4617	2	•	1	
3Bs 1.7x3Cr		Screw	6	•	4	
mFC 4651		Right ruck plate	1	•	5	
mFC 4652	· · · · · · · · · · · · · · · · · · ·	Left rack plate	1	•	5	
aFC 4653		Stopper	2	•	5	
mFC 4654		Exposure factor scale	· 4. 1 .		5	
FC 4655		Screw	2	1, 1 ¹ •	5	
FC 4656		Screw	3	. † ●	5	

Parts No.	Common Parts No.	Description	Pcs.	Term of sale	Ref.	Romarks
mFC 4657		Strip for rack plate	0 to	•	5	
mFC 4658		Distance scale plate (curve-line)	1	•	5	
3D 2x4Cr		Serew for mFC 4651 & 465	2 8	•	5	
25Cs 1.4x2.	5Cr	Screw for mFC 4654	1	•	5	
mFC 4661		Focusing knob	2	•	3	
aFC 4662		Nut	2	: 0 ;	3•4	
cFC 4663		Disk	2	•	3.4	
mFC 4664		l'inion shaft	. 1	•	4	
mFC 4665		Pinion shaft bearing	2	•	3.4	
dFC 4668		Synthetic tube	2	0	3.4	the free first see a second
3Bs 1.7x3C		Screw for mFC 4665	4	•	3.4	
SN 149	hFC 4669	Screw	2	•	3.4	
mFC 4671		Guide plate for 4651	1	•	4	
mFC 4672		Guide plate for 4652	1		: 3	
aFC 4673		Brake spring	2	•	3.4	n de la Companya de Companya de la Companya de la Compa
dFC 4674		Brake bar	2	•	3.4	
mFC 4675		Strip for 4671, 4672	0 to	•	3.4	
aFC 4677		Screw	6	•	3.4	
dFC 4678		Hole cover	2	•	3.4	
FC 4655	AFC 4679	Screw	4	•	Ĵ84	
mFC 4681		plate "220 120"	1	•	3	
mFC 4682K2		Slider assy.	1	•	3.8	
-mFC 4682 (mFC 4683	3)	Slider Buttom	1	••	8 8	mFC4621K2
■FC 4684		Shoulder scree	1	•	3	

. . . .

Parte No.	Common Parts No.	Description	Pcs.	Term of sale	Ref.	Romanka
mFC 4685		Lever	1	•	3	
mFC 4686		Shoulder screw	1	•	3	
mFC 4687		Pin	1	•	8	
mFC 4688		Click	1	•	3	and the second s
mFC 4689		Shoulder acrew	1	•	3	
cFC 4712		Leatherette for houd	1	•	7	
cFC 4713		Leatherette for hood end	1	•	7	
cFC 4714		Leatherette for flap	1	•	7	
(mFC 4715)		Leatherette for back	1	0*	8	mFC 44 IIK2
mFC 4716		cover Leatherette for right panel	1	•	1	
mFC 4717		Leatherette for left panel	1	•	1	
cFC 4718		Leatherette for knob	2	•	4	
cFC 4721		Leatherette for focusing	2	•	3.4	
(aFC 4723)		Light tight strip	3	••	8	mFC 4411K2
aFC 4724		Light tight strip	1	•	5	