

Sea-Bird Scientific 13431 NE 20th Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 2107 CALIBRATION DATE: 18-Feb-23 SBE 3 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

COEFFICIENTS:

g = 4.09067895e-003 h = 6.23929151e-004 i = 2.01284338e-005 j = 2.09616018e-006

f0 = 1000.0

BATH TEMP (° C)	INSTRUMENT OUTPUT (Hz)	INST TEMP (° C)	RESIDUAL (° C)
-1.5000	1953.735	-1.4999	0.00012
1.0000	2066.361	0.9999	-0.00011
4.5000	2231.849	4.4999	-0.00014
8.0000	2406.677	8.0000	-0.00003
11.5000	2591.094	11.5001	0.00011
15.0000	2785.347	15.0003	0.00027
18.5000	2989.644	18.4999	-0.00008
22.0000	3204.259	21.9998	-0.00019
25.5000	3429.419	25.4999	-0.00005
29.0000	3665.323	29.0001	0.00007
32.5000	3912.168	32.5000	0.00002

f = Instrument Output (Hz)

Temperature ITS-90 (°C) = $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$

Residual (°C) = instrument temperature - bath temperature

