Sea-Bird Scientific 13431 NE 20th Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 4130 CALIBRATION DATE: 03-Jan-24

SBE 3 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

COEFFICIENTS:

g = 4.40281141e-003 h = 6.48649897e-004 i = 2.40505994e-005 j = 2.22493336e-006

f0 = 1000.0

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (Hz)	(° C)	(° C)
-1.5000	3179.668	-1.5000	0.00002
1.0000	3362.308	0.9999	-0.00005
4.5000	3630.617	4.5000	0.00002
8.0000	3913.998	8.0000	0.00004
11.5000	4212.855	11.5000	-0.00001
15.0000	4527.591	15.0000	-0.00004
18.5000	4858.593	18.5000	0.00000
22.0000	5206.222	22.0000	0.00001
25.5000	5570.838	25.5000	0.00001
29.0000	5952.783	29.0000	0.00001
32.5000	6352.386	32.5000	-0.00001

f = Instrument Output (Hz)

Temperature ITS-90 (°C) = $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$

Residual ($^{\circ}$ C) = instrument temperature - bath temperature

