

Sea-Bird Scientific 13431 NE 20th Street Bellevue, WA 98005 USA +1 425-643-9866 seabird@seabird.com www.seabird.com

SENSOR SERIAL NUMBER: 4130 CALIBRATION DATE: 18-Jan-24 SBE 3 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

COEFFICIENTS:

g = 4.40286038e-003 h = 6.48727438e-004 i = 2.40983035e-005j = 2.23567839e-006

f0 = 1000.0

BATH TEMP	INSTRUMENT	INST TEMP	RESIDUAL
(° C)	OUTPUT (Hz)	(° C)	(° C)
-1.5000	3179.703	-1.5000	0.00003
1.0000	3362.344	1.0000	-0.00002
4.5001	3630.649	4.5000	-0.00008
8.0000	3914.028	8.0000	0.00003
11.5000	4212.889	11.5000	0.00004
15.0000	4527.621	15.0000	-0.00002
18.5000	4858.623	18.5000	0.00004
22.0000	5206.245	22.0000	0.00000
25.5000	5570.854	25.5000	-0.00002
29.0001	5952.800	29.0000	-0.00008
32.5000	6352.402	32.5001	0.00006

f = Instrument Output (Hz)

Temperature ITS-90 (°C) = $1/\{g + h[ln(f0/f)] + i[ln^2(f0/f)] + j[ln^3(f0/f)]\} - 273.15$

Residual ($^{\circ}$ C) = instrument temperature - bath temperature

