




- 2. solder
- 3. component
- 4. componentmask
- 5. soldermask
- 6. plated-drill
- 7. unplated-drill
- 8. topsilk
- 9. bottomsilk
- 10. toppaste
- 11. topassembly
- 12. bottomassembly
- 13. fab





























There are 6 different drill sizes used in this layout, 135 holes total Symbol Diam. (Inch) Count Plated? Y 0.028 68 YES Y 0.028 53 YES Title: (unknown) - Fabrication Drawing N 0.038 53 YES Ruthor: Revin RRYMOND Particular States N Pressure of the States of the Sta	+ + × × × × × × × × × × × × × × × × × ×	Board outline is the centerline of this 18 ml rectangle - 6,8 to 5880,5888 mils
(null), fab, scale = 1:1.000 /user/kraymond/Recepted	ı) ır.pcb	