VC1 SP, MP and AP (Progressive Only) Decoder on DM365 Version 01.00.00

Release Notes

September 2010

Build ID: 01.00.00.06

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issues

New In This Release

• None

Validation Information

Release Configuration	Description	Validation Platform
VC1_DEC_01	VC1 SP, MP and AP (Progressive Only) Decoder on DM365 EVM	DM365 EVM [Datasheet] [User Guide]

This release is validated on the following:

- DM365 EVM on Linux
 - Framework components Version 2.24.01.06
 - XDC tools version 3.15.00.12
 - MVL tool chain 5.0
 - BIOS version 5.32.00.02
 - LSP version 02.10.00.08



Fixed In This Release

Defect ID	Description	Release Configuration
SDOCM00069306	VC1 Decoder Extended parameters test with, video_res=352x288,bit_rate=1000000, outloopDeblocking=1 failed	VC1_DEC_01
SDOCM00069197	DM365 - DVSDKv3.10: VC1 decoder buffer size requirement not correct.	VC1_DEC_01
	Sample test application on linux does not release all resources allocated to it	VC1_DEC_01

Known Issues

• None



VC1 SP, MP and AP (Progressive Only) Decoder on DM365 Version 01.00.00

Release Notes

December 2009

Build ID: 01.00.00.04

The release note is divided into the following sections:

- New In This Release
- Validation Information
- Fixed In This Release
- Known Issues

New In This Release

• First release of VC1 decoder on DM365

Validation Information

Release Configuration	Description	Validation Platform
VC1_DEC_01	VC1 SP, MP and AP (Progressive Only) Decoder on DM365 EVM	DM365 EVM [Datasheet] [User Guide]

This release is validated on the following:

- DM365 EVM on Linux
 - Framework components Version 2.24.01.06
 - XDC tools version 3.15.00.12
 - MVL tool chain 5.0
 - BIOS version 5.32.00.02
 - LSP version 02.10.00.08



Fixed In This Release

• None

Known Issues

None

