
HAZARD
Flammable liquid transfer
THREAT
Hose rupture
BARRIER
Pre-transfer hose inspection
Effectiveness: Effective · Transfer operator · Inspect transfer hose · Action: Improve inspection lighting
ESCALATION FACTOR
Poor lighting
BARRIER
Portable inspection light
TOP EVENT
Loss of containment
THREAT
Tank overfill during transfer
BARRIER
High-level trip
BARRIER
Emergency isolation
CONSEQUENCE
Pool fire
Action: A-02
BARRIER
Bund containment
CONSEQUENCE
Environmental release