



Residential Equipment Guide

V11.05.25



SCAN ME



The AC Pro Difference

The AC Pro Difference was born out of a sense of responsibility and a great desire to help your business thrive and grow. Our commitment to add value beyond the sale is what drives us to continually create services and resources that are easy to use and specific to your needs, and tailored to growing your business. Please ask your territory manager how we can put these resources to work for you today!



Truck Stock Management

Using our inventory management solution, you are capable of keeping track and replenishing your truck stock or warehouse inventory with the ease and simplicity of a scan of a bar code.



Technical Training

We offer free training to our contractors to keep them up to date on the newest information in the HVAC industry. The majority of our training classes qualify for NATE Continuing Education Accreditation credits.



Free Tech Support

Accelerate troubleshooting with experts on-call to help find the best solution. Call our tech support line on the job:

Monday - Friday from 7 am - 5 pm

Saturday from 7 am - 11 am

Call now 855.972.2776



Instant Warranty

Warrantied items can add up, and before you know it you have a pile of warrantied items sitting around your office or still in your truck.

AC Pro has one of the easiest warranty programs, simply bring it in and we will instantly provide a credit to your account.

Consignment

You're in full control, we'll help you set up inventory in your building, and you or your staff will manage the inventory. We have custom solutions to meet your needs and budget.

Free Local Delivery near our branches & no minimum

AC Pro has trucks running daily throughout Southern California, Nevada and Arizona. Utilize this free resource to have the parts, supplies and equipment delivered to you, no matter the size of the order. Simply tell us when you need it delivered and our team will work with your schedule.



Free After hours 888.674.4822

Will call locations are available for after-hours calls on an availability basis. After-hours are:

Monday-Friday: 5pm until 8 pm
Saturday: 11 am until 5 pm
Sunday: 8 am until 5 pm

Free drop-off for change-out units and job trash

HOURS:

MON - FRI 6 AM - 5 PM

SAT 7 AM - 11AM

*Unavailable Christmas day



2025 Energy Efficiency Home Improvement Tax Credit (25C)

**Beginning January 1, 2023 through December 21, 2032 consumers
are eligible for the following Tax Credit:**

- Up to \$600 for qualified air conditioners and gas furnaces with an annual cap of \$1,200 limit per household*
- Up to \$2,000 for qualified heat pumps*

* Qualifications are based on the highest CEE tier (not advanced tier) at the start of each year.

25C Tax Credit Requirements for 2025

2025 25C Tax Credit - Based on 2025 CEE Tiers				
Product	SEER2	EER2	HSPF2	COP at 5° F
Air Conditioners - Split	17	12		
Air Conditioners - Package Unit	16	11.5		
Heat Pump - Split (Path B - cooling dominate use and dual fuel installs)	16	11	8	1.75
Heat Pump - Package Unit	15.2	10	7.2	1.75
Heat Pump - Cold Climate Split/Package	16	11	8.5	2.1-2.4

CEE Tiers for 2025 only.

Any credit amounts or product types included in this and other supporting documents are intended as references only. Tax credit levels may change throughout the life of the program. Check with your tax professional for further/specific product and eligibility details. We reserve the right to correct any clerical errors.

1.5 Ton M-Series

SPAC-M-1018BB



Specs

Width	23.63
Depth	23.63
Height	24.94
Suction	3/4
Liquid	3/8
Stages	1
Amps - Min/Max	11.4/19.89
dB Rating	73

Features

High quality condenser with innergroove copper tube and aluminum fin.

Warranty

10 Year Parts
10 Year Compressor

Product Information

AC Pro Part #	83887
Condenser Cost	\$1,168.50

80% 1-Stage Variable

FURN-M-L1A40V12A



Warranty:
10 Year Parts
1 Year Heat Exchanger

BTUs 40k

Width 14.5

Depth 28.5

Height 33.75

AC Pro Part # 83933

Furnace Cost \$847.16

↓ Choose A Coil ↓

Multi-Position

COIL-M-03036AMTB



W 14.5
D 21
H 20

AC Pro Part # 83912

AHRI # 216623606

SEER2/EER2 15.2/12

Coil Cost \$500.00

Complete System \$2,515.66

↓ Choose A Coil ↓

Multi-Position

COIL-M-03036BMTB



W 17.50
D 21
H 30.00

AC Pro Part # 83913

AHRI # 216623651

SEER2/EER2 15.2/12

Coil Cost \$524.64

Complete System \$3,173.74

2 Ton M-Series

SPAC-M-1024BB



Specs

Width	28
Depth	28
Height	24.94
Suction	3/4
Liquid	3/8
Stages	1
Amps - Min/Max	15.3/26.5
dB Rating	75

Features

High quality condenser with innergroove copper tube and aluminum fin.

Warranty

10 Year Parts
10 Year Compressor

Product Information

AC Pro Part #	83890
Condenser Cost	\$1,243.94

80% 1-Stage Variable

FURN-M-L1A60V12A



Warranty:
10 Year Parts
1 Year Heat Exchanger

BTUs 60k

Width 14.5

Depth 28.5

Height 33.75

AC Pro Part # 85054

Furnace Cost \$816.42

↓ Choose A Coil ↓

Multi-Position

COIL-M-03036AMTB



W 14.5
D 21
H 20

AC Pro Part # 83912

AHRI # 216623610

SEER2/EER2 14.3/11.7

Coil Cost \$500.00

Complete System \$2,560.36



96% 2-Stage Variable

FURN-M-R2B60V12A

Warranty:
10 Year Parts
1 Year Heat Exchanger

BTUs 60k

Width 17.5

Depth 28.75

Height 33.75

AC Pro Part # 85057

Furnace Cost \$1,480.60

↓ Choose A Coil ↓

Multi-Position

COIL-M-03036BMTB



W 17.50
D 21
H 30.00

AC Pro Part # 83913

AHRI # 216623654

SEER2/EER2 14.3/11.7

Coil Cost \$524.64

Complete System \$3,249.18

2025 25C Tax Credit criteria for AC Split systems is 17/12 SEER2/EER2.

Energy Star Certification criteria for AC Split systems is 15.2/12 SEER2/EER2

2.5 Ton M-Series

SPAC-M-1030BB



Specs

Width	28
Depth	28
Height	33.19
Suction	3/4
Liquid	3/8
Stages	1
Amps - Min/Max	16.4/28.4
dB Rating	75

Features

High quality condenser with innergroove copper tube and aluminum fin.

Warranty

10 Year Parts
10 Year Compressor

Product Information

AC Pro Part #	83891
Condenser Cost	\$1,389.79

80% 1-Stage Variable FURN-M-L1A60V12A



Warranty:
10 Year Parts
1 Year Heat Exchanger

BTUs 60k

Width 14.5

Depth 28.5

Height 33.75

AC Pro Part # 85054

Furnace Cost \$816.42

↓ Choose A Coil ↓

Multi-Position COIL-M-03036AMTB



W 14.5
D 21
H 20

AC Pro Part # 83912

AHRI # 216623611

SEER2/EER2 14.3/11.7

Coil Cost \$500.00

Complete System \$2,706.21

↓ Choose A Coil ↓

96% 2-Stage Variable FURN-M-R2B60V12A



Warranty:
10 Year Parts
1 Year Heat Exchanger

BTUs 60k

Width 17.5

Depth 28.75

Height 33.75

AC Pro Part # 85057

Furnace Cost \$1,480.60

↓ Choose A Coil ↓

Multi-Position COIL-M-03036BMTB



W 17.50
D 21
H 30.00

AC Pro Part # 83913

AHRI # 216623657

SEER2/EER2 15.2/12

Coil Cost \$524.64

Complete System \$3,395.03

3 Ton M-Series

SPAC-M-1036BB



Specs

Width	29.13
Depth	29.13
Height	24.94
Suction	3/4
Liquid	3/8
Stages	1
Amps - Min/Max	21.9/38.2
dB Rating	77

Features

High quality condenser with innergroove copper tube and aluminum fin.

Warranty

10 Year Parts
10 Year Compressor

Product Information

AC Pro Part #	83892
Condenser Cost	\$1,512.17

80% 1-Stage Variable FURN-M-L1B80V16A



Warranty:
10 Year Parts
1 Year Heat Exchanger

BTUs 80k

Width 17.5

Depth 28.5

Height 33.75

AC Pro Part # 85055

Furnace Cost \$929.85

↓ Choose A Coil ↓

Multi-Position COIL-M-03036BMTB



W 17.50
D 21
H 30.00

AC Pro Part # 83913

AHRI # 216623624

SEER2/EER2 14.3/11.7

Coil Cost \$524.64

Complete System \$2,966.66

96% 2-Stage Variable FURN-M-R2B80V12A



Warranty:
10 Year Parts
1 Year Heat Exchanger

BTUs 80k

Width 17.5

Depth 28.75

Height 33.75

AC Pro Part # 83935

Furnace Cost \$1,633.43

↓ Choose A Coil ↓

Multi-Position COIL-M-03036BMTB



W 17.50
D 21
H 30.00

AC Pro Part # 83913

AHRI # 216623660

SEER2/EER2 14.3/11.7

Coil Cost \$524.64

Complete System \$3,670.24

2025 25C Tax Credit criteria for AC Split systems is 17/12 SEER2/EER2.

Energy Star Certification criteria for AC Split systems is 15.2/12 SEER2/EER2

3.5 Ton M-Series

SPAC-M-1042BB



Specs

Width	29.13
Depth	29.13
Height	33.19
Suction	7/8
Liquid	3/8
Stages	1
Amps - Min/Max	24.5/42.6
dB Rating	78

Features

High quality condenser with innergroove copper tube and aluminum fin.

Warranty

10 Year Parts
10 Year Compressor

Product Information

AC Pro Part # 83893
Condenser Cost \$1,830.70

80% 1-Stage Variable

FURN-M-L1B80V16A



Warranty:
10 Year Parts
1 Year Heat Exchanger

BTUs 80k

Width 17.5

Depth 28.5

Height 33.75

AC Pro Part # 85055

Furnace Cost \$929.85

↓ Choose A Coil ↓

Multi-Position

COIL-M-04248BMTB



W 17.5
D 21
H 30

AC Pro Part # 83914

AHRI # 216623626

SEER2/EER2 14.3/11.7

Coil Cost \$586.96

Complete System \$3,347.51

BTUs 80k

Width 17.5

Depth 28.75

Height 33.75

AC Pro Part # 83935

Furnace Cost \$1,633.43

↓ Choose A Coil ↓

Multi-Position

COIL-M-04248BMTB



W 17.5
D 21
H 30

AC Pro Part # 83914

AHRI # 216623662

SEER2/EER2 14.3/11.7

Coil Cost \$586.96

Complete System \$4,051.09

4 Ton M-Series

SPAC-M-1048BB



Specs

Width	28
Depth	28
Height	33.19
Suction	7/8
Liquid	3/8
Stages	1
Amps - Min/Max	28.3/49.3
dB Rating	78

Features

High quality condenser with innergroove copper tube and aluminum fin.

Warranty

10 Year Parts
10 Year Compressor

Product Information

AC Pro Part # 83894
Condenser Cost \$1,879.33

80% 1-Stage Variable

FURN-M-L1B80V16A



Warranty:
10 Year Parts
1 Year Heat Exchanger

BTUs 80k

Width 17.5

Depth 28.5

Height 33.75

AC Pro Part # 85055

Furnace Cost \$929.85

↓ Choose A Coil ↓

Multi-Position

COIL-M-04248BMTB



W 17.5
D 21
H 30

AC Pro Part # 83914

AHRI # 216623627

SEER2/EER2 14.3/11.7

Coil Cost \$586.96

Complete System \$3,396.14

BTUs 80k

Width 17.5

Depth 28.75

Height 33.75

AC Pro Part # 83935

Furnace Cost \$1,633.43

↓ Choose A Coil ↓

Multi-Position

COIL-M-04248BMTB



W 17.5
D 21
H 30

AC Pro Part # 83914

AHRI # 216623663

SEER2/EER2 14.3/11.7

Coil Cost \$586.96

Complete System \$4,099.72

2025 25C Tax Credit criteria for AC Split systems is 17/12 SEER2/EER2.

Energy Star Certification criteria for AC Split systems is 15.2/12 SEER2/EER2

5 Ton M-Series

SPAC-M-1060BB



Specs

Width	29.13
Depth	29.13
Height	33.19
Suction	1-1/8
Liquid	3/8
Stages	1
Amps - Min/Max	36.8/64.5
dB Rating	80

Features

High quality condenser with innergroove copper tube and aluminum fin.

Warranty

10 Year Parts
10 Year Compressor

Product Information

AC Pro Part #	83895
Condenser Cost	\$2,031.88

80% 1-Stage Variable

FURN-M-L1C100V20A



Warranty:
10 Year Parts
1 Year Heat Exchanger

BTUs	100k
Width	21
Depth	28.5
Height	33.75
AC Pro Part #	85056
Furnace Cost	\$1,068.65

↓ Choose A Coil ↓

Multi-Position

COIL-M-04860CMTB



W 21
D 21
H 30

AC Pro Part #	83915
AHRI #	216623641
SEER2/EER2	13.8/11.2
Coil Cost	\$724.64
Complete System \$3,825.17	

↓ Choose A Coil ↓

Multi-Position

COIL-M-04860CMTB



W 21
D 21
H 30

AC Pro Part #	83915
AHRI #	216623693
SEER2/EER2	13.8/11.2
Coil Cost	\$724.64
Complete System \$4,468.46	

2025 25C Tax Credit criteria for AC Split systems is 17/12 SEER2/EER2.

Energy Star Certification criteria for AC Split systems is 15.2/12 SEER2/EER2

M-Series 14.3 SEER2 Heat Pump R454B

1.5 Ton 15.2 SEER2 SPHP-M-1018BB	
Warranty 10 Year Parts 10 Year Compressor	
Width	23.7
Depth	23.7
Height	25
Suction	3/4
Liquid	3/8
Amp	11.4/19.9
dB Rating	73
AC Pro Part #	83897
HP Cost	\$1,585.94

2.0 Ton 15.2 SEER2 SPHP-M-1024BB	
Warranty 10 Year Parts 10 Year Compressor	
Width	28
Depth	28
Height	25
Suction	3/4
Liquid	3/8
Amp	15.3/26.5
dB Rating	75
AC Pro Part #	83898
HP Cost	\$1,668.10

2.5 Ton 15.2 SEER2 SPHP-M-1030BB	
Warranty 10 Year Parts 10 Year Compressor	
Width	28
Depth	28
Height	33.2
Suction	3/4
Liquid	3/8
Amp	16.4/28.4
dB Rating	75
AC Pro Part #	83899
HP Cost	\$1,721.74

3.0 Ton 15.2 SEER2 SPHP-M-1036BB	
Warranty 10 Year Parts 10 Year Compressor	
Width	29.2
Depth	29.2
Height	25
Suction	3/4
Liquid	3/8
Amp	21.9/38.3
dB Rating	77
AC Pro Part #	83900
HP Cost	\$1,973.20

Air Handler AIRH-M-1018108B	
W 18.13	
D 20.5	
H 41.38	
AC Pro Part #	83916
AHRI #	215853854
SEER2/EER2/HSPF2	14.3/11.7/7.5
Air Handler Cost	\$794.59
Complete System	\$2,380.53

Air Handler AIRH-M-1024108B	
W 19.63	
D 21.63	
H 46.5	
AC Pro Part #	83917
AHRI #	215853784
SEER2/EER2/HSPF2	14.3/11.7/7.5
Air Handler Cost	\$840.54
Complete System	\$2,508.64

Air Handler AIRH-M-1024108B	
W 19.63	
D 21.63	
H 46.5	
AC Pro Part #	83917
AHRI #	215853797
SEER2/EER2/HSPF2	14.3/11.7/7.5
Air Handler Cost	\$840.54
Complete System	\$2,562.28

Air Handler AIRH-M-1036112B	
W 19.63	
D 21.63	
H 46.5	
AC Pro Part #	83918
AHRI #	215853812
SEER2/EER2/HSPF2	14.3/11.7/7.5
Air Handler Cost	\$931.08
Complete System	\$2,904.28

3.5 Ton 15.2 SEER2 SPHP-M-1042BB	
Warranty 10 Year Parts 10 Year Compressor	
Width	29.2
Depth	29.2
Height	33.2
Suction	7/8
Liquid	3/8
Amp	24.5/42.6
dB Rating	78
AC Pro Part #	83901
HP Cost	\$2,109.00

4.0 Ton 15.2 SEER2 SPHP-M-1048BB	
Warranty 10 Year Parts 10 Year Compressor	
Width	28
Depth	28
Height	33.2
Suction	7/8
Liquid	3/8
Amp	28.3/49.3
dB Rating	78
AC Pro Part #	83902
HP Cost	\$2,177.73

5.0 Ton 14.3 SEER2 SPHP-M-1060BB	
Warranty 10 Year Parts 10 Year Compressor	
Width	29.2
Depth	29.2
Height	33.2
Suction	7/8
Liquid	3/8
Amp	36.8/64.5
dB Rating	80
AC Pro Part #	83903
HP Cost	\$2,427.53

Air Handler AIRH-M-1060120B	
W 22	
D 24	
H 51.5	
AC Pro Part #	83920
AHRI #	215853834
SEER2/EER2/HSPF2	14.3/11.7/7.5
Air Handler Cost	\$1,122.97
Complete System	\$3,231.97

Air Handler AIRH-M-1048116B	
W 22	
D 24	
H 51.5	
AC Pro Part #	83919
AHRI #	215853844
SEER2/EER2/HSPF2	14.3/11.7/7.5
Air Handler Cost	\$1,122.97
Complete System	\$3,300.70

Variable Air Handler AIRH-M-1060E20B	
W 22	
D 24	
H 54.5	
AC Pro Part #	83924
AHRI #	215853853
SEER2/EER2/HSPF2	14.3/11.7/7.5
Air Handler Cost	\$1,491.89
Complete System	\$3,919.42

2025 25C Tax Credit criteria for HP Split systems is 16/11/8/1.75 SEER2/EER2/HSPF2/COP
 Energy Star Certification criteria for HP Split systems is 15.2/11/7.8 SEER2/EER2/HSPF2

M-Series 14.3-15.2 SEER2 Heat Pump R454B

1.5 Ton 15.2 SEER2 SPHP-M-1018BB		2.0 Ton 15.2 SEER2 SPHP-M-1024BB		2.5 Ton 15.2 SEER2 SPHP-M-1030BB		3.0 Ton 15.2 SEER2 SPHP-M-1036BB	
	Warranty 10 Year Parts 10 Year Compressor		Warranty 10 Year Parts 10 Year Compressor		Warranty 10 Year Parts 10 Year Compressor		Warranty 10 Year Parts 10 Year Compressor
Width	23.7	Width	28	Width	28	Width	29.2
Depth	23.7	Depth	28	Depth	28	Depth	29.2
Height	25	Height	25	Height	33.2	Height	25
Suction	3/4	Suction	3/4	Suction	3/4	Suction	3/4
Liquid	3/8	Liquid	3/8	Liquid	3/8	Liquid	3/8
Amp	11.4/19.9	Amp	15.3/26.5	Amp	16.4/28.4	Amp	21.9/38.3
dB Rating	73	dB Rating	75	dB Rating	75	dB Rating	77
AC Pro Part #	83897	AC Pro Part #	83898	AC Pro Part #	83899	AC Pro Part #	83900
HP Cost	\$1,585.94	HP Cost	\$1,668.10	HP Cost	\$1,721.74	HP Cost	\$1,973.20

Variable Air Handler AIRH-M-1024E08B		Variable Air Handler AIRH-M-1024E08B		Variable Air Handler AIRH-M-1036E12B		Variable Air Handler AIRH-M-1048E16B	
	W 18.13		W 18.13		W 19.63		W 22
	D 20.5		D 20.5		D 21.63		D 24
	H 41.38		H 41.38		H 46.5		H 54.5
AC Pro Part #	83921	AC Pro Part #	83921	AC Pro Part #	83922	AC Pro Part #	83923
AHRI #	215853761	AHRI #	215853763	AHRI #	215853765	AHRI #	215853769
SEER2/EER2/HSPF2	15.2/12/7.8	SEER2/EER2/HSPF2	15.2/12/7.8	SEER2/EER2/HSPF2	15.2/12/7.8	SEER2/EER2/HSPF2	15.2/12/7.8
Air Handler Cost	\$1,186.49	Air Handler Cost	\$1,186.49	Air Handler Cost	\$1,285.95	Air Handler Cost	\$1,491.89
Complete System	\$2,772.43	Complete System	\$2,854.59	Complete System	\$3,007.69	Complete System	\$3,465.09

3.5 Ton 15.2 SEER2 SPHP-M-1042BB		4.0 Ton 15.2 SEER2 SPHP-M-1048BB		5.0 Ton 14.3 SEER2 SPHP-M-1060BB	
	Warranty 10 Year Parts 10 Year Compressor		Warranty 10 Year Parts 10 Year Compressor		Warranty 10 Year Parts 10 Year Compressor
Width	29.2	Width	28	Width	29.2
Depth	29.2	Depth	28	Depth	29.2
Height	33.2	Height	33.2	Height	33.2
Suction	7/8	Suction	7/8	Suction	7/8
Liquid	3/8	Liquid	3/8	Liquid	3/8
Amp	24.5/42.6	Amp	28.3/49.3	Amp	36.8/64.5
dB Rating	78	dB Rating	78	dB Rating	80
AC Pro Part #	83901	AC Pro Part #	83902	AC Pro Part #	83903
HP Cost	\$2,109.00	HP Cost	\$2,177.73	HP Cost	\$2,427.53

Variable Air Handler AIRH-M-1048E16B		Variable Air Handler AIRH-M-1048E16B		Variable Air Handler AIRH-M-1060E20B	
	W 22		W 22		W 22
	D 24		D 24		D 24
	H 54.5		H 54.5		H 54.5
AC Pro Part #	83923	AC Pro Part #	83923	AC Pro Part #	83924
AHRI #	215853771	AHRI #	215853773	AHRI #	215853757
SEER2/EER2/HSPF2	15.2/12/7.8	SEER2/EER2/HSPF2	15.2/12/7.8	SEER2/EER2/HSPF2	14.3/11.7/7.5
Air Handler Cost	\$1,491.89	Air Handler Cost	\$1,491.89	Air Handler Cost	\$1,491.89
Complete System	\$3,600.89	Complete System	\$3,669.62	Complete System	\$3,919.42

2025 25C Tax Credit criteria for HP Split systems is 16/11/8/1.75 SEER2/EER2/HSPF2/COP
 Energy Star Certification criteria for HP Split systems is 15.2/11/7.8 SEER2/EER2/HSPF2

AC Pro M-Series with CoreFAU 1.5-3 Ton

1.5 Ton SPHP-M-1018BB		2.0 Ton SPHP-M-1024BB		2.5 Ton SPHP-M-1030BB		3.0 Ton SPHP-M-1036BB	
Warranty 10 Year Parts 10 Year Compressor							
Width	23.7	Width	28	Width	28	Width	29.2
Depth	23.7	Depth	28	Depth	28	Depth	29.2
Height	25	Height	25	Height	33.2	Height	25
Suction	3/4	Suction	3/4	Suction	3/4	Suction	3/4
Liquid	3/8	Liquid	3/8	Liquid	3/8	Liquid	3/8
Amp	11.4/19.9	Amp	15.3/26.5	Amp	16.4/28.4	Amp	21.9/38.3
dB Rating	73	dB Rating	75	dB Rating	75	dB Rating	77
AC Pro Part #	83897	AC Pro Part #	83898	AC Pro Part #	83899	AC Pro Part #	83900
HP Cost	\$1,585.94	HP Cost	\$1,668.10	HP Cost	\$1,721.74	HP Cost	\$1,973.20

Air Handler CORE-M-1A14A		Air Handler CORE-M-1A14A		Air Handler CORE-M-1A14A		Air Handler CORE-M-1B16A	
	W 14.5 D 28.75 H 33.75		W 14.5 D 28.75 H 33.75		W 14.5 D 28.75 H 33.75		W 17.5 D 28.75 H 33.75
AC Pro Part #	83428	AC Pro Part #	83428	AC Pro Part #	83428	AC Pro Part #	83429
Air Handler Cost	\$617.65	Air Handler Cost	\$617.65	Air Handler Cost	\$617.65	Air Handler Cost	\$644.65

Multi-Position COIL-M-03036AMTB		Multi-Position COIL-M-03036AMTB		Multi-Position COIL-M-03036AMTB		Multi-Position COIL-M-03036BMTB	
	W 14.5 D 21 H 20		W 14.5 D 21 H 20		W 14.5 D 21 H 20		W 17.50 D 21 H 30.00
AC Pro Part #	83912	AC Pro Part #	83912	AC Pro Part #	83912	AC Pro Part #	83913
AHRI #	217231773	AHRI #	217231776	AHRI #	217231779	AHRI #	217231782
SEER2/EER2	14.3/11.7	SEER2/EER2	14.3/11.7	SEER2/EER2	14.3/11.7	SEER2/EER2	14.3/11.7
Coil Cost	\$500.00	Coil Cost	\$500.00	Coil Cost	\$500.00	Coil Cost	\$524.64
Complete System	\$2,703.59	Complete System	\$2,785.75	Complete System	\$2,839.39	Complete System	\$3,142.49

2025 25C Tax Credit criteria for HP Split systems is 16/11/8/1.75 SEER2/EER2/HSPF2/COP

Energy Star Certification criteria for HP Split systems is 15.2/11/7.8 SEER2/EER2/HSPF2

AC Pro M-Series with CoreFAU 3.5-4 Ton

3.5 Ton SPHP-M-1042BB		4.0 Ton SPHP-M-1048BB	5 Ton rated system unavailable
Warranty	10 Year Parts 10 Year Compressor	Warranty	10 Year Parts 10 Year Compressor
Width	29.2	Width	28
Depth	29.2	Depth	28
Height	33.2	Height	33.2
Suction	7/8	Suction	7/8
Liquid	3/8	Liquid	3/8
Amp	24.5/42.6	Amp	28.3/49.3
dB Rating	78	dB Rating	78
AC Pro Part #	83901	AC Pro Part #	83902
HP Cost	\$2,109.00	HP Cost	\$2,177.73

Air Handler CORE-M-1B16A		Air Handler CORE-M-1C20A	
	W 17.5		W 21
	D 28.75		D 28.75
	H 33.75		H 33.75
AC Pro Part #	83429	AC Pro Part #	83430
Air Handler Cost	\$644.65	Air Handler Cost	\$699.14

Multi-Position COIL-M-04248BMTB		Multi-Position COIL-M-04860CMTB	
	W 17.5		W 21
	D 21		D 21
	H 30		H 30
AC Pro Part #	83914	AC Pro Part #	83915
AHRI #	217231770	AHRI #	217231772
SEER2/EER2	14.3/11.7	SEER2/EER2	14.3/11.7
Coil Cost	\$586.96	Coil Cost	\$724.64
Complete System	\$3,340.61	Complete System	\$3,601.51

2025 25C Tax Credit criteria for HP Split systems is 16/11/8/1.75 SEER2/EER2/HSPF2/COP
 Energy Star Certification criteria for HP Split systems is 15.2/11/7.8 SEER2/EER2/HSPF2

AC Pro Gas/Electric Package Units



10 Year Parts Warranty
10 Year Compressor

AC Pro M-Series 13.4 SEER2 Gas/Electric R454B

Model	Size	Cooling BTUs	Heating BTUs	AMP	SEER2	EER2	AHRI	W	L	H	Cost
PKGE-M-024L1060BB	2.0 Ton	24K	60k	18.8/25	13.4	11.0	214303036	50.7	46.5	35.1	\$2,771.62
PKGE-M-030L1060BB	2.5 Ton	30K	60k	21.5/30	13.4	11.0	214303039	50.7	46.5	35.1	\$2,886.49
PKGE-M-036L1090BB	3.0 Ton	36K	90k	25.2/40	13.4	11.0	214303041	50.7	46.5	35.1	\$3,118.92
PKGE-M-042L1090BB	3.5 Ton	42K	90k	29.9/45	13.4	11.0	214303041	51.6	49.75	44.8	\$3,375.68
PKGE-M-048L1090BB	4.0 Ton	48K	90	36.4/50	13.4	11.0	214303037	51.6	49.75	44.8	\$3,387.84
PKGE-M-060L1090BB	5.0 Ton	60K	90k	41.4/60	13.4	11.0	214303038	51.6	49.75	44.8	\$4,259.46
PKGE-M-060L1110BB	5.0 Ton	60K	110k	41.4/60	13.4	11.0	214303038	51.6	49.75	44.8	\$4,036.49

2025 25C Tax Credit criteria for AC Package Units is 16/11.5 SEER2/EER2
Energy Star Certification criteria for AC Package Units is 15.2/11.5 SEER2/EER2

AC Pro Heat Pump Package Units



10 Year Parts Warranty
10 Year Compressor

AC Pro M-Series 13.4 SEER2 R454B

Model	Size	Cooling BTUs	Heating BTUs	AMP	SEER2	EER2	HSPF	AHRI	W	L	H	Cost
PKHP-M-0241BB	2.0 Ton	22K	22K	18/25	13.4	11.0	6.7	216619261	50.8	35.1	46.7	\$2,923.48
PKHP-M-0361BB	3.0 Ton	34K	34K	28/35	13.4	11.0	6.7	216619263	50.8	35.1	46.7	\$3,095.65
PKHP-M-0481BB	4.0 Ton	46K	46K	34/45	13.4	11.0	6.7	216619265	51.6	44.8	51.5	\$3,810.43
PKHP-M-0601BB	5.0 Ton	56K	57K	43/50	13.4	11.0	6.7	216619266	51.6	44.8	51.5	\$4,088.69
PKHP-M-0601CB	5.0 Ton 3-Phase	55K	57K	29/40	13.4	11.0	6.7	216619267	51.6	44.8	51.5	\$4,309.57



10 Year Parts Warranty
10 Year Compressor

AC Pro P-Series Horizontal Discharge 13.4 SEER2 R454B

Model	Size	Cooling BTUs	Heating BTUs	AMP	SEER2	EER2	HSPF	AHRI	W	L	H	Cost
PKHP-P-0241BB	2	22K	22K	18/25	13.4	11.0	6.7	216619255	37.75	52	24.8	\$2,260.59
PKHP-P-0301BB	2.5	28K	28K	24/30	13.4	11.0	6.7	216619256	37.75	52	24.8	\$2,731.76
PKHP-P-0361BB	3	34K	34K	27/35	13.4	11.2	6.7	216619257	37.75	52	24.8	\$2,786.47
PKHP-P-0421BB	3.5	40K	40K	30/40	13.4	11.2	6.7	216619258	42.1	58.5	33.1	\$3,202.94
PKHP-P-0481BB	4	46K	46K	36/45	13.4	11.4	6.7	216619259	42.1	58.5	33.1	\$3,624.70
PKHP-P-0601BB	5	56K	48.6/60	13.4	11.0	6.7		216619260	42.1	58.5	33.1	\$3,852.35

2025 25C Tax Credit criteria for HP Package Units is 15.2/10/7.2/1.75 SEER2/EER2/HSPF2/COP

Energy Star Certification criteria for HP Package Units is 15.2/10/7.2 SEER2/EER2/HSPF2

Furnace Sheet

AC Pro M-Series 80% Single Stage Non-Variable

Furnace Model	W	D	H	BTUs	Size	Part #	Cost
FURN-M-L1A40V12A	14.5	28.5	33.75	40k	2T	83933	\$847.16
FURN-M-L1A60V12A	14.5	28.5	33.75	60k	3-4T	85054	\$816.42
FURN-M-L1B80V16A	17.5	28.5	33.75	80k	4-5T	85055	\$929.85
FURN-M-L1C100V20A	21	28.5	33.75	100k	5T	85056	\$1,068.65



AC Pro M-Series 96% Two Stage Variable

Furnace Model	W	D	H	BTUs	Size	Part #	Cost
FURN-M-R2B60V12A	17.5	28.75	33.75	60k	3-4T	85057	\$1,480.60
FURN-M-R2B80V12A	17.5	28.75	33.75	80k	4-5T	83935	\$1,633.43
FURN-M-R2C80V16A	21	28.75	33.75	80k	4-5T	85058	\$1,659.70
FURN-M-R2C100V20A	21	28.75	33.75	100k	5T	85059	\$1,711.94



Warranty:
10 Year Parts
1 Year
Heat Exchanger

Furnace Sheet

AC Pro N-Series 80% Single Stage Non-Variable

Furnace Model	W	D	H	BTUs	Size	Part #	Cost
FG7SA-045CT23A2	14.5	28	34.5	45K	2-3T	85388	824.10
FG7SA-054CT23A2	14.5	28	34.5	54K	2-3T	85389	802.33
FG7SA072CT24B2	17.5	28	34.5	72K	3T	85390	854.22
FG7SA090CT35C2	21	28	34.5	90K	4T	85391	892.15
FG7SA108CT35C2	21	28	34.5	108K	5T	85392	1011.90



Warranty:
10 Year Parts

10 Year
Dependability

Lifetime Heat
Exchanger
(FG7 models)

AC Pro N-Series 80% Two Stage Non-Variable

Furnace Model	W	D	H	BTUs	Size	Part #	Cost
FG7TA080CV24BP	17.5	28	34.5	80K	3T	77401	1292.10
FG7TA100CV35CP	21	28	34.5	100K	5T	77346	1150.27

AC Pro N-Series 95% Two Stage Non-Variable

Furnace Model	W	D	H	BTUs	Size	Part #	Cost
FG7TC060DV24BP	17.5	28	34.5	60K	2-3T	77396	1498.10
FG7TC080DV35CP	21	28	34.5	80K	3T	77397	1676.85
FG7TC100DV35CP	21	28	34.5	100K	5T	77398	1786.87



Warranty:
10 Year Parts

1 Year
Dependability
Lifetime Heat
Exchanger
(KG7 model)

AC Pro N-Series 80% Single Stage Non-Variable Downflow

Furnace Model	W	D	H	BTUs	Size	Part #	Cost
KG7SK054CT23A2	14.5	28	34.5	54K	2-3T	85383	921.78
KG7SK072CT24B2	17.5	28	34.5	2K	3-4T	85384	1033.67
KG7SK108CT35C2	21	28	34.5	108K	5T	85386	1145.60

X-Series Condenser Air Conditioning 16 SEER2 R32

2 Ton

SPAC-X-I036BC



3 Ton

SPAC-X-I036BC



4 Ton

SPAC-X-I060BC



5 Ton

SPAC-X-I060BC



Specs

Width	36.25
Depth	14.57
Height	29.38
Suction	3/4
Liquid	3/8
Stages	1
Amps - Min/Max	21.6-25
dB Rating	56

Warranty

10 Year Parts
10 Year Compressor

Product Information

AC Pro Part #	84597
Condenser Cost	\$1,185.00

↓ Furnace ↓

80% 1-Stage Variable

FURN-M-L1A60V12A



Warranty:
10 Year Parts
1 Year Heat Exchanger

BTUs 60k

Width 14.5

Depth 28.5

Height 33.75

AC Pro Part # 85054

Furnace Cost \$816.42

Multi-Position

COIL-X-24CMEC



W 17.50

D 21.25

H 23.00

AC Pro Part # 85986

AHRI # 217605548*

SEER2/EER2 16/12

Coil Cost \$953.04

Complete System \$2,954.46

Multi-Position

COIL-X-36CMEC

AC Pro Part # 85060

AHRI # 217605545*

SEER2/EER2 16/11

Coil Cost \$953.04

Complete System \$2,954.46

Multi-Position

COIL-X-48DMEC

AC Pro Part # 85987

AHRI # 217605546*

SEER2/EER2 16/10

Coil Cost \$1,278.26

Complete System \$4,323.11

Multi-Position

COIL-X-60DMEC

AC Pro Part # 85061

AHRI # 217605547*

SEER2/EER2 16/10

Coil Cost \$1,278.26

Complete System \$4,461.91

*Ratings shown are for Condenser & Coil only

2025 25C Tax Credit criteria for AC Split systems is 17/12 SEER2/EER2.

Energy Star Certification criteria for AC Split systems is 15.2/12 SEER2/EER2

AC Pro X-Series with CoreFAU R32

2.0 Ton SPHP-X-I036B		3.0 Ton SPHP-X-I036B		4.0 Ton SPHP-X-I060B		5.0 Ton SPHP-X-I060B	
Warranty 10 Year Parts 10 Year Compressor							
Width	39.00	Width	39.00	Width	35.43	Width	35.43
Depth	14.80	Depth	14.80	Depth	13.9	Depth	13.9
Height	37.8	Height	37.8	Height	49.61	Height	49.61
Suction	3/4	Suction	3/4	Suction	3/4	Suction	3/4
Liquid	3/8	Liquid	3/8	Liquid	3/8	Liquid	3/8
Amp	27.7/30	Amp	27.7/30	Amp	39.9/45	Amp	39.9/45
dB Rating	61	dB Rating	61	dB Rating	63	dB Rating	63
AC Pro Part #	83985	AC Pro Part #	83985	AC Pro Part #	83986	AC Pro Part #	83986
HP Cost	\$1,930.91	HP Cost	\$1,930.91	HP Cost	\$2,845.72	HP Cost	\$2,845.72

Air Handler AEFE3A00S1HA1		Air Handler AEFE3A00S1HA1		Air Handler AEFE4B00S1HA1		Air Handler AEFE5C00S1HA1	
W 14.5	D 28	W 14.5	D 28	W 17.5	D 28	W 21.0	D 28
H 30		H 30		H 30		H 30	
AC Pro Part #	81528	AC Pro Part #	81528	AC Pro Part #	81529	AC Pro Part #	81530
Air Handler Cost	\$687.50	Air Handler Cost	\$687.50	Air Handler Cost	\$794.44	Air Handler Cost	\$854.17

Multi-Position COIL-X-24CMEC		Multi-Position COIL-X-36CMEC		Multi-Position COIL-X-48DMEC		Multi-Position COIL-X-60DMEC	
W 17.50	D 21.25	W 17.50	D 21.25	W 24.50	D 21.25	W 24.50	D 21.25
H 23.00		H 23.00		H 28.50		H 28.50	
AC Pro Part #	85986	AC Pro Part #	85060	AC Pro Part #	85987	AC Pro Part #	85061
AHRI #	217469243	AHRI #	217469244	AHRI #	217605549	AHRI #	217469242
SEER2/EER2	16/11/8.5	SEER2/EER2	16/11/8.5	SEER2/EER2	15.2/10/8.5	SEER2/EER2	15.2/9.5/8.5
Coil Cost	\$953.04	Coil Cost	\$953.04	Coil Cost	\$1,278.26	Coil Cost	\$1,278.26
Complete System	\$3,571.45	Complete System	\$3,571.45	Complete System	\$4,918.42	Complete System	\$4,978.15

2025 25C Tax Credit criteria for HP Cold Climate Systems is 16/11/8.5/2.1-2.4* SEER2/EER2/HSPF2/COP

Energy Star Certification criteria for HP Cold Climate Systems is 15.2/8.1 SEER2/HSPF2

AC Pro X-Series 18-19 SEER2 Heat Pump R32

2.0 Ton SPHP-X-I036B	3.0 Ton SPHP-X-I036B	4.0 Ton SPHP-X-I060B	5.0 Ton SPHP-X-I060B
Warranty 10 Year Parts 10 Year Compressor 	Warranty 10 Year Parts 10 Year Compressor 	Warranty 10 Year Parts 10 Year Compressor 	Warranty 10 Year Parts 10 Year Compressor 
Width 39.00	Width 39.00	Width 35.43	Width 35.43
Depth 14.80	Depth 14.80	Depth 13.9	Depth 13.9
Height 37.8	Height 37.8	Height 49.61	Height 49.61
Suction 3/4	Suction 3/4	Suction 3/4	Suction 3/4
Liquid 3/8	Liquid 3/8	Liquid 3/8	Liquid 3/8
Amp 27.7/30	Amp 27.7/30	Amp 39.9/45	Amp 39.9/45
dB Rating 61	dB Rating 61	dB Rating 63	dB Rating 63
AC Pro Part # 83985	AC Pro Part # 83985	AC Pro Part # 83986	AC Pro Part # 83986
HP Cost \$1,930.91	HP Cost \$1,930.91	HP Cost \$2,845.72	HP Cost \$2,845.72

X-Series Air Handler AIRH-X-176B	X-Series Air Handler AIRH-X-1100B	X-Series Air Handler AIRH-X-1120B	X-Series Air Handler AIRH-X-1150B
 W 21.26	 W 21.26	 W 21.26	 W 21.26
D 18.11	D 18.11	D 24.8	D 24.8
H 43.5	H 43.5	H 51.97	H 51.97
AC Pro Part # 83987	AC Pro Part # 83988	AC Pro Part # 83989	AC Pro Part # 83990
AHRI # 216623548	AHRI # 216623546	AHRI # 216623549	AHRI # 216623547
SEER2/EER2/HSPF2 18/12.5/10.0	SEER2/EER2/HSPF2 18/12/10.0	SEER2/EER2/HSPF2 19/12/10.0	SEER2/EER2/HSPF2 18.5/11.7/10.5
Air Handler Cost \$1,481.66	Air Handler Cost \$1,496.66	Air Handler Cost \$1,780.00	Air Handler Cost \$1,780.00
Complete System \$3,412.57	Complete System \$3,427.57	Complete System \$4,625.72	Complete System \$4,625.72

2025 25C Tax Credit criteria for HP Cold Climate Systems is 16/11/8.5/2.1-2.4* SEER2/EER2/HSPF2/COP

Energy Star Certification criteria for HP Cold Climate Systems is 15.2/8.1 SEER2/HSPF2

AC Pro Heat Pump Package Units



10 Year Parts Warranty
10 Year Compressor

AC Pro X-Series Inverter 17-17.8 SEER2 HP R32												
Model	Size	Cooling BTUs	Heating BTUs	AMP	SEER2	EER2	HSPF	AHRI	W	L	H	Cost
PKHP-X-024VBC	2.0 Ton	24K	24K	35/40	18	11.7	8.8	217469239	44	35.44	49.25	\$5,030.26
PKHP-X-036VBC	3.0 Ton	36K	36K	35/40	18	11.2	8.5	217469237	44	35.44	49.25	\$5,030.26
PKHP-X-048VBC	4.0 Ton	47K	47K	39/45	18	11.2	8.5	217469240	44	44	49.25	\$5,644.73
PKHP-X-060VBC	5.0 Ton	56K	56K	39/45	18	11.2	8.3	217469238	44	44	49.25	\$5,644.73

2025 25C Tax Credit criteria for HP Package Units is 15.2/10/7.2/1.75 SEER2/EER2/HSPF2/COP

Energy Star Certification criteria for HP Package Units is 15.2/10/7.2 SEER2/EER2/HSPF2

AC Pro Y-Series Heat Pump R454B

1.5 Ton 19 SEER SPHP-Y-V018BB	2.0 Ton 19.4 SEER SPHP-Y-V024BB	3.0 Ton 18 SEER SPHP-Y-V036BB	4.0 Ton 17.3 SEER SPHP-Y-V048BB
Warranty 10 Year Parts 10 Year Compressor 	Warranty 10 Year Parts 10 Year Compressor 	Warranty 10 Year Parts 10 Year Compressor 	Warranty 10 Year Parts 10 Year Compressor 
Width 31.69	Width 35.04	Width 37.24	Width 38.58
Depth 13.00	Depth 13.46	Depth 16.14	Depth 16.34
Height 21.81	Height 26.5	Height 31.89	Height 38.39
Suction 3/4	Suction 3/4	Suction 3/4	Suction 3/4
Liquid 3/8	Liquid 3/8	Liquid 3/8	Liquid 3/8
Max Breaker 16/20	Max Breaker 19/20	Max Breaker 24/30	Max Breaker 36/40
dB Rating 55	dB Rating 60	dB Rating 63	dB Rating 65
AC Pro Part # 84086	AC Pro Part # 84087	AC Pro Part # 84089	AC Pro Part # 84090
HP Cost \$781.08	HP Cost \$1,014.86	HP Cost \$1,412.16	HP Cost \$2,081.08
<hr/>			
Air Handler AIRH-Y-V01808CB  W 17.52 D 21.02 H 45	Air Handler AIRH-Y-V02408CB  W 17.52 D 21.02 H 45	Air Handler AIRH-Y-V03612CB  W 21.02 D 21.02 H 49.02	Air Handler AIRH-Y-V04816CB  W 24.49 D 21.02 H 52.99
AC Pro Part # 84080	AC Pro Part # 84081	AC Pro Part # 84083	AC Pro Part # 84084
AHRI # 216497956	AHRI # 216497957	AHRI # 216497959	AHRI # 216497960
SEER2/EER2/HSPF2 18.8/11/9.1	SEER2/EER2/HSPF2 18.1/11/9.7	SEER2/EER2/HSPF2 16.1/10/8.7	SEER2/EER2/HSPF2 16/10/8.5
Air Handler Cost \$990.54	Air Handler Cost \$1,016.21	Air Handler Cost \$1,181.08	Air Handler Cost \$1,254.05
Complete System \$1,771.62	Complete System \$2,031.07	Complete System \$2,593.24	Complete System \$3,335.13
<hr/>			
5.0 Ton 18 SEER SPHP-Y-V060BB Warranty 10 Year Parts 10 Year Compressor 			
Width 38.58			
Depth 16.34			
Height 38.39			
Suction 3/4			
Liquid 3/8			
Max Breaker 39/40			
dB Rating 65			
AC Pro Part # 84091			
HP Cost \$2,171.62			
<hr/>			
Air Handler AIRH-Y-V06020CB  W 24.49 D 21.02 H 52.99			
AC Pro Part # 84085			
AHRI # 216497961			
SEER2/EER2/HSPF2 15.2/8.6/8.4			
Air Handler Cost \$1,348.65			
Complete System \$3,520.27			

2025 25C Tax Credit criteria for HP Cold Climate Systems is 16/11/8.5/2.1-2.4* SEER2/EER2/HSPF2/COP

Energy Star Certification criteria for HP Cold Climate Systems is 15.2/8.1 SEER2/HSPF2

AC Pro Z-Series 17.5-19 SEER2 Inverter R454B

SPHP-Z-V018BB	SPHP-Z-V024BB	SPHP-Z-V036BB
1.5 Ton 19 SEER2	2 Ton 18.6 SEER2	3 Ton 17.7 SEER2
Warranty	Warranty	Warranty
10 Year Parts	10 Year Parts	10 Year Parts
10 Year Compressor	10 Year Compressor	10 Year Compressor
		
Width 35.04	Width 35.04	Width 37.25
Depth 13.46	Depth 13.46	Depth 16.13
Height 26.50	Height 26.50	Height 31.8
Suction 3/4	Suction 3/4	Suction 3/4
Liquid 3/8	Liquid 3/8	Liquid 3/8
Amp 16/20	Amp 19/20	Amp 26/30
dB Rating 57	dB Rating 59	dB Rating 63
AC Pro Part # 84231	AC Pro Part # 84232	AC Pro Part # 84233
HP Cost \$889.19	HP Cost \$1,213.51	HP Cost \$1,864.87

Air Handler	Air Handler	Air Handler
AIRH-Z-V018V06C	AIRH-Z-V024V08C	AIRH-Z-V036V12C
		
W 14.49	W 14.49	W 17.52
D 21.50	D 21.50	D 21.50
H 49.72	H 49.72	H 53.98
AC Pro Part # 84226	AC Pro Part # 84227	AC Pro Part # 84228
AHRI # 216497962	AHRI # 216497963	AHRI # 216497965
SEER2/EER2/HSPF2 19/12.5/10.1	SEER2/EER2/HSPF2 18.6/12/10	SEER2/EER2/HSPF2 17.7/12/10
Air Handler Cost \$1,059.46	Air Handler Cost \$1,221.62	Air Handler Cost \$1,456.76
Complete System \$1,948.65	Complete System \$2,435.13	Complete System \$3,321.63

SPHP-Z-V048BB	SPHP-Z-V060BB
4 Ton 17.5 SEER2	5 Ton 17.5 SEER2
Warranty	Warranty
10 Year Parts	10 Year Parts
10 Year Compressor	10 Year Compressor
	
Width 38.58	Width 37.5
Depth 16.34	Depth 16.34
Height 38.39	Height 52.25
Suction 3/4	Suction 3/4
Liquid 3/8	Liquid 3/8
Amp 38/40	Amp 40/40
dB Rating 65	dB Rating 65
AC Pro Part # 84234	AC Pro Part # 84235
HP Cost \$2,410.81	HP Cost \$2,554.06


Air Handler	Air Handler
AIRH-Z-V048V16C	AIRH-Z-V060V18C
	
W 21.50	W 21.50
D 21.50	D 21.50
H 55.94	H 55.94
AC Pro Part # 84229	AC Pro Part # 84230
AHRI # 216497966	AHRI # 216497967
SEER2/EER2/HSPF2 17.5/12/9.5	SEER2/EER2/HSPF2 17.5/12/9.5
Air Handler Cost \$1,744.60	Air Handler Cost \$1,766.21
Complete System \$4,155.41	Complete System \$4,320.27

2025 25C Tax Credit criteria for HP Split systems is 16/11/8/1.75 SEER2/EER2/HSPF2/COP
 Energy Star Certification criteria for HP Split systems is 15.2/11/7.8 SEER2/EER2/HSPF2

Visit ACPro.com for Product Pricing, Matchups, Install related items and much more

1 Pricing

See your special product pricing 24/7 on a phone, tablet, or desktop computer. Add product to cart by clicking on the "+" symbol.



Top of Page

Condenser Air Conditioning 1.5 Ton 14.5 SEER 12.2 EER 208/230V Single Phase Single Stage
AC Pro | AC Pro: 52786 MFG: AAC1HL10P
Not Available in NV
• Layered panel provides extra coil protection:
- High quality condenser coil provides maximum heat transfer:
- 10 year compressor and gears warranty:
- 50 year compressor and gears warranty:
- Bi-directional liquid filter over factory installed

1 **WARNING!** Cancer and Reproductive Harm. [View Details](#)


2 Order in the next 2 hrs 36 mins, receive it as soon as tomorrow
60-day returns with no restocking fee

3 **Related Products**

Condenser Pad Black 24" x 24" x 3"	Iso-Cube Rubber Anti-Vibration Pad 2" x 2" 180lb Max	Condenser Hold Down Bracket	Fusible Disconnect Switch 30 Amps Single Phase 230V	Dual Element Time Delay Fuse 20 Amps 250V
AC Pro	Universal	Universal	Diversitech	Universal
AC PRO P-42-NR MFG: K-UNIVERSAL	AC PRO R-3000 MFG: K-UNIVERSAL	AC PRO R-2024 MFG: K-UNIVERSAL	AC PRO R-251 MFG: K-3005-30	AC PRO K-1114 MFG: K-UNIVERSAL
Quantity in cart <input type="button" value="-"/> <input type="button" value="0"/> <input type="button" value="+"/>	Quantity in cart <input type="button" value="-"/> <input type="button" value="0"/> <input type="button" value="+"/>	Quantity in cart <input type="button" value="-"/> <input type="button" value="0"/> <input type="button" value="+"/>	Quantity in cart <input type="button" value="-"/> <input type="button" value="0"/> <input type="button" value="+"/>	Quantity in cart <input type="button" value="-"/> <input type="button" value="0"/> <input type="button" value="+"/>
Anaheim (4) Nearby Branches (54) View All (127)	Anaheim (72) Nearby Branches (4847) View All (14460)	Anaheim (283) Nearby Branches (2684) View All (155667)	Anaheim (24) Nearby Branches (213) View All (1085)	Anaheim (42) Nearby Branches (446) View All (1342)

2 Inventory

View all inventory 24/7. Select your branch or any other location near your job site.



Page continues


3 Detailed Photos

Zoom view allows you to view close-up details, down to the inch. Plus, 360 view reveals the entire unit.



4 Related Items

Free checklist for technicians. Easily find all the required items to install the product. Plus, your purchasing staff can minimize mistakes by ordering correct product the first time.



Prices subject to change without notice. We reserve the right to correct any clerical errors.

Bottom of Page

The screenshot shows a list of complete HVAC systems. At the top, there are three radio button options: Horizontal Coil Match (selected), Vertical Coil Match, and Plenum Coil Match. Below this, two furnace models are listed:

- Gas Furnace 95% Single Stage 45,000 BTU Non-Variable (Upflow/Horizontal 17.5" wide)**
AF PRE-11200
MFG: 05020000001212
- Gas Furnace 80% Single Stage 45,000 BTU Non-Variable (Upflow/Horizontal 14.5" wide)**
AF PRE-11200
MFG: 05020000001212

For each model, there are two coil options:

- Evaporator Coil Horizontal 3 Ton 21" x 26.5" x 13.5"**
AC PRE-01170
MFG: VSP01000000001212
- Evaporator Coil Horizontal 3 Ton 21" x 26.5" x 14.5"**
AC PRE-01170
MFG: VSP01000000001212

Below the coils, there are AHRI certificates for both models.

Product Questions
No questions have been asked.

ASK A QUESTION

5 Equipment Matchups


Take the guess work out, our matchups provide the correct components for a complete system with one click. Plus, the online store has more matchups than the printed Equipment Guide. Also, download and view AHRI certificates.



6 Product Questions

6 Product Questions

Ask a tech question and get an answer next day or see other questions that have been answered.



7 Product Specifications

Instantly view tech specs, installation guides, submittals, warranty, consumer brochures, and MSDS sheets(for chemical items).



HOURS:		
MON – FRI 6 AM – 5 PM		
SAT 7 AM – 11AM		
Complimentary after-hours service 888.674.4822		
Anaheim	3000 La Palma Ave.	714.933.1777
Baldwin Park	13409 Garvey Ave #4	626.507.1430
Bellflower	9214 Artesia Blvd.	562.257.1440
Bloomington	10380 Alder Ave.	951.968.2115
Chatsworth	9216 Eton Ave.	818.884.1100
Chino	12365 Central Ave.	909.267.1122
Chula Vista	595 C St.	619.812.3670
El Cajon	1402 N Magnolia Ave.	619.566.8130
Escondido	2181 Meyers Ave., Ste B	760.233.2545
Kearny Mesa	7832 Armour St.	858.379.6455
Laguna Hills	23456 S Pointe Dr., Ste B	949.598.8333
La Habra	591 S. Walnut St.	562.257.1133
Mission Viejo	23831 Vía Fabricante #301	949.680.1770
Lemon Grove	3475 Lemon Grove Ave.	619.859.4785
Los Angeles	1369 West Washington Blvd.	213.712.5880
Lawndale	15438 Hawthorne Blvd.	562.549.2130
Oceanside	2040 Oceanside Blvd.	760.797.6234
Palm Desert	73760 Spyder Cir	760.341.7007
Pasadena	170 N. Daisy Ave.	626.507.1440
Perris	1622 Illinois Ave., Unit 18-19	951.368.1405
Rancho Cucamonga	9409 Charles Smith Ave.	951.360.7849
Riverside	1751 Marlborough Ave.	951.361.6161
San Diego	13230 Evening Creek Dr. South, Ste. 202	858.386.5005
San Dimas	149 Village Court	909.835.1155
Santa Ana	1442 Ritchey St.	949.680.1975
Signal Hill	2875 Cherry Ave.	562.595.5050
South Gate	4951 Mason St.,	323.510.1985
Temecula	27230 Madison Ave., Ste. C1	951.368.1978
Van Nuys	16116 Valerio St.	818.949.3095
Westminster	7606 Garden Grove Blvd.	714.464.1700
Henderson	7365 Commercial Way, Ste. 155	702.560.5670
Las Vegas - North	2910 S Highland Dr., Ste D	702.829.3010
Las Vegas - NW	2651 Crimson Canyon Dr. #120 & 140	725.333.6850
Las Vegas - South	4085 W Russell Rd.	702.795.4746
Goodyear	580 N Bullard Ave Suite 64-65	602.675.8470
Lake Havasu	1769 N McCulloch Blvd.	928.846.8707
Mesa	954 East Juanita Ave.	480.682.5405
Peoria	16681 N 84th Ave., #110	480.385.1380
Phoenix Central	11034 N. 23rd Dr., Ste. 105	602.648.9100
Phoenix DC Will Call	5502 W Maricopa St.	928.227.5810
Phoenix	3906 E. Broadway Rd., Ste 104	602.648.0320
Tucson East	8351 E Broadway Blvd.	520.652.3350
Tucson West	990 S Cherry Ave	520.306.2050
St. George	1357 S 320 E., Suite B	435.272.0580

California

Nevada

Arizona

Utah

MFG / Home office - 11700 Industry Ave, Fontana CA 92337
 All information in this manual is subject to change without notice.

© 2025 AC Pro

